

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
CAIRNS	55 Greenslopes St Cairns	10-11-15	Infill panel	Entrance to toilet area	Cement sheeting		ASB_033 55	Not Detected	Wall	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Main area South end	Adjacent to access door to patio	Cement sheeting		ASB_033 53	Not Detected	Wall	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Patio South end	North west corner wall	Cement sheeting		ASB_033 52	Not Detected	Wall	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Print room 1	Ceiling	Cement sheeting on raked ceilings		ASB_033 47	Not Detected	Ceiling	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Print room 1	Top wall section on East side	Cement sheeting above gyprock - same on west side. Sample taken as representative of walls above internal doorways in Staff Office, Print Room 2, wet area.		ASB_033 46	Not Detected	Wall	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Roof gable	External & internal cladding to Gables and gable soffits.	Representative sample taken North side internal cladding.		ASB_033 48	Not Detected	Gable cladding	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Wet area	Above window East side internal & external	Infill with cement sheeting - different construction method to other rooms		ASB_033 50	Not Detected	Wall	Fibre cement product	Property has been removed from JCU's portfolio
CAIRNS	55 Greenslopes St Cairns	10-11-15	Wet area (small) at Southern end	East wall above window - internal	Cement sheeting. Taken as representative of southern Patio, west wall and Main Area (door to southern Patio).		ASB_033 51	Not Detected	Wall	Fibre cement product	Property has been removed from JCU's portfolio
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 1	Rear yard	Eaves		ASB_015 12	Not Detected	Eaves	Fibre cement product	
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 1	Rear yard	Tiles at Entrance to rear door, same as kitchen floor tiles		ASB_015 13	Not Detected	Floor Covering		
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 1	Rear yard	Loose tiles on ground, same as lounge and bedroom tiles		ASB_015 14	Not Detected	Floor Covering		
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 1	Front Yard	Eaves		Same as ASB_015 12	Not Detected	Eaves	Fibre cement product	
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 1	Unit 4 Shed	At entrance to Unit 1 Eaves		ASB_015 16	Not Detected	Eaves	Fibre cement product	
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 1	Carport	Decorative fascia		ASB_015 17	Not Detected	Fascia	Fibre cement product	
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 2	Rear yard	Eaves		ASB_015 15	Not Detected	Eaves	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	10 Duchess Road, Mt Isa	20-07-15	Unit 2	Front Yard	Eaves		Same as ASB_01512	Not Detected	Eaves	Fibre cement product	
Remote	19 Samsa St, Mt Isa	20-07-15	Ensuite	Walls	Tiled and Fibre Cement Sheeting added in 2011	0138/13-ED04		Not Detected	Wall	Fibre cement product	
Remote	19 Samsa St, Mt Isa	20-07-15	Ensuite	Ceiling	Fibre Cement Sheet added 2011	See 0138/13-ED04		Not Detected	Ceiling	Fibre cement product	
Remote	19 Samsa St, Mt Isa	20-07-15	External	Eaves	New renovation, north east corner. Hardiflex installed in 2011	0138/13-ED06		Not Detected	Eaves	Fibre cement product	
Remote	19 Samsa St, Mt Isa	20-07-15	Rear Patio	Ceiling	Fibre Cement Sheeting added 2010		ASB_01520	Not Detected	Ceiling	Fibre cement product	
Remote	19 Samsa St, Mt Isa	20-07-15	Walk in Robe	Walls	Combination of Block on North, South, West and Fibre Cement Sheeting added in 2011 on East	See ASB_01520		Not Detected	Wall	Fibre cement product	
Remote	19 Samsa St, Mt Isa	20-07-15	Walk in Robe	Ceiling	Fibre Cement Sheet added 2011	See ASB_01520		Not Detected	Ceiling	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Bedroom 1	Wall - North Panel	Textured panel		ASB_01534	Not Detected	Wall	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)		ASB_01533	Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Bedroom 2	Wall - South Panel	Textured panel (ASB01534)			Not Detected	Wall	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Laundry	Sheeting on East Wall	Fibre Cement Sheet		ASB_01536	Not Detected	Wall	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Laundry	Tub	Precast Concrete - original		ASB_01537	Not Detected	Sink	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 1, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 2, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 2, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 2, Laundry	Tub	Precast Concrete - original (ASB 01537)			Not Detected	Basin	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 2, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 3, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 3, Bedroom 1	Wall - North Panel	Textured Panel		ASB_01542	Not Detected	Wall	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 3, Bedroom 2	Wall - South Panel	Textured Panel (ASB01542)			Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	35 East St, Mt Isa	21-07-15	Unit 3, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 3, Laundry	Tub	Precast Concrete - original (ASB 01537)			Not Detected	Basin	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 3, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 4, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 4, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
Remote	35 East St, Mt Isa	21-07-15	Unit 4, Laundry	Tub	Precast Concrete - original (ASB 01537)			Not Detected	Basin	Fibre cement product	
Remote	35 East St, Mt Isa	21-07-15	Unit 4, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet	
REMOTE	48 Jack Street Atherton	09-11-15	Access to seminar room	Ramp way ceiling	Cement sheeting - representative sample taken in store room		same as ASB_033 34	Not Detected	Ceiling	Fibre cement product	
REMOTE	48 Jack Street Atherton	09-11-15	Bed 1	Floor	Floral patterned vinyl type sheeting glued to Masonite type product. Carpet laid over.		ASB_033 42	Not Detected	Floor	Vinyl sheet	
REMOTE	48 Jack Street Atherton	09-11-15	Bed 1	Southern wall	Fibrous plaster		ASB_033 41	Not Detected	Wall		
REMOTE	48 Jack Street Atherton	09-11-15	Bed 2	Floor	Carpet on vinyl type sheeting on top of Masonite - pattern type vinyl thin layer glued to masonite type product - representative sample taken bed 1			Not Detected	Floor	Vinyl sheet	
REMOTE	48 Jack Street Atherton	09-11-15	External	Western wall	Cement sheeting with render over		ASB_033 45	Not Detected	Wall	Fibre cement product	
REMOTE	48 Jack Street Atherton	09-11-15	Man hole cover	Ceiling entrance	Cement sheeting		ASB_033 43	Not Detected	Ceiling	Fibre cement product	
REMOTE	48 Jack Street Atherton	09-11-15	Seminar room	Above Ceiling old soffit southern end	Cement sheeting		ASB_033 35	Not Detected	Eaves	Fibre cement product	
REMOTE	48 Jack Street Atherton	09-11-15	Seminar room	Above Ceiling old gable sheeting East end	Cement sheeting -debris in ceiling space from hole being smashed through gable end wall, debris sitting in ceiling over access way to seminar room		ASB_033 36	Not Detected	Debris	Fibre cement product	
REMOTE	48 Jack Street Atherton	09-11-15	Store room attached to seminar room	Ceiling	Cement sheeting		ASB_033 34	Not Detected	Ceiling	Fibre cement product	
REMOTE	48 Jack Street Atherton	09-11-15	Toilet laundry area - behind seminar room	Ceiling	Cement sheeting - representative sample taken in store room		same as ASB_033 34	Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
REMOTE	48 Jack Street Atherton	09-11-15	Toilet off hallway	Top section of Walls	Plaster		ASB_03338	Not Detected	Wall		
Remote	Duncragan House	14-07-15	Common kitchen	North wall, centre of to west wall	East side of wall is Masonite		ASB_00536	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Common kitchen	West wall, including diagonal to window			Same as ASB_00536	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Common kitchen	Bulk head ceiling panel	Rest of ceiling and bulkhead vertical infill panels are Masonite		Same as ASB_00536	Not Detected	Ceiling	Fibre cement product	
Remote	Duncragan House	14-07-15	Common kitchen	Northeast wall infill panel between cabinets (above and below)	fibre cement sheet 1m x 1m		Same as ASB_00536	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	East entrance foyer	Floor between rooms 5 and 6	Under green carpet		ASB_00525	Not Detected	Floor Covering	Fibre cement product	
Remote	Duncragan House	15-07-15	External house	External wall between bathhouse and room 19 (East-west)			ASB_00546	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	15-07-15	External house	Common kitchen - Infill panel around box air conditioner			ASB_00547	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	15-07-15	External house	Common kitchen - serving hatch	Hinged perforated panel, no longer used		ASB_00548	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	15-07-15	External house	Infill panel on PVC pipe at ground level - South side of southwest bath house			ASB_00549	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Hallway external to room 4	East wall panel around entrance door (North section only)	1 sheet only		Same as ASB_00522	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Hallway to common kitchen, South end	Cupboard internal walls (x3)	Assumed all 3 walls the same. Adjacent room 11 outside of common kitchen door		ASB_00533	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Hallway to common kitchen, South end	Adjacent to room 20 door	2 sheets above and South side of door. Assume same material as other side of the wall, sampled		Same as ASB_00533	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Hallway to common kitchen, South end	Inside hallway at South courtyard door	Brown vinyl sheet. Masonite underlay. No glue.		ASB_00535	Not Detected	Floor Covering	Vinyl sheet	
Remote	Duncragan House	14-07-15	Main hallway Nth end	Wall sheeting around door to West entry foyer (opposite West courtyard entrance)	Around door with security screen, 850mm door		ASB_00526	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	North entry foyer	East wall	Same material as hallway on the other side, refer to sample 00526		Same as ASB_00526	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	NW bathroom	Toilet and bathroom hallway	Black and white chequered tiles, matching. Sampled black tile		ASB_00539	Not Detected	Floor Covering	Vinyl tile	
Remote	Duncragan House	14-07-15	NW bathroom	Shower room	Raised ceramic tile floor, fibre cement 16mm sheet underneath		ASB_00550	Not Detected	Floor Covering	Fibre cement product	
Remote	Duncragan House	14-07-15	NW kitchen	Partition walls	Behind fridge, both sides of wall		ASB_00537	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	NW kitchen	Pantry backing, east side	Both sides, reverse captured in living room		Same as ASB_00537	Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	Duncragan House	14-07-15	NW living room	Pantry rear wall / hallway to dining	Both sides, reverse captured in pantry for kitchen		Same as ASB_005 37	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 11	Serving hatch infill panel, west internal wall	Vertical sheet between 11 and the common kitchen		ASB_005 23	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 13	West wall infill panel of removed door, South side of window	1 sheet		ASB_005 24	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 18	South wall	Entire wall		ASB_005 27	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 20	East wall	Cement sheeting only, excluding tongue and groove		ASB_005 31	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 20	South door infill panel	Door removed		ASB_005 32	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 3	North wall, air conditioning infill panel	Not painted		ASB_005 21	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	Room 4	West wall panel around entrance door (North section only)	1 sheet only		ASB_005 22	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	Shower base floor panel- East shower adjacent hallway	16mm sheeting. Now cleaners store		ASB_005 28	Not Detected	Floor Covering	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	East shower (cleaner's store)			Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	West shower			Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	Bathroom internal partition	Sample taken next to sinks, behind paper towel holder.		ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	Laundry	First room to the left		Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	Store room, opposite toilets	Second room to the left; Shelves in room		Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	South toilet			Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	Centre toilet			Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	North toilet			Same as ASB_005 29	Not Detected	Wall	Fibre cement product	
Remote	Duncragan House	14-07-15	South west bath house	Floor, all areas except store room	Sheet vinyl, marble colour. Sample taken in north toilet		ASB_005 30	Not Detected	Floor Covering	Vinyl sheet	
Remote	Fletcherview Station	16-07-15	Main residence- internal	Hallway cupboard	mounted wall panel underneath lowest shelf, E side		ASB_005 63	Not Detected	Wall	Fibre cement product	
Remote	Fletcherview Station	16-07-15	Storage yard, external to sheds	30m SE of dongas laying against JCU fire truck	2x partial sheets plus debris on the ground (local)		ASB_005 59	Not Detected	Debris	Fibre cement product	
Remote	Fletcherview Station	16-07-15	Student accommodation- ATCO dongas	Room 8, cupboard	Different colour sheet vinyl to rest of building		ASB_005 56	Not Detected	Floor Covering	Vinyl sheet	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	Fletcherview Station	16-07-15	Student accommodation- ATCO dongas	All rooms and hallway	Light pink vinyl sheeting		ASB_00558	Not Detected	Floor Covering	Vinyl sheet	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Lab walls - all	Sample taken behind fume cupboard		ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Instrument room	Room northeast of lab		Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Store room	2nd room northeast of lab		Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Office A	3rd room northeast of lab		Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Office B	4th room northeast of lab		Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Hallway			Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Tea room			Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Toilet - East			Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Toilet - West			Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	General office / foyer			Same as ASB_02251	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	Vinyl tiles- all rooms	Light green colour, damage near door		ASB_02252	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	External siding	Unpainted walls and eaves same material		ASB_02253	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building A - Lab / Admin	External eaves	Unpainted walls and eaves same material		Same as ASB_02253	Not Detected	Eaves	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Kitchen - all walls	Sample taken on west wall		ASB_02254	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Laundry - all walls			Same as ASB_02254	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Dining / recreation			Same as ASB_02254	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Dining / recreation, partition wall	Painted blue, centre of room. Both sides of wall		Same as ASB_02254	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Hallway for bedrooms			Same as ASB_02254	Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	Horn Island	29-07-15	Building B - accommodation	Bunk room - West side, north end			Same as ASB_022 54	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Bunk room - West, centre			Same as ASB_022 54	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Bunk room - West side, south end			Same as ASB_022 54	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Bunk room - East side, North end			Same as ASB_022 54	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Male bathroom			Same as ASB_022 54	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Male bathroom - partition walls	Toilets and shower cubicles		ASB_022 55	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Female bathroom			Same as ASB_022 54	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Female bathroom - partition walls	Toilets and shower cubicles		Same as ASB_022 55	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Vinyl tiles - hallway centre only	Grey colour		ASB_022 56	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	29-07-15	Building B - accommodation	Vinyl tiles - all building	Cream colour. Except for 3 of the dorms		ASB_022 57	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	29-07-15	Building B - accommodation	Shower base - male shower	Sample of damaged section, broken through to bathroom ceramic tiles		ASB_022 58	Not Detected	Flooring Underlay	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Shower base - female shower			Same as ASB_022 58	Not Detected	Flooring Underlay	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	External siding	Unpainted walls and eaves same material. Some damage.		ASB_022 59	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	External eaves	Unpainted walls and eaves same material		Same as ASB_022 59	Not Detected	Eaves	Fibre cement product	
Remote	Horn Island	29-07-15	Building B - accommodation	Underneath floor, debris	Various pieces. Found large piece in SE corner under female bathroom. Assume same material as walls by texture		Same as ASB_022 59	Not Detected	Debris	Fibre cement product	
Remote	Horn Island	29-07-15	Building B1 - single accomm	External siding	Unpainted walls and eaves same material. Some damage.		Same as ASB_022 59	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B1 - single accomm	External eaves	Unpainted walls and eaves same material		Same as ASB_022 59	Not Detected	Eaves	Fibre cement product	
Remote	Horn Island	29-07-15	Building B1 - single accomm	Internal walls	Unpainted, same as external siding		Same as ASB_022 59	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building B1 - single accomm	Ceiling	Unpainted, same as external siding		Same as ASB_022 59	Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	Horn Island	30-07-15	Building C - house	Vinyl tiles - all building	Cream colour. Except for 3 of the dorms		ASB_022 62	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	30-07-15	Building C - house	Bathroom floor	Sample from pipe hole; can see underside of shower base, fibreglass		ASB_022 63	Not Detected	Floor Covering	Fibre cement product	
Remote	Horn Island	30-07-15	Building C - house	External siding	Sample northwest corner in damaged area; Unpainted walls and eaves same material. Some damage.		ASB_022 64	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	30-07-15	Building C - house	External eaves	Unpainted walls and eaves same material. Some damage.		Same as ASB_022 64	Not Detected	Eaves	Fibre cement product	
Remote	Horn Island	30-07-15	Building C - house	Underneath floor, debris	Various pieces. Found piece East side under bathroom + sheets in northwest corner. Assume same material as walls by texture		Same as ASB_022 64	Not Detected	Debris	Fibre cement product	
Remote	Horn Island	30-07-15	Building C - house	Yard, debris	2 pieces East side under roof sheeting. Assume same material a under bathroom		Same as ASB_022 63	Not Detected	Debris	Fibre cement product	
Remote	Horn Island	30-07-15	Building D - units	South unit - shower floor	Same as C block bathroom		Same as ASB_022 64	Not Detected	Floor Covering	Fibre cement product	
Remote	Horn Island	30-07-15	Building D - units	South unit - vinyl tile floor	Same as C block		Same as ASB_022 63	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	30-07-15	Building D - units	North unit - shower floor	Same as C block bathroom		Same as ASB_022 64	Not Detected	Floor Covering	Fibre cement product	
Remote	Horn Island	30-07-15	Building D - units	North unit - vinyl tile floor	Same as C block		Same as ASB_022 63	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	30-07-15	Building D - units	Laundry floor	Same as C block		Same as ASB_022 63	Not Detected	Floor Covering	Vinyl tile	
Remote	Horn Island	30-07-15	Building D - units	External siding	Same as C block		Same as ASB_022 64	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	30-07-15	Building D - units	External eaves	Same as C block		Same as ASB_022 64	Not Detected	Eaves	Fibre cement product	
Remote	Horn Island	30-07-15	Building E - garage	Store A & B - fascia	Brown paint		ASB_022 65	Not Detected	Fascia	Fibre cement product	
Remote	Horn Island	29-07-15	Building F - flammable store	Internal walls	Unpainted, same as external		Same as ASB_022 60	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building F - flammable store	Ceiling	Unpainted, same as external		Same as ASB_022 60	Not Detected	Ceiling	Fibre cement product	
Remote	Horn Island	29-07-15	Building F - flammable store	External walls	Sample next to door		ASB_022 60	Not Detected	Wall	Fibre cement product	
Remote	Horn Island	29-07-15	Building F - flammable store	Fascia	Unpainted, same as external		Same as ASB_022 60	Not Detected	Fascia	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	Kirrama Research Hut	23-07-15	External	Window Putty	Putty visually consistent on all windows. No other suspected items of ACM found. Structure is timber, no signs of previous use of ACM or debris. Presence of ACM considered highly unlikely.		ASB_001 95	Not Detected	Window putty	Mastic	
Remote	Orpheus Island, Communal Building	22-07-15	External	Northern Veranda Floor	Thick compressed fibre cement sheet. Confirmed by Abscan 2010.	1466/09-16		Not Detected	Floor	Fibre cement product	
Remote	Orpheus Island, Communal Building	22-07-15	Food Storage	Floor panels at south side	Visible from underneath immediately west of walkway to toilets/showers		ASB_001 78	Not Detected	Floor	Fibre cement product	
Remote	Orpheus Island, Communal Building	22-07-15	South East Corner Kitchen	Floor panels at SE corner	Thick compressed fibre cement sheet		ASB_001 77	Not Detected	Floor	Fibre cement product	
Remote	Orpheus Island, Communal Building	22-07-15	Subfloor	Packers to timber floor joists and debris on ground. Vinyl tile material.	Sampled from under southern food storage area.		ASB_001 79	Not Detected	Packers and Debris	Vinyl tile	
Remote	Orpheus Island, Dry Lab	22-07-15	External	Walls	All external walls clad with wood grain patterned fibre cement weather boards. Confirmed by Abscan 2010.	1466/09-12		Not Detected	Wall	Fibre cement product	
Remote	Orpheus Island, Dry Lab	22-07-15	External	Eave Soffits to South, East and West sides.	Re-sampled to confirm.	1466/09-19	ASB_001 84	Not Detected	Eaves	Fibre cement product	
Remote	Orpheus Island, Dry Lab	22-07-15	Floor	Fibre cement structural floor panels	Floor panels visually consistent throughout. Re-sampled to confirm.	1466/09-13	ASB_001 83	Not Detected	Floor	Fibre cement product	
Remote	Orpheus Island, Dry Lab	22-07-15	Internal Ceilings	All Rooms	All internal ceilings visually consistent. Confirmed by Abscan 2010.	1466/09-11		Not Detected	Ceiling	Fibre cement product	
Remote	Orpheus Island, Dry Lab	22-07-15	Internal Walls	All Rooms	All internal walls visually consistent. Confirmed by Abscan 2010.	1466/09-10		Not Detected	Wall	Fibre cement product	
Remote	Orpheus Island, Dry Lab	22-07-15	Sub Floor	Packers to timber Joists	Sampled at Southern side.		ASB_001 82	Not Detected	Packer	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	Bathroom	NE wall, next to shower	Location of water damage, exposed joint. Cement sheet visually consistent with other internal wall sheeting.		ASB_001 93	Not Detected	Wall	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	External, Eastern corner of Bathroom	External Wall Cladding	Wood grain patterned fibre cement vertical boards. Sampled by Abscan 2010, no asbestos detected. Re-sampled to confirm.	1466/09-07	ASB_001 85	Not Detected	Wall	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	External, Front Veranda	Floor Panels	Thick fibre cement sheet floor panels	1466/09-06		Not Detected	Floor	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	Orpheus Island, Manager's Residence	22-07-15	External, landing to stairs to Rear Office/First Aid.	Floor	Thick fibre cement sheet floor panel		ASB_00186	Not Detected	Floor	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	Front Office	Ceiling	Taken as representative of all ceilings and eave soffits. Double skinned, polystyrene sandwich panels.	1466/09-09	ASB_00187	Not Detected	Ceiling	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	Front Office	Floor Covering, Under Modern Sheet Vinyl. Patterned vinyl with fibrous backing layer			ASB_00188	Not Detected	Floor Covering	Vinyl sheet	
Remote	Orpheus Island, Manager's Residence	22-07-15	Front Office	South West Wall	Taken as representative of all walls in this room.		ASB_00189	Not Detected	Wall	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	Kitchen	Floor Covering, Under Modern Sheet Vinyl. Patterned vinyl with fibrous backing layer	Same material observed in other rooms.		ASB_00192	Not Detected	Floor Covering	Vinyl sheet	
Remote	Orpheus Island, Manager's Residence	22-07-15	Laundry	Ceiling	Taken as representative of all ceilings and eave soffits. Double skinned, polystyrene sandwich panels.	1466/09-09	ASB_00194	Not Detected	Ceiling	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	Living Room	North West wall	sampled in Northern Corner, taken as representative of all walls in this room.		ASB_00191	Not Detected	Wall	Fibre cement product	
Remote	Orpheus Island, Manager's Residence	22-07-15	Rear Office/First Aid Room & Store	Floor	Thick fibre cement sheet floor panel		ASB_00190	Not Detected	Floor	Fibre cement product	
Remote	Paluma, 34 Mt Spec Rd	24-07-15	House, Internal	Dining Room, wall cladding East and above French Doors to rear Deck.	Appears to be modern FC sheet		ASB_00197	Not Detected	Wall	Fibre cement product	
Remote	Paluma, 34 Mt Spec Rd	24-07-15	Lab/Station	Sub-Floor Area	Flat sheet debris		ASB_00199	Not Detected	Debris	Fibre cement product	
Remote	Roxmere Station	19-07-15	Class room	Floor	Vinyl		ASB_01510	Not Detected	Floor	Vinyl sheet	
Remote	Roxmere Station	19-07-15	Female Ablutions	Eastern toilet cubicle, eastern wall	Taken from Lino, same covering whole floor		ASB_01501	Not Detected	Floor Covering	Vinyl sheet	
Remote	Roxmere Station	19-07-15	Male Ablutions	Shower partition, south west	Beneath towel rail		ASB_01502	Not Detected	Wall	Fibre cement product	
Remote	Roxmere Station	19-07-15	Male Ablutions	Shower partition, north west	Beneath towel rail, west end		ASB_01503	Not Detected	Wall	Fibre cement product	
Remote	Roxmere Station	19-07-15	Male Ablutions	Shower partition, north east	Near floor west side		ASB_01504	Not Detected	Wall	Fibre cement product	
Remote	Roxmere Station	19-07-15	Ringer's house	West interior wall	Replaced with hardiflex in 1999		ASB_01509	Not Detected	Wall	Fibre cement product	
Remote	Roxmere Station	19-07-15	Ringer's house	West interior ceiling	Replaced with hardiflex in 1999			Not Detected	Ceiling	Fibre cement product	
Remote	Roxmere Station	19-07-15	Storerooms	Floor	Vinyl tile		ASB_01511	Not Detected	Floor Covering	Vinyl tile	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Remote	RV James Kirby	09-07-15	Crew berth	Floor	Glued to steel floor		ASB_00518	Not Detected	Floor Covering	Vinyl sheet	Vessel has been removed from JCU's ownership
Remote	RV James Kirby	09-07-15	Scientist berth	Floor	Covering below carpet. Floating wood panelling floor. Same material as crew bunks		Same as ASB_00518	Not Detected	Floor Covering	Vinyl sheet	Vessel has been removed from JCU's ownership
Remote	RV James Kirby	09-07-15	Store room	Floor	Covering below carpet. Floating wood panelling floor. Same material as crew bunks		Same as ASB_00518	Not Detected	Floor Covering	Vinyl sheet	Vessel has been removed from JCU's ownership
Remote	RV James Kirby	09-07-15	Store room	Spare parts dry store	1x partial roll of TBA oil jointing		ASB_00519	Not Detected	Gasket	Compressed Fibre Gasket	Vessel has been removed from JCU's ownership
Remote	RV James Kirby	09-07-15	Top wheelhouse deck	Exhaust riser on rear of wheelhouse	Captain believes it is original material. Uniform on both the primary and secondary exhaust pipes		ASB_00517	Not Detected	Insulation	Lagging (Friable)	Vessel has been removed from JCU's ownership
Townsville	DA001	15-01-15	000C	Wall	Infill adjacent to Rm 001	AT100712.05		Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	002	Walls		AT100712.02		Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	003	Air conditioning flange joint		AT100712.01		Not Detected	Gasket	Compressed Fibre Gasket	
Townsville	DA001	14-01-15	006	Ceiling			AG20150114/30	Not Detected	Ceiling	Textured Coating	
Townsville	DA001	14-01-15	012	Walls		AT100712.02		Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	012A	South wall			AG20150114/17	Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	013	Wall cladding			AG20150114/21	Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	013	Shelving	Fibre cement sheet cut into regular shape		AG20150114/22	Not Detected	Debris	Fibre cement product	
Townsville	DA001	14-01-15	014	Floor	Grey vinyl tile beneath carpet. Same as that observed in 015.			Not Detected	Floor Covering	Vinyl tile	
Townsville	DA001	14-01-15	015	Wall common with 016 and partitions			AG20150114/18	Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	015	Walls, ceiling and boxing in of air conditioning ductwork			AG20150114/19	Not Detected	Wall	Low Density Fibre Board	
Townsville	DA001	14-01-15	015	Floor	Grey vinyl tile beneath carpet. Result confirmed by XRD.		AG20150114/23	Not Detected	Floor Covering	Vinyl tile	
Townsville	DA001	14-01-15	016	Walls		AT100712.04		Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	018	Wall cladding			AG20150114/24	Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	018	Floor		AT100712.06		Not Detected	Floor Covering	Vinyl sheet	
Townsville	DA001	14-01-15	018A	Wall cladding	Same as AG20150114/24			Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	018B	Wall cladding	Same as AG20150114/24			Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	019	Penetration infill panel			AG20150114/28	Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA001	14-01-15	020	21/02/2015	Same as AG20150114/19			Not Detected	Wall	Low Density Fibre Board	
Townsville	DA001	14-01-15	021	Wall cladding	Same as AG20150114/19			Not Detected	Wall	Low Density Fibre Board	
Townsville	DA001	14-01-15	021	Wall cladding	West wall.		AG20140114/27	Not Detected	Wall	Low Density Fibre Board	
Townsville	DA001	14-01-15	022	Wall cladding	Same as AG20150114/19			Not Detected	Wall	Low Density Fibre Board	
Townsville	DA001	14-01-15	024	Shower recess		AT100712.07		Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	100C	Floor, outside 115	Red vinyl sheet with no backing		AG20150114/15	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DA001	13-01-15	101	Ceiling	Brown grey suspended ceiling tile		AG20150113/6	Not Detected	Ceiling	Fibre cement product	
Townsville	DA001	30-10-15	103	Floor	Green vinyl sheet (modern) approx. 1 square meter.		ASB_00569	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DA001	14-01-15	103A	Ceiling			AG20150114/12	Not Detected	Ceiling	Textured Coating	
Townsville	DA001	13-01-15	104	Floor	Green vinyl tile beneath carpet. Same as AG20150113/5.			Not Detected	Floor Covering	Vinyl tile	
Townsville	DA001	13-01-15	104A	Floor	Green vinyl beneath blue vinyl beneath carpet.		AG20150113/5	Not Detected	Floor Covering	Vinyl tile	
Townsville	DA001	13-01-15	106	Floor	Green vinyl tile beneath carpet. Same as AG20150113/5.			Not Detected	Floor Covering	Vinyl tile	
Townsville	DA001	13-01-15	118	Walls		AT100712.08		Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	119B	Ceiling			AG20150114/14	Not Detected	Ceiling	Textured Coating	
Townsville	DA001	14-01-15	120	Ceiling			AG20150114/16	Not Detected	Ceiling	Textured Coating	
Townsville	DA001	14-01-15	128B	Partition wall, left hand side of doorway			AG20150114/11	Not Detected	Wall	Fibre cement product	
Townsville	DA001	13-01-15	202A	Floor level	Fibrous insulation to penetrations and also as debris on the floor.		AG20150113/4	Not Detected	Insulation	Loose Fibre	
Townsville	DA001	13-01-15	320	Wall cladding	Sampled from roof space above.		AG20150113/9	Not Detected	Wall	Fibre cement product	
Townsville	DA001	14-01-15	Foyer, main entrance	Packing finish under cornice near entrance	Appears to be ceiling spray coat applied to the glass bricks		AG20150114/10	Not Detected	Ceiling	Textured Coating	
Townsville	DA001	13-01-15	Roof space	Underside of copper roofing and debris	Original roof sarking		AG20150113/8	Not Detected	Insulation	Loose Fibre	
Townsville	DA001	14-01-15	Stairwell adjacent to 011	Underside of stairs			AG20150114/31	Not Detected	Ceiling	Textured Coating	
Townsville	DA001	12-01-15	Stairwell adjacent to 217	Underside of stairs			AG20150112/3	Not Detected	Ceiling	Textured Coating	
Townsville	DA002	09-01-15	0 C001	Infill panels	Used on west wall		AG20150109/12	Not Detected	Wall	Fibre cement product	
Townsville	DA002	16-01-15	001	Ceiling			ASB_00256	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DA002	09-01-15	003	Floor	Cream vinyl sheet beneath blue vinyl sheet		AG20150109/5	Not Detected	Floor	Vinyl sheet	
Townsville	DA002	08-01-15	010	Ceiling			AG20150108/3	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DA002	16-01-15	1st floor C101	Suspended ceiling panels	White fibrous under layer of glass wool panels		AG20150116/8	Not Detected	Ceiling	Low Density Fibre Board	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA002	09-01-15	EXTERNAL	Ceiling, Level 1 entrances	Present to both north and south entrances	AT100712.15		Not Detected	Ceiling	Fibre cement product	
Townsville	DA003	05-02-15	001 Lecture Theatre	Floor Area in front of stage	Fibre cement sheeting		ASB_00282	Not Detected	Floor	Fibre cement product	
Townsville	DA003	09-02-15	001 Lecture Theatre	Front stage area floor under carpet	300mm x 300mm green vinyl square tiles laid on cream vinyl (unable to confirm if sheet or tile)		ASB_00284	Not Detected	Floor	Vinyl tile	
Townsville	DA003	09-02-15	001B Projector Room	Ceiling	Fibre cement sheeting indicates on old report that old sheeting had been replaced		ASB_00283	Not Detected	Ceiling	Fibre cement product	
Townsville	DA003	04-02-15	102	Wall sections on East and west wall	Fibre cement sheeting		ASB_00280	Not Detected	Wall	Fibre cement product	
Townsville	DA003	03-02-15	103	Small infill wall section between block work	Fibre cement sheeting		ASB_00274	Not Detected	Wall	Fibre cement product	
Townsville	DA003	04-02-15	104	Infill under window	Fibre cement sheeting representative sample taken room 105 [ASB_00278]			Not Detected	Wall	Fibre cement product	
Townsville	DA003	04-02-15	105	Ceiling	Textured finish representative sample taken in 206A [ASB_00314]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA003	04-02-15	105	Wall near entrance way	Fibre cement sheeting		ASB_00277	Not Detected	Wall	Fibre cement product	
Townsville	DA003	04-02-15	105	Infill under window (next to doorway)	Fibre cement sheeting (painted Blue)		ASB_00278	Not Detected	Wall	Fibre cement product	
Townsville	DA003	04-02-15	105	Infill under window	Fibre cement sheeting (painted white) sampled from behind black plastic skirting.		ASB_00279	Not Detected	Wall	Fibre cement product	
Townsville	DA003	03-02-15	109	Infill panel under beam	Fibre cement sheeting		ASB_00272	Not Detected	Wall	Fibre cement product	
Townsville	DA003	03-02-15	109	Ceiling	Fibre cement sheeting		ASB_00273	Not Detected	Ceiling	Fibre cement product	
Townsville	DA003	04-02-15	113	Ceiling	Textured finish representative sample taken in 206A [ASB_00314]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA003	02-02-15	202A, 202B, 202C	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASE_00264]			Not Detected			
Townsville	DA003	24-02-15	203A	Roof space	Vermiculite sprayed on concrete above suspended ceiling representative sample [ASB_00314] taken in 206A.			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA003	21-01-15	203A & 204	North wall	Infill under windows		ASB_00262	Not Detected	Walls	Fibre cement product	
Townsville	DA003	21-01-15	203A & 204	Ceiling space	Sprayed on product. Representative sample already taken from rm 302 [ASB_00258]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA003	21-01-15	206, 206A	Floor under floor covering	black adhesive, previously sampled in room 103, Not detected.			Not Detected	Floor		
Townsville	DA003	23-02-15	206A	ceiling space	Coating sprayed to underside of concrete slab along northern side of room		ASB_00314	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA003	24-02-15	210	Roof space	Vermiculite sprayed on concrete above suspended ceiling representative sample [ASB_00314] taken in 206A.			Not Detected	Sprayed Coating	Vermiculite	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA003	21-01-15	211	Lower window infills	Cement sheeting		ASB_00264	Not Detected	Walls	Fibre cement product	
Townsville	DA003	02-02-15	213	Floor under carpet	Carpet on floor levelling compound		ASB_00268	Not Detected	Floor		
Townsville	DA003	21-01-15	213	Wall	Cement sheet		ASB_00265	Not Detected	Walls	Fibre cement product	
Townsville	DA003	21-01-15	213 & 214	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected			
Townsville	DA003	21-01-15	213, 214, 215, 216, 219	Walls	Cement sheet. JTA [AT110712.11] No asbestos detected. Location of JTA sample not indicated. Representative sample taken in 213 [ASB_00265]			Not Detected			
Townsville	DA003	02-02-15	214	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected			
Townsville	DA003	02-02-15	215	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected	Cladding		
Townsville	DA003	03-02-15	219	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected			
Townsville	DA003	03-02-15	220	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]	AT060812.50		Not Detected			
Townsville	DA003	03-02-15	2nd floor Corridor (C201). Western Section from Rm 220 to Stairway S202.	Floor covering	Carpet laid on cream sheet vinyl from rm 220 to Western Stairs. Representative sample taken outside room 220.		ASB_00270	Not Detected	Floor	Vinyl sheet	
Townsville	DA003	13-02-15	301 External Roof	Top of building above 301 Plant Room.	Waterproofing membrane over concrete slab		ASB_00300	Not Detected	Water Proofing	Bituminous product	
Townsville	DA003	23-02-15	301 Plant Room	Inside ventilation duct from AHU 4	Original section of duct below plant room floor level, brown fibrous insulation lining.		ASB_00317	Not Detected	Insulation		Demolished
Townsville	DA003	23-02-15	301 Plant Room	Inside ventilation duct from AHU 4	Duct elbow leading into service riser below plant room floor, woven cover over glass wool insulation lining (material covered in dust).		ASB_00318	Not Detected	Insulation		Demolished
Townsville	DA003	23-02-15	301 Plant Room	Inside ventilation duct from AHU 4	Impacted dust sampled from duct elbow blades, elbow leading down into service riser below plant room floor.		ASB_00319	Not Detected	Dust		Demolished
Townsville	DA003	21-01-15	302	Ceiling	Sprayed textured finish		ASB_00258	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA003	21-01-15	302	Aircon unit surround	Fibre cement sheeting		ASB_00259	Not Detected	Walls	Fibre cement product	
Townsville	DA003	13-02-15	B001 Basement Plant Room	Ventilation plant	Flexible joints - original joints on all plant external and internal - 4 air con plant units		ASB_00299	Not Detected		Woven fibre	
Townsville	DA003	21-01-15	Eastern Stairwell	Floor covering	Vinyl sheet, blue grey in colour		ASB_00260	Not Detected	Flooring	Vinyl sheet	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA003	13-02-15	HVAC System	HVAC system was inspected for ACM Heater Banks and Fire Dampers on 13/02/2015 with Paul McDonald (Donair).	No heater banks or ACM fire dampers found. Review of old mechanical plans and visual inspection of system.			Not Detected			
Townsville	DA003	21-01-15	Western Stairwell	Floor covering	Vinyl sheet, blue grey in colour, consistent with vinyl in eastern stairwell. Representative sample [ASB_00260]			Not Detected	Flooring	Vinyl sheet	
Townsville	DA004	20-01-15	031	Floor under first layer of vinyl sheet	Grey sheet vinyl		ASB_00251	Not Detected	Flooring	Vinyl sheet	
Townsville	DA004	20-01-15	0 ground floor C002	Adjacent room 029	Vinyl sheet - blue		ASB_00252	Not Detected	Flooring	Vinyl sheet	
Townsville	DA004	23-03-15	0 Ground level	Ceiling area under walkway	Cement sheeting - previous sample taken opposite room 32	AT170712.02	ASB_00388	Not Detected	Ceiling	Fibre cement product	
Townsville	DA004	23-03-15	0 Ground level	External	Window infill - adjacent Room 033B	AT170712.03		Not Detected			
Townsville	DA004	23-03-15	004	Collections room	Heater bank lining		ASB_00387	Not Detected	Insulation	Millboard	
Townsville	DA004	19-01-15	029	Walls	Cement sheet	AT170712.06		Not Detected			
Townsville	DA004	19-01-15	032	Ceiling	cement sheet tiles. Taken as representative of ceilings in rooms 042	AT170712.05		Not Detected			
Townsville	DA004	19-01-15	033	Room 033, air-conditioning ducting	Flange Joints	AT170712.11		Not Detected			
Townsville	DA004	19-02-15	034 Lift Motor Room	Fire door	Internal core of door. Sampled from handle penetration.		ASB_00085	Not Detected	Fire door	Insulation	
Townsville	DA004	19-02-15	034 Lift Motor Room	Electrical backing board		AT170712.04		Not Detected			
Townsville	DA004	19-01-15	037	Partitions	Cement sheet. No asbestos detected. Sample taken in Room 037.	AT170712.07		Not Detected			
Townsville	DA004	20-01-15	042	Packer underneath HWS			ASB_00254	Not Detected	Packer	Fibre cement product	
Townsville	DA004	20-01-15	042	Gaskets	black wrap seal round release valves		ASB_00253	Not Detected	Pipe insulation	Bituminous product	
Townsville	DA004	16-01-15	116	Lab sink	Black bituminous material under sink. Taken to be representative of similar sinks in Rooms 024 & 028 021A		CH20150116/18	Not Detected	Insulation	Bituminous product	
Townsville	DA004	16-01-15	116	Small tank base	Fibre cement product		CH20150116/17	Not Detected	Packer	Fibre cement product	
Townsville	DA004	19-01-15	116	Ducting	Ducting adjacent fume cupboard, mastic round duct. This is representative of material used for ducting in ceiling space		CH20150116/19	Not Detected	Caulking compound	Mastic	
Townsville	DA004	19-01-15	116A off corridor	Service Cupboard	Cement sheeting placed behind cable rack going up wall		CH20150116/21	Not Detected	Cladding	Fibre cement product	
Townsville	DA004	19-01-15	117	electrical cabinet floor	Vermiculite material	AT170712.09		Not Detected			
Townsville	DA004	19-01-15	121	Walls	Cement sheet. No asbestos detected.	AT170712.08		Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA004	19-01-15	121	Shower	Cement sheeting behind shower		CH20150116/20	Not Detected	Walls	Fibre cement product	
Townsville	DA004	19-01-15	142	Floor	Sheet vinyl floor		CH20150116/22	Not Detected	Flooring	Vinyl sheet	
Townsville	DA004	23-03-15	1st Level	AHU1.2 In duct heater bank	Heater bank. Inspected internally, material visually identical to lining in 004 heater bank [ASB_00387]			Not Detected	Insulation	Millboard	
Townsville	DA004	15-01-15	244	Partitions	Compressed cement sheet. Taken as representative of partitions in 122.		CH20150114/11	Not Detected	Walls	Fibre cement product	
Townsville	DA004	15-01-15	244	Ceiling	Cement sheeting panel. Taken as representative of ceiling in room 122.	AT170712.10	CH20150114/12	Not Detected	Ceiling	Fibre cement product	
Townsville	DA004	15-01-15	244	Floor jointing	Jointing compound		CH20150114/14	Not Detected	Caulking compound	Mastic	
Townsville	DA004	15-01-15	260	jointing compound	CH 260 - jointing compound between block work and concrete columns		CH20150115/6	Not Detected	Caulking compound	Mastic	
Townsville	DA004	15-01-15	260	Ceiling	Ceiling panels		CH20150115/5	Not Detected	Suspended ceiling		
Townsville	DA004	14-01-15	261	Walls	Blockwork, concrete, plaster, laminated particle board - (CH 261 only, rooms 261 A&B walls consist of carpet glued to walls which appear to be fibrous cement product there is plasterboard wall dividing A & B)		CH20150114/1	Not Detected	Wall	Fibre cement product	
Townsville	DA004	14-01-15	261	Ceiling	Ceilings in 261 A&B are a sound proof product which are glued in position		CH20150114/2	Not Detected	Ceiling	Fibre cement product	
Townsville	DA004	15-01-15	261	Ceiling	Cement sheeting panel		CH20150115/4	Not Detected	Ceiling	Fibre cement product	
Townsville	DA004	15-01-15	261 to 262	Floor	Sheet vinyl light green speckle		CH20150115/10	Not Detected	Flooring	Vinyl sheet	
Townsville	DA004	15-01-15	262 & 262A	Floor covering	Non-asbestos vinyl sheet. No backing layer. CH green sheet vinyl		CH20150115/7	Not Detected	Flooring	Vinyl sheet	
Townsville	DA004	15-01-15	266B	Window sill	Jointing compound		CH20150115/8	Not Detected	Caulking compound	Mastic	
Townsville	DA004	27-03-15	2nd Level	AHU 2-12	In duct heater bank		ASB_00430	Not Detected	Insulation	Millboard	
Townsville	DA004	27-03-15	2nd Level	AHU 2-12	In duct heater bank		ASB_00431	Not Detected	Insulation	Fibre cement product	
Townsville	DA004	20-01-15	External	Infill panels over windows - adjacent Room 032	Cement sheet. No asbestos detected.	AT170712.01		Not Detected			
Townsville	DA004	20-01-15	External	Eaves lining	Sampled by Abscan in 2007.	285/07.DA004-11		Not Detected	Eaves	Fibre cement product	
Townsville	DA004	20-01-15	External	Fascia	Sampled by Abscan in 2007.	285/07.DA004-10		Not Detected	Fascia	Fibre cement product	
Townsville	DA004	20-01-15	External	Potential Flue Pipe	Previous Survey by JTA noted an external flue pipe that was assumed to contain asbestos but was not accessed "due to height restriction". No fibre cement flue pipes were found during this survey.			Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA004	16-01-15	Level 3 Roof space	Underside of roof	Plaster joint round fire seal		CH20150 116/15	Not Detected	Sprayed fire rating/insulation	Insulation	
Townsville	DA004	15-01-15	Telecom Cupboard Adjacent to Room 222 & 253C	Floor	Infill in concrete floor		CH20150 115/9	Not Detected	Flooring	Vermiculite	
Townsville	DA005	19-03-15	002 Storeroom	Floor	Tile Adhesive		ASB_001 06B	Not Detected	Floor Covering		
Townsville	DA005	20-03-15	External East side, C000	Facia to front awning	Appears to be new material		ASB_001 08	Not Detected	Cladding	Fibre cement product	
Townsville	DA005	20-03-15	External East Side, covered walkway between main building and toilet block.	Facias to awning including at garden/ courtyard	Appears to be new material. Visually identical to sample ASB_00108			Not Detected			
Townsville	DA005	19-03-15	Undercroft below 001	Doorway in northern end of west wall	Fibre cement cladding as doorway infill		ASB_001 07	Not Detected	Wall	Fibre cement product	
Townsville	DA006	03-02-15	001	Infill panels above servery		AT120712.03		Not Detected	Infill	Fibre cement product	Demolished
Townsville	DA006	17-07-17	001	Central partition	Previously sampled by JTA	AT120712.05		Not Detected	Wall	Fibre cement product	Demolished
Townsville	DA006	03-02-15	007	Panelling	Infill panel to range hood. Same as ASB_00038			Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DA006	03-02-15	008	Infill panels above refrigerators/cool room		See AT120712.03		Not Detected	Infill	Fibre cement product	Demolished
Townsville	DA006	03-02-15	008	Infill panels above servery		AT120712.03		Not Detected	Infill	Fibre cement product	Demolished
Townsville	DA006	03-02-15	009	Walls		AT120712.07		Not Detected	Wall	Fibre cement product	Demolished
Townsville	DA006	17-07-17	001	Infill panels above eastern (main) entrance	Not sampled previously		ASB_000 31	Not Detected	Infill	Fibre cement product	Demolished
Townsville	DA006	18-07-17	011	East wall, southern end	Cream painted sheeting		ASB_000 33	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DA006	02-02-15	External	Expansion Joints	Expansion joint. 2 locations on South wall, 1 on the west wall. 3 linear metres each. Sampled at South Wall.		ASB_000 34	Not Detected	Sealant	Mastic	Demolished
Townsville	DA006	03-02-15	012	Ceiling	Sample taken from southern half. Northern half is MDF tile		ASB_000 35	Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DA006	03-02-15	012	Wall	One sheet to South west corner. Different to other sheeting		ASB_000 37	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DA006	18-07-17	007	Panelling	Panelling to air conditioning bulkhead at rear of kitchen area		ASB_000 38	Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DA006	17-07-17	001	Expansion joint under running North-south (directly beneath eastern most beam)			ASB_030 49	Not Detected	Sealant	Bituminous product	Demolished
Townsville	DA006	17-07-17	001	1x hole in slab 1200mm Nth of central partition wall	Hole approx 20mm in slab with black resin filling the hole		ASB_030 50	Not Detected	Sealant	Bituminous product	Demolished
Townsville	DA006	17-07-17	01	Adhesive layer throughout, above expansion joints in slab and beneath sheet vinyl.	Black adhesive <5mm thick. Adhered to sheet vinyl. Qty is an estimate as could be under ceramic tiles.		ASB_030 51	Not Detected	Sealant	Mastic	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA006	17-07-17	01	Sealant at boarder of ceramic tiles and sheet vinyl (west end of room).	Grey material along channel		ASB_03052	Not Detected	Sealant	Mastic	Demolished
Townsville	DA006	18-07-17	External (west aspect)	External to 009 cold room			ASB_03053	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DA006	18-07-17	External (East aspect)	Infill panels above East entry doors to 001			ASB_03054	Not Detected	Infill	Fibre cement product	Demolished
Townsville	DA007	10-02-15	External	Infill beside air conditioner southern wall	Cement sheeting		ASB_00288	Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DA007	11-02-15	External & internal	Soffit lining and ceiling lining	Plywood with a layer of wood type material bonded on thin paper like material		ASB_00291	Not Detected	Eaves		Demolished
Townsville	DA007	10-02-15	Internal	Infill beside air conditioner - different thickness sheeting to external southern wall	Cement sheeting		ASB_00289	Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DA008	05-02-15	001	South wall	Air conditioning unit on the other (external) side of the wall. Same material as used externally, ASB 00044			Not Detected	Wall	Fibre cement product	
Townsville	DA008	05-02-15	External	Gable end infill sheets. South end of building, West side.	Material appears to be not original. Likely installed at same time as windows below. Fixtures used to secure the sheet look different to the eaves. Also used as a cladding to the wall where air conditioning penetrates masonry.		ASB_00044	Not Detected	Cladding	Fibre cement product	
Townsville	DA008	05-02-15	External	Expansion joint	Previously sampled	AT110712.20		Not Detected	Sealant	Bituminous product	
Townsville	DA008	05-02-15	Internal	Ceiling space	Suspended plasterboard ceiling. No manhole. Inspected ceiling space in several locations and no fibreglass insulation sits on top of the ceiling panels. Foil backed fibreglass applied directly beneath roof.			Not Detected			
Townsville	DA009	05-02-15	000C (entry corridor)	Ceiling space	Removed 2 plaster ceiling panels to inspect for presence of heater banks. None observed.			Not Detected			
Townsville	DA009	05-02-15	001	Ceiling space	Removed 6 plaster ceiling panels to inspect for presence of heater banks. None observed.			Not Detected			
Townsville	DA009	05-02-15	002	Ceiling space	Removed 6 plaster ceiling panels to inspect for presence of heater banks. None observed.			Not Detected			
Townsville	DA009	05-02-15	006	Ceiling space	Removed 4 plaster ceiling panels to inspect for presence of heater banks. None observed.			Not Detected			
Townsville	DA009	05-02-15	014	Door	No fibre cement lining to door as previously observed by JTA. Removed latch and inspected cross section of door, all timber			Not Detected	Door		
Townsville	DA010	05-02-15	External	Eaves	Visual assessment confirms previous analysis of fibre cement. Plastic strips used at joins	AT120712.15		Not Detected	Eaves	Fibre cement product	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA010	05-02-15	External	North wall	Mastic to expansion joint		ASB_00045	Not Detected	Sealant	Mastic	Demolished
Townsville	DA018	24-03-15	0 Ground Floor	Ceilings in stage 1 and 2	Sprayed Vermiculite suspected above new plaster ceilings. Material visually identical to Level 1 ceilings.			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018		0 Ground Floor. Passageway to Teaching & Learning Development	Walls	Item sampled by JTA 17/07/2012	AT170712.23		Not Detected	Cladding	Fibre cement product	
Townsville	DA018	24-03-15	029 Closed Compactus	Ceiling	Sprayed coating. White powdery material (not vermiculite) Coated with paint. Also found in other rooms including 028. Not practicable to assess full extent due to new plaster ceilings.		ASB_00126	Not Detected	Ceiling	Textured Coating	
Townsville	DA018		041	Walls	Item sampled by JTA 17/07/2012	AT170712.22		Not Detected	Cladding	Fibre cement product	
Townsville	DA018		063	External wall	Item sampled by JTA 17/07/2012	AT170712.21		Not Detected	Cladding	Fibre cement product	
Townsville	DA018	22-03-15	103 (including A to G)	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	105 & 105A	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	107 "Ladies" Toilet (stage 1)	South and East walls with bent metal batons on concrete.	Sample from South wall. Only fibre cement walls in this room. Other walls are clad with timber boards (appear original), cubical partitions are steel cased with wood filling.		ASB_00122	Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	108 "Gentlemen" Toilet (stage 1)	North and East walls with bent metal batons on concrete.	Sample from North wall. Only fibre cement walls in this room. Other walls are clad with timber boards (appear original), cubical partitions are steel cased with wood filling.		ASB_00121	Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	110	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	111 office	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	112 plant room	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	113 male toilet	North and West walls with bent metal battens onto cast concrete.	Walls and cladding appear to be a later addition.		ASB_00116	Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	114 female toilet	South and West walls with bent metal battens onto cast concrete.	Walls and cladding appear to be a later addition.		ASB_00117	Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	115 (stage 1)	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018		120	HVAC Flange Joints	Item sampled by JTA 17/07/2012	AT170712.28		Not Detected	Sealant	Mastic	
Townsville	DA018	22-03-15	1st Level, central stairs (stage 1)	Ceiling at western side of stairs	Sprayed coating, darker shade than Stage 2 side.		ASB_00120	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	1st Level, data rack room East of fire stairs.	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA018	22-03-15	1st Level, eastern end (stage 2)	Ceiling, sampled above southern duct above book shelves.	Sprayed coating.		ASB_00119	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018		1st Level, Library	Floor under floor covering, middle stripe section of floor	Item sampled by JTA 17/07/2012	AT170712.27		Not Detected	Floor	Fibre cement product	
Townsville	DA018	20-03-15	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately south of Toilet 114. Location shown on MECH-T106-A2-REV-B.	Wiring to heater bank elements. White woven wire insulation. Wiring is redundant.		ASB_00111	Not Detected	Wire Insulation	Woven fibre	
Townsville	DA018	20-03-15	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately south of Toilet 114. Location shown on MECH-T106-A2-REV-B.	Wiring to heater bank elements. Brown woven wire insulation. Wiring is redundant.		ASB_00112	Not Detected	Wire Insulation	Woven fibre	
Townsville	DA018	20-03-15	1st Level, Library, Eastern end (Stage 2)	Ceiling immediately south of Toilet 114	Thick sprayed vermiculite coating on underside of slab.		ASB_00113	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	20-03-15	1st Level, Library, Eastern end (Stage 2)	HVAC duct immediately North of Fire Stairs & Toilets	Flange sealant/mastic. Grey flexible mastic, appears to contain fibre.		ASB_00115	Not Detected	Sealant	Mastic	
Townsville	DA018	20-03-15	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately North of Fire Stairs & Toilets. Location shown on MECH-T106-A2-REV-B.	Wiring to heater bank elements. White woven wire insulation. Wiring is redundant. Same as ASB_00111			Not Detected	Wire Insulation	Woven fibre	
Townsville	DA018	20-03-15	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately North of Fire Stairs & Toilets. Location shown on MECH-T106-A2-REV-B.	Wiring to heater bank elements. Brown woven wire insulation. Wiring is redundant. Same as ASB_00112			Not Detected	Wire Insulation	Woven fibre	
Townsville	DA018	22-03-15	210 "Ladies" Toilet (stage 1)	South and East walls with bent metal batons on concrete.	Only fibre cement walls in this room. As for ASB_00121 & ASB_00122. Other walls are clad with timber boards (appear original), cubical partitions are steel cased with wood filling.			Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	210 "Ladies" Toilet (stage 1)	Ceiling	Same as level 1 sprayed coating. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	211 "Gentlemen" Toilet (stage 1)	Ceiling	Same as level 1 sprayed coating. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018	22-03-15	211 "Gentlemen" Toilet (stage 1)	North and East walls with bent metal batons on concrete.	Only fibre cement walls in this room. As for ASB_00121 & ASB_00122. Other walls are clad with timber boards (appear original), cubical partitions are steel cased with wood filling.			Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	226 gentlemen toilet	North and West walls with bent metal battens onto cast concrete.	Walls and cladding appear to be a later addition. Visually identical material to ASB_00116.			Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	227 ladies toilet	South and West walls with bent metal battens onto cast concrete.	Walls and cladding appear to be a later addition. Visually identical material to ASB_00117.			Not Detected	Wall	Fibre cement product	
Townsville	DA018	22-03-15	2nd Level, Central Stairs, Stage 1 west of stairs	Ceiling	Tan coloured vermiculite sprayed coating on compressed straw ceiling panels		ASB_00124	Not Detected	Sprayed Coating	Vermiculite	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DA018	22-03-15	2nd Level, near Central Stairs, Stage 2 East of stairs	Ceiling	Brown wood shaving and vermiculite sprayed coating on compressed straw ceiling panels. Throughout Stage 2 and in Stage 3.		ASB_00125	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DA018		Entrance way to Room A006	Ceiling to alcove	Item sampled by JTA 17/07/2012	AT170712.20		Not Detected	Sprayed Coating	Textured Coating	
Townsville	DA018		External. Lower south wall	Window shade panels	Item sampled by JTA 17/07/2012	AT170712.25		Not Detected	Shade Panels	Fibre cement product	
Townsville	DA018		External. South wall.	window shade and upper panel over central entrance	Item sampled by JTA 17/07/2012	AT170712.24		Not Detected	Cladding	Fibre cement product	
Townsville	DA018		External. Upper south wall	Window shade panels	Item sampled by JTA 17/07/2012	AT170712.26		Not Detected	Shade Panels	Fibre cement product	
Townsville	DA018	25-03-15	Roof Space, Eastern End (Stage 2)	Decommissioned heater banks have wire insulation visually identical to Level 1 heater banks				Not Detected			
Townsville	DA018	25-03-15	Roof Space, Eastern End (Stage 2)	Heater banks (decommissioned) Six (6) Locations as shown on MECH-T106-A3-REV-B.	Location of previous heater banks inspected internally. Heater elements and insulation lining no longer in place, internal duct surfaces clean.			Not Detected	Heater Bank		
Townsville	DA018	24-03-15	Roof Space, Western End (Stage 1)	Heater bank (decommissioned) in central duct heading west from main riser. HB location shown on MECH-T106-A3-REV-B.	Location of previous heater bank inspected internally. Heater elements and insulation lining no longer in place, internal duct surfaces clean.			Not Detected	Heater Bank		
Townsville	DA018	25-03-15	Roof Space, Western End (Stage 1)	Heater bank (decommissioned) in duct heading North from main riser. Duct is shown on MECH-T106-A3-REV-B but HB not marked.	Location of previous heater bank inspected internally. Heater elements and insulation lining no longer in place, internal duct surfaces clean.			Not Detected	Heater Bank		
Townsville	DA018	25-03-15	Roof Space, Western End (Stage 1)	Heater bank (decommissioned) at South side of concrete slab in duct running East-West. Duct is shown on MECH-T106-A3-REV-B but HB not marked.	Location of previous heater bank inspected internally. Heater elements and insulation lining no longer in place, internal duct surfaces clean.			Not Detected	Heater Bank		
Townsville	DB017	17-03-15	022	Pipe work	Lagging representative sample taken in room 122 [ASB_00367]			Not Detected	Insulation	Woven fibre	
Townsville	DB017	16-03-15	028	Ceiling	Sprayed texture finish on concrete		ASB_00372	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DB017	16-03-15	028A	Floor	Clear/Amber adhesive, Carpet glued over - appears to be remnant vinyl in corners of room and black glue under clear glue. Insufficient black adhesive in sample ASB_00373 for laboratory to test.		ASB_00373	Not Detected	Adhesive	Adhesive	
Townsville	DB017	16-03-15	028B	Floor	Amber adhesive. Carpet glued to concrete - appears to be remnant vinyl in corners of room. No black adhesive noted at sample location.		ASB_00371	Not Detected	Adhesive		

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB017	17-03-15	038C	Wall	2 x small Infill sections on west wall		ASB_00375	Not Detected	Cladding	Fibre cement product	
Townsville	DB017	17-03-15	038D	Wall	1 small Infill sections on west wall - representative sample taken 38C [ASB_00375]			Not Detected	Cladding	Fibre cement product	
Townsville	DB017	23-03-15	040A	Walls	Infill round door cement sheeting representative sample taken 040D [ASB_00390]			Not Detected	Wall	Fibre cement product	
Townsville	DB017	23-03-15	040A	Fascia	Cement sheeting 9mm sheeting representative sample taken in walkway between bldg. 17 & 34 [ASB_00360]			Not Detected	Fascia	Fibre cement product	
Townsville	DB017	23-03-15	040A	Windows South face	Jointing compound round all windows		ASB_00392	Not Detected	Sealant	Mastic	
Townsville	DB017	23-03-15	040C	Floor	Sheet vinyl on concrete		ASB_00389	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DB017	23-03-15	040D	Columns	Formwork representative sample taken North wing west face [ASB_00393]			Not Detected	Formwork	Fibre cement product	
Townsville	DB017	23-03-15	040D	Walls	Cement sheeting		ASB_00390	Not Detected	Wall	Fibre cement product	
Townsville	DB017	17-03-15	047	East wall	Fibre cement sheeting - representative sample taken in 048 [ASB_00374]	AT180712.40		Not Detected	Wall		
Townsville	DB017	17-03-15	047A	West & East wall	Fibre cement sheeting - representative sample taken in 048 [ASB_00374]			Not Detected	Wall	Fibre cement product	
Townsville	DB017	17-03-15	048	West wall	Fibre cement sheeting		ASB_00374	Not Detected	Wall	Fibre cement product	
Townsville	DB017	17-03-15	052	Roof Space	Inspected, no signs of remnant ACM.			Not Detected	NA		
Townsville	DB017	18-03-15	060 plant room	Ceiling	Sprayed texture finish		ASB_00384	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DB017	18-03-15	068	Roof Space	Suspended ceiling - steel roof structure above no signs of ACM			Not Detected	NA		
Townsville	DB017	18-03-15	069	Roof Space	Suspended ceiling - steel roof structure above no signs of ACM			Not Detected	NA		
Townsville	DB017	18-03-15	071	Roof Space	Suspended ceiling - steel roof frame above no sign of ACM			Not Detected	NA		
Townsville	DB017	18-03-15	071	Walls	Fibre board fixed to Plasterboard which is then fixed to fibre cement sheeting South west Cnr.. near air return vent		ASB_00382	Not Detected	Wall	Fibre cement product	
Townsville	DB017	18-03-15	071A	Floor	Cream vinyl tiles (black adhesive under tiles assumed to contain asbestos.	AT180712.37		Not Detected	Floor Covering	Vinyl tile	
Townsville	DB017	18-03-15	071A	Ceiling	Cement sheeting - sampled previously in 077A	See AT180712.36		Not Detected	Ceiling		
Townsville	DB017	18-03-15	071A	Walls	Cement sheeting	See AT180712.36		Not Detected	Wall		

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB017	18-03-15	071B	Ceiling	Cement sheeting	See AT180712.36		Not Detected	Ceiling		
Townsville	DB017	18-03-15	071B	Walls	Cement sheeting - sampled previously in 077A	See AT180712.36		Not Detected	Wall		
Townsville	DB017	18-03-15	077A	Walls	Cement sheeting	AT180712.36		Not Detected	Wall		
Townsville	DB017	17-03-15	078	Walls	Cement sheeting	AT180712.32		Not Detected	Wall		
Townsville	DB017	17-03-15	078A	Walls internal lining	Cement sheeting		ASB_00378	Not Detected	Wall	Fibre cement product	
Townsville	DB017	17-03-15	078A	Walls external lining	Cement sheeting		ASB_00379	Not Detected	Wall	Fibre cement product	
Townsville	DB017	04-03-15	101 lecture room	Top section of all walls and ceiling	Sprayed textured finish		ASB_00355	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DB017	05-03-15	121	Ceiling	Old duct with black jointing material - sample taken room 247 [ASB_00331]			Not Detected	Sealant	Bituminous product	
Townsville	DB017	05-03-15	122	Water pipe	Wrapped with insulation material		ASB_00367	Not Detected	Pipe Lagging	Woven fibre	
Townsville	DB017	04-03-15	128	Roof space through suspended plasterboard ceiling	Inspected, safety mesh, modern insulation, no signs of ACM			Not Detected	NA		
Townsville	DB017	04-03-15	129C	Eastern wall	Infill section		ASB_00357	Not Detected	Wall	Fibre cement product	
Townsville	DB017	04-03-15	131	Walls	Infill above windows		ASB_00358	Not Detected	Wall	Fibre cement product	
Townsville	DB017	04-03-15	139 & 138	Roof space through suspended plasterboard ceiling	Inspected, safety mesh, modern insulation, no signs of remnant ACM			Not Detected	NA		
Townsville	DB017	05-03-15	164A	Wall - northern side	Fibre cement sheeting - previously sampled	AT180712.42		Not Detected	Wall		
Townsville	DB017	05-03-15	165	Wall -southern side	Fibre cement sheeting - previously sampled room 164A	See AT180712.42		Not Detected	Wall		
Townsville	DB017	05-03-15	1st floor S102	Walkway from bldg. 017 to bldg. 34 - southern side wall and North side wall past window ledge	Cement sheeting same as under window ledge sample [ASB_00362]			Not Detected	Wall	Fibre cement product	
Townsville	DB017	25-02-15	201 lecture room	Roof space	Inspected for remnant ACM, no suspect material found. Steel structure with modern insulation material.			Not Detected	NA		
Townsville	DB017	03-03-15	220	Near emergency exit door S205	Mastic against door frame		ASB_00348	Not Detected	Sealant	Mastic	
Townsville	DB017	03-03-15	220	Roof space	Inspected for remnant ACM. Viewed safety mesh, modern insulation, box gutter, no signs of remnant limpet or other suspect material.			Not Detected	NA		
Townsville	DB017	03-03-15	221	Roof space	Inspected for remnant ACM. Viewed safety mesh, modern insulation, no suspect materials found.			Not Detected	NA		

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB017	03-03-15	225	Floor	Sheet vinyl on concrete kitchen area		ASB_003 51	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DB017	26-02-15	247	Southern wall Plant room	Old duct with black jointing material		ASB_003 31	Not Detected	Sealant	Mastic	
Townsville	DB017	26-02-15	247	Floor Various locations	Jointing mastic attached to floor grey in colour		ASB_003 34	Not Detected	Sealant	Mastic	
Townsville	DB017	26-02-15	247	Floor Various locations	Amber adhesive coating on floor hard brittle product		ASB_003 35	Not Detected	Surface Coating	Paint	
Townsville	DB017	26-02-15	247	West wall section and various locations	Material coated on concrete column edge		ASB_003 36	Not Detected	Surface Coating	Bituminous product	
Townsville	DB017	26-02-15	247	West Wall - old insulation	Wool type material flame.		ASB_003 37	Not Detected	Insulation	Woven fibre	
Townsville	DB017	26-02-15	248	West wall below insulation	Fibre cement sheeting		ASB_003 38	Not Detected	Cladding	Fibre cement product	
Townsville	DB017	26-02-15	248	Drain	Infill round drain		ASB_003 39	Not Detected	Sealant	Mastic	
Townsville	DB017	26-02-15	249	Walls	Cement sheet	AT180712.43A		Not Detected	Wall		
Townsville	DB017	02-03-15	249 radioactive room	Roof/ceiling of structure	Cement sheet (over timber frame)		ASB_003 47	Not Detected	Roof	Fibre cement product	
Townsville	DB017	02-03-15	302 outside room	Concrete deck area	Waterproof membrane over joints & cracks		ASB_003 40	Not Detected	Sealant		
Townsville	DB017	17-03-15	C001	Floor west end	Different grey tiles - brighter tile with more white and black throughout		ASB_003 76	Not Detected	Floor Covering	Vinyl tile	
Townsville	DB017	04-03-15	C101	Ceiling space	Ceiling space inspected for remnant ACM. No suspect materials found. Suspended ceiling plaster board - roof space concrete and duct work.			Not Detected	NA		
Townsville	DB017	04-03-15	C101	Ceiling	Sprayed texture finish sample taken previously taken from ground floor. New sample taken in western corner of ceiling		ASB_003 54	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DB017	25-02-15	C201	Top of access stair ceiling	Suspended ceiling tiles compressed fibre material (SMF)		ASB_003 26	Not Detected	Ceiling	Low Density Fibre Board	
Townsville	DB017	26-02-15	C201	Floor	Vinyl sheet on concrete		ASB_003 30	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DB017	04-03-15	C201	High section of suspended ceiling - roof space	Inspected for remnant ACM. Viewed safety mesh, modern insulation, no suspect materials found.			Not Detected	NA		
Townsville	DB017	18-03-15	F001 entrance South side	Pipes outside coming out of ground west wall - external	Pipes have black bituminous insulation		ASB_003 85	Not Detected	Insulation	Bituminous product	
Townsville	DB017	23-03-15	North wing - North face	DT surround	Formwork		ASB_003 94	Not Detected	Formwork	Fibre cement product	
Townsville	DB017	23-03-15	North wing - West face	Columns	Formwork		ASB_003 93	Not Detected	Formwork	Fibre cement product	
Townsville	DB017	23-03-15	S001	Foyer & East wall	Cement sheet with pebble finish	AT180712.31		Not Detected	Wall	Fibre cement product	
Townsville	DB017	05-03-15	S102	Walkway from bldg. 017 to bldg. 34 - fascia on external wall room 131 southern side	9mm sheeting - this is different from other fascia material used on building		ASB_003 60	Not Detected	Fascia	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB017	05-03-15	S102	Walkway from bldg. 017 to bldg. 34 - wall under window ledge room 131 lined with fibre cement sheeting over block work	Cement sheeting		ASB_003 62	Not Detected	Wall	Fibre cement product	
Townsville	DB017	05-03-15	S102	Walkway from bldg. 017 to bldg. 34 - ceiling	Cement sheeting		ASB_003 63	Not Detected	Ceiling	Fibre cement product	
Townsville	DB017	05-03-15	S102	Walkway from bldg. 017 to bldg. 34 - floor	Vinyl sheet on concrete		ASB_003 64	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DB017	05-03-15	S102	Walkway from bldg. 017 to bldg. - window ledge joins	Joins filled with jointing compound		ASB_003 65	Not Detected	Sealant	Mastic	
Townsville	DB017	26-02-15	S201 top of stairs	Slab edge	Sprayed texture finish		ASB_003 29	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DB017	20-03-15	South wing bottom level work shop	West and east gutter Box gutter on roof	Lined with rubber product		ASB_003 86	Not Detected	Guttering		
Townsville	DB017	02-03-15	Top platform weather station above lift motor room.	Floor	Black bituminous product with stones laid over		ASB_003 41	Not Detected	Adhesive	Bituminous product	
Townsville	DB017	02-03-15	Top platform weather station above lift motor room.	Edge board	Fibre cement sheeting		ASB_003 42	Not Detected	Cladding	Fibre cement product	
Townsville	DB020	24-03-15	000C	Walls	Cement sheet		ASB_004 00	Not Detected	Wall	Fibre cement product	
Townsville	DB020	24-03-15	003	Ceiling entrance external	Cement sheet		ASB_004 05	Not Detected	Ceiling	Fibre cement product	
Townsville	DB020	24-03-15	008	Ceiling	Cement sheet		ASB_003 97	Not Detected	Ceiling	Fibre cement product	
Townsville	DB020	24-03-15	009	Walls	Cement sheet		ASB_003 98	Not Detected	Wall	Fibre cement product	
Townsville	DB020	24-03-15	011	Walls	Cement sheet	AT120712.23		Not Detected	Wall	Fibre cement product	
Townsville	DB020	24-03-15	012	Ceiling	Cement sheet		ASB_004 01	Not Detected	Ceiling	Fibre cement product	
Townsville	DB020	24-03-15	016	Plant room	Remnant cement sheeting		ASB_004 02	Not Detected	Ceiling	Fibre cement product	
Townsville	DB020	24-03-15	022	Walls	Cement sheet	AT120712.22		Not Detected	Wall	Fibre cement product	
Townsville	DB020	24-03-15	C000	Duct	Jointing		ASB_003 99	Not Detected	Sealant	Mastic	
Townsville	DB020	24-03-15	External	Block walls	Control joint		ASB_004 04	Not Detected	Sealant	Mastic	
Townsville	DB020	24-03-15	External	Eaves west end	Cement sheet, resampled as previous description of location was incomplete.	AT120712.20	ASB_004 06	Not Detected	Eaves	Fibre cement product	
Townsville	DB021	12-12-15	002E	Ceiling	Plaster			Not Detected	Ceiling		Demolished
Townsville	DB021	12-12-15	003	Ceiling	Above both entrances. Ceilings are plaster board. Glass fibre ceiling within lecture room.			Not Detected	Ceiling		Demolished
Townsville	DB021	08-07-17	004A	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB_00205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	19-07-12	004A	Walls	Same material as ASB_00210			Not Detected	Wall	Fibre cement product	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB021	06-07-17	006	Walls	Same material as ASB_00211			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	006	South wall Infill above exit door	Same material as ASB_00211			Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DB021	06-07-17	006	Walls	Same as ASB_00211			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	010	Entrance area ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB_00205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	19-07-12	010	Walls	Same as ASB_00211			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	010B	Entrance area ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB_00205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012B	Walls	North wall has cladding beneath the Windows and west wall. Same as 213.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012C	Wall	South wall only. Same as 213			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012D	Wall	South wall to stairs leading down to door. Same as 213			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012D	Infill	Infill panel above door. Same as 213.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012F	Walls	North wall has cladding beneath the Windows and west wall. Same as 213.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012H	Walls	North wall has cladding beneath the Windows and west wall. Same as 213.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	015	Floor covering	Blue vinyl tile. Presumed no asbestos detected by JTA from sample taken from floor in Ground Floor Corridor	See AT190712.05		Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	12-12-15	015	Ceiling		AT190712.07		Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	08-07-17	017	Partitions (not found)	Presumed asbestos by JTA from sample taken in 018. No partitions in 017 cleaners cupboard	See AT190712.11		Not Detected	Wall		Demolished
Townsville	DB021	08-07-17	017	Ceiling	Presumed asbestos by JTA cross referencing Abscan 2007 sample. Ceiling to 017 is cast concrete.	See 0285/07 DB021-23		Not Detected	Ceiling		Demolished
Townsville	DB021	08-07-17	022	Flues / vent pipes	Presumed asbestos by JTA cross referencing Abscan 2007 sample. Item not found at this location.	See 0285/07 DB021-11		Not Detected	Flue	Fibre cement product	Demolished
Townsville	DB021	19-07-12	022	Walls	Presumed no asbestos detected by JTA from sample taken from walls in 012H	See AT190712.08		Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	022	Ceiling	Presumed no asbestos detected by JTA from sample taken from ceiling in 015	See AT190712.07		Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	100C	Walls	Cladding outside entrance to Room 116. Same as ASB209.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	100C	Floor	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB021	06-12-15	100C	Wall	Infill to doorways of Rooms 119 and 120. Same as ASB_00209			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	102	Infill panels to top of fume cupboard	Fibre cement sheet the same as ASB_00205			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	103 Chemistry Lab	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	103	Infill panels to top of fume cupboard	Fibre cement sheet the same as ASB205			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	103A	Walls	Same as ASB_00206.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	103A	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	103A	Wall	Wall panelling abutting northern entrance to Room 103. Same as ASB206			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	110	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	110	Infill panels to top of fume cupboard				Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	10-07-17	110A	South Wall				Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	09-07-17	112B	North Wall	Modern fibre cement. Same as ASB_00209			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	113	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	116	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	09-07-17	119	Ceiling	Suspended ceiling panels with smooth finish. Plaster panels. Previously documented as ACM.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	19-07-12	119	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	06-12-15	120	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	120	Floor	Vinyl tile beneath carpet	Same as AT190712.12		Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	07-07-17	206	Splashback wall	Presumed asbestos by JTA from sample of wall from 121. Item not found 7/7/17	See AT190712.13		Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	209A	Floor under floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	05-11-15	224A	Floor	Sheet vinyl on concrete floor with carpet laid over - representative sample taken in Room 206			Not Detected	Floor	Vinyl sheet	Demolished
Townsville	DB021	19-07-12	228	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB021	05-11-15	230	Floor	Sheet vinyl on concrete floor with carpet laid over - representative sample taken in Room 206			Not Detected	Floor	Vinyl sheet	Demolished
Townsville	DB021	06-11-15	231	Undertook intrusive inspection of floor and from roof space above.	No ACM found. Walls are cast concrete or masonry block. No suspect floor coverings found.			Not Detected			Demolished
Townsville	DB021	19-07-12	232	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	19-07-12	103C Corridor approaching 119	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	18-06-15	External	AHU2. E000003	Red Flexible duct connector to original yellow ducting on east side. See ASB 00513			Not Detected	Vinyl		Demolished
Townsville	DB021	08-07-17	008B	Walls	As for 008A			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	10-07-17	HVAC System	Heater banks in Supply Ducts	A review of historical plans, visual inspection of the plant room and ceiling spaces throughout the building and discussion with Paul McDonald of Kaltec did not reveal the presence of any heater banks with ACM.			Not Detected			Demolished
Townsville	DB021	11-07-17	003	Ceiling	Above both entrances. Ceilings are plaster board. Glass fibre ceiling within lecture room.			Not Detected	Ceiling		Demolished
Townsville	DB021	11-07-17	003	Ceiling	Above both entrances. Ceilings are plaster board. Glass fibre ceiling within lecture room.			Not Detected	Ceiling		Demolished
Townsville	DB021	06-07-17	005A	South section east wall				Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	005A	South section southern wall				Not Detected		Fibre cement product	Demolished
Townsville	DB021	09-07-17	120	South Wall	Two sheet types. Same as rm 119.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	09-07-17	112A	North Wall.	Same material as sampled on 112 side.			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	11-07-17	220A	Floor	Carpet on vinyl tiles - representative sample taken in Room 223			Not Detected	Floor Covering	Vinyl tile	Demolished
Townsville	DB021	06-12-15	115	Floor	Vinyl tile beneath carpet. Grey.	AT190712.12		Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	09-07-17	114	Floor	Vinyl tile beneath carpet. Grey.	AT190712.12		Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	10-07-17	225C	East wall	Representative sample taken from 225			Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	203	Internal partition wall				Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	19-07-12	206	Walls				Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	005	Western upper Wall	Sample taken between panels 1 & 2		ABS_02352	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	102	Ceiling	Suspended fibre cement sheets with a white textured surface		ASB_00205	Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	06-12-15	103	East Wall	Wall panelling abutting northern entrance to Room 103A		ASB_00206	Not Detected	Wall	Fibre cement product	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB021	06-12-15	116	Walls	North, south and east walls. Internal & external cladding.		ASB_00209	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	004	Walls	North, south and west walls are fibre cement. East wall is plasterboard, no sheeting behind it.		ASB_00210	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	005A	South section, partition Wall to 005	Unpainted surface.		ASB_00211	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	005A	Main section, south Wall	Upper infill above masonry block wall. White surface.		ASB_00212	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	010B	East Wall near fire extinguisher	South, east and west walls. North wall is concrete	AT190712.06	ASB_00213	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	08-07-17	023 plant room	A/C AUX UNIT 3. E001278	Flexible duct connector, red colour. Present to join on north end of unit and top of unit.		ASB_00513	Not Detected	Vinyl		Demolished
Townsville	DB021	18-06-15	External	Radio chem lab AHU. E001330	Grey flexible duct connectors on top of unit.		ASB_00514	Not Detected	Vinyl		Demolished
Townsville	DB021	18-06-15	241 plant rm	Room 241. Internal lining to AHU E001412.			ASB_00515	Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DB021	18-06-15	241 External	On top of AHU below old heater bank locations.	Brown micaceous millboard debris. Also present as lining to part of the ductwork and debris inside ductwork.		ASB_00516	Not Detected	Insulation		Demolished
Townsville	DB021	18-01-16	Lift motor room	Brake shoe	Appears to be metallic		ASB_02277	Not Detected	Brake	Friction Product	Demolished
Townsville	DB021	18-02-16	107	Floor	Blue vinyl floor tile		ASB_02281	Not Detected	Floor Covering	Vinyl tile	Demolished
Townsville	DB021	18-02-16	107	Walls	Internal and external walls, southern and eastern aspect and door frame		ASB_02282	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	12-12-15	012	North Wall near fire extinguisher	Fibre cement infill to door frames of 012H and 012I and between 012G and 012H. Walls are primarily gyprock.		ASB_02283	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	005	Western lower wall	Second sheet from western wall. Wall switch g1/29		ASB_02349	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-07-17	005	South Wall	Sampled under the sink in corner. Representative of both sides of door.		ASB_02351	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	07-07-17	008A	North wall outer layer. PCR room.	Reddish.		ASB_02358	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	07-07-17	008A	North wall. Inner layer. PCR room.	Grey		ASB_02359	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	08-07-17	003	East side HVAC supply duct.	Settled dust at base of duct		ASB_02360	Not Detected	Dust	Dust	Demolished
Townsville	DB021	06-07-17	005 & 005A	Ceiling to south section.	Suspended ceiling panels with smooth finish.		ASB_02362	Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB021	08-07-17	029C	ground floor corridors	Blue 300mm vinyl tiles		ASB_02363	Not Detected	Floor Covering	Vinyl tile	Demolished
Townsville	DB021	08-07-17	012D	Walls	Outer cladding to all walls, sampled at vent riser.		ASB_02366	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	08-07-17	023 plant room	Two steel armoured cables running from back of main switchboard to cable tray into room 005A	Tar impregnated woven fibre outer layer		ASB_02369	Not Detected	Cable	Woven fibre	Demolished

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB021	09-07-17	119	North Wall	Two types of fibre cement. Sample from older looking Hardy's Versilux. Same material in Rm120.		ASB_023_73	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-12-15	112	Wall to 112A	common with 112A. Appears to be modern fibre cement.		ASB_023_74	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	11-07-17	223	Floor	Grey flexible vinyl tiles with yellow adhesive.		ASB_023_79	Not Detected	Floor	Vinyl tile	Demolished
Townsville	DB021	05-11-15	209A	Floor	Carpet on vinyl sheet		ASB_033_17	Not Detected	Floor Covering	Vinyl sheet	Demolished
Townsville	DB021	05-11-15	203	Floor	Vinyl tiles 300mm x 300mm grey on North side of room		ASB_033_18	Not Detected	Floor Covering	Vinyl tile	Demolished
Townsville	DB021	05-11-15	206	Floor	Sheet vinyl on concrete floor.		ASB_033_20	Not Detected	Floor Covering	Vinyl sheet	Demolished
Townsville	DB021	10-07-17	207	Door way sheeted over	Cement sheeting		ASB_033_21	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	05-11-15	225	West wall	Cement sheeting		ASB_033_23	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	05-11-15	221	Southern wall	Cement sheeting		ASB_033_24	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	05-11-15	221	Eastern wall	Cement sheeting - appears different to southern wall gyprock on top section		ASB_033_25	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-11-15	222	West wall to 221	Cement sheeting		ASB_033_27	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB021	06-11-15	219	Floor	Vinyl sheet on concrete joins are butted not welded		ASB_033_29	Not Detected	Floor	Vinyl sheet	Demolished
Townsville	DB021	06-11-15	017	Cleaners cupboard Floor	Vinyl sheet on concrete - pieces only most has been removed		ASB_033_33	Not Detected	Floor	Vinyl sheet	Demolished
Townsville	DB025	13-04-15	004	Walls	Fibre cement	AT220212.03		Not Detected	Wall	Fibre cement product	
Townsville	DB025	13-04-15	018	Infill over glass entrance	Fibre cement		ASB_004_45	Not Detected	Wall	Fibre cement product	
Townsville	DB025	19-02-15	019	Ceiling		AT220212.07	ASB_000_83	Not Detected	Ceiling	Fibre cement product	
Townsville	DB025	13-04-15	019	Fascia outside room	Fibre cement	AT220212.01	ASB_004_46	Not Detected	Fascia	Fibre cement product	
Townsville	DB025	13-04-15	019	Ceiling outside representative of above ceiling and soffit lining	Fibre cement		ASB_004_47	Not Detected	Ceiling	Fibre cement product	
Townsville	DB025	13-04-15	101	Walls	Fibre cement	AT220212.04		Not Detected	Wall	Fibre cement product	
Townsville	DB025	13-04-15	101A	Outside balcony walls	Expansion joint		ASB_004_44	Not Detected	Sealant	Mastic	
Townsville	DB025	13-04-15	111	Plant room	Infill above door		ASB_004_42	Not Detected	Wall	Fibre cement product	
Townsville	DB025	13-04-15	113A	Fire service cupboard opposite	Dividing wall - fibre cement		ASB_004_41	Not Detected	Wall	Fibre cement product	
Townsville	DB025	13-04-15	117	Floor	Green vinyl sheet - different from main area		ASB_004_43	Not Detected	Floor	Vinyl sheet	
Townsville	DB025	13-04-15	119	Male toilet	Partition wall	AT220212.06		Not Detected	Wall	Fibre cement product	
Townsville	DB025	14-04-15	1st Floor	Air conditioning duct boxing	Sampled by JTA 2012	AT220212.05		Not Detected	Cladding	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB025	13-04-15	226	Service duct area	Jointing compound		ASB_00439	Not Detected	Sealant	Mastic	
Townsville	DB025	13-04-15	226	Service duct area	Insulation/Fire Stopping round pipe		ASB_00440	Not Detected	Insulation		
Townsville	DB025	13-04-15	C201	Floor	Green Vinyl sheet		ASB_00438	Not Detected	Floor	Vinyl sheet	
Townsville	DB025	13-04-15	External	Soffit and Fascia	Representative sample taken outside room 019. [ASB_00447]			Not Detected	Cladding	Fibre cement product	
Townsville	DB025	14-04-15	External	Awning linings	Sampled by JTA 2012	AT220212.02		Not Detected	Cladding	Fibre cement product	
Townsville	DB025	14-04-15	Hole in the wall	Plant room	Infill panels round duct work 9mm fibre cement		ASB_00448	Not Detected	Cladding	Fibre cement product	
Townsville	DB025	14-04-15	Hole in the wall	Plant room	Infill panels fibre cement sheeting		ASB_00449	Not Detected	Cladding	Fibre cement product	
Townsville	DB028 Nth Annex	04-11-15	041E	Telecom service duct walls	North & East		ASB_03306	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	041F	Electrical switchboard ceiling	Cement sheet		ASB_03307	Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	041F	Electrical switchboard wall west side	Cement sheet		ASB_03308	Not Detected	Ceiling	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	129A & 130	Northern wall	Wall built out metal frame cement sheeting in behind gyprock		ASB_03301	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	41A / 41B / 41D	Floor	Carpet on sheet vinyl representative sample of vinyl taken from 41A		ASB_03309	Not Detected	Floor Covering	Vinyl sheet	Demolished
Townsville	DB028 Nth Annex	04-11-15	C107	Service duct western wall	Cement sheeting		ASB_03303	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	External	Northern Soffit sheeting	Able to access Soffit sheeting in ceiling space		ASB_03302	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	External	Upper Fascade sheeting	Cement sheeting		ASB_03305	Not Detected	Fascia	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	External East	Cement sheeting cladding	Middle section of building, plastic joining strip		ASB_03313	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	External North	Window awnings	Cement sheeting	AT190712.26	ASB_03310	Not Detected	Cladding	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	External North	Cement sheeting pieces scattered round	Representative samples taken		ASB_03312	Not Detected	Debris	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	External North / Southside	Cement sheeting cladding	Middle section of building, metal joining strip		ASB_03311	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB028 Nth Annex	04-11-15	X101	Ceiling	Cement sheeting		ASB_03304	Not Detected	Wall	Fibre cement product	Demolished
Townsville	DB035	24-03-15	001 (DB035)	Ceiling	Spray on textured finish		ASB_00407	Not Detected	Ceiling	Vermiculite	Demolished
Townsville	DB035	17-07-17	Entrance Fire door (E004717)	Core Insulation.	Intrusive inspection undertaken of door on 11/7/2017, holes drilled through full depth of door in multiple locations, core is solid timber.			Not Detected	Fire door		Demolished
Townsville	DB036	24-03-15	001 (DB036)	Ceiling	Cement sheet, taken as representative of ceilings throughout DB036.		ASB_00409	Not Detected	Ceiling	Fibre cement product	
Townsville	DB036	24-03-15	001 - (DB036)	Ceiling - man hole	Cement sheet		ASB_00408	Not Detected	Ceiling	Fibre cement product	
Townsville	DB036	24-03-15	001 External (DB036)	Fascia	Cement sheet		ASB_00411	Not Detected	Fascia	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB036	24-03-15	001 External (DB036)	Infill North wall	Cement sheet		ASB_004_12	Not Detected	Cladding	Fibre cement product	
Townsville	DB036	24-03-15	001A (DB036)	Floor	Vinyl on concrete		ASB_004_10	Not Detected	Floor	Vinyl sheet	
Townsville	DB067	11-02-15	017	Walls	Considered representative of other fibre cement internal walls in DB067.	AT130712.12		Not Detected	Wall	Fibre cement product	
Townsville	DB067	12-02-15	External	Ceilings in walkways			ASB_002_97	Not Detected	Eaves	Fibre cement product	
Townsville	DB067	12-02-15	External	Eaves		AT130712.10		Not Detected	Eaves	Fibre cement product	
Townsville	DB067	12-02-15	External	walls	Hardiplank Boards	AT130712.11		Not Detected	Wall	Fibre cement product	
Townsville	DB067	12-02-15	External	walls	Infill panels to walls where old air conditioning units were removed	AT130712.13		Not Detected	Cladding	Fibre cement product	
Townsville	DB067	12-02-15	Roof space	Accessed roof space from rooms 0011,003D,020	Observed SMF insulation over ceiling space, foil insulation to underside of roof, hardwood trusses, did not observe any suspect material.			Not Detected			
Townsville	DB067	12-02-15	Room 001	Floor	Vinyl sheet covered up walls same as room 003 except it is laid over vinyl - sample taken from bottom layer		ASB_002_96	Not Detected	Floor	Vinyl sheet	
Townsville	DB067	11-02-15	Room 003	Floor	Vinyl sheet covered up walls laid on Masonite on top of timber		ASB_002_93	Not Detected	Floor	Vinyl sheet	
Townsville	DB067	11-02-15	Room 014	Floor	Vinyl sheet covered up walls		ASB_002_92	Not Detected	Floor	Vinyl sheet	
Townsville	DB067	11-02-15	Room 026	Infill where old conditioner was located	Fibre cement		ASB_002_90	Not Detected	Wall	Fibre cement product	
Townsville	DB067	12-02-15	Subfloor Space	Accessed from sides of building	Steel beams and joists attached to steel posts - floor raised approx. 1m to 1.5 metres off ground. Observed plywood flooring sitting on joists. Did not observe any suspect material.			Not Detected			
Townsville	DB068	12-02-15	Room 002	Floor	Sheet vinyl under carpet. Sample representative of material in room 1 also.		ASB_002_98	Not Detected	Floor	Vinyl sheet	
Townsville	DB082	13-04-15	001	Cladding	West end, to washing up area		ASB_105_6	Not Detected	Cladding	Fibre cement product	
Townsville	DB082	13-04-15	002	Walls	All walls, double skinned on South wall as it fronts onto main area. Sampled from North wall		ASB_010_54	Not Detected	Wall	Fibre cement product	
Townsville	DB082	13-04-15	002	Ceiling			ASB_105_5	Not Detected	Ceiling	Fibre cement product	
Townsville	DB082	13-04-15	003	Ceiling	Representative sample taken in room 004 [ASB_1057]			Not Detected	Ceiling	Fibre cement product	
Townsville	DB082	13-04-15	003	Walls	East and west ends. Representative sample taken in room 004 [ASB_1058]			Not Detected	Wall	Fibre cement product	
Townsville	DB082	13-04-15	004	Ceiling			ASB_105_7	Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB082	13-04-15	004	Walls			ASB_1058	Not Detected	Wall	Fibre cement product	
Townsville	DB083	13-04-15	003	North walls, upper level. Cladding to 002 and 003A			ASB_01048	Not Detected	Wall	Fibre cement product	
Townsville	DB083	13-04-15	003a	Upper infill above walls to North and west			ASB_01049	Not Detected	Infill	Fibre cement product	
Townsville	DB083	13-04-15	101	East wall			ASB_01050	Not Detected	Wall	Fibre cement product	
Townsville	DB084	27-03-15	101	Wall	Cement sheet - representative sample 102 [ASB_00433]			Not Detected	Wall	Fibre cement product	
Townsville	DB084	27-03-15	101	Floor	Cream vinyl tiles 12" x 12"		ASB_00432	Not Detected	Floor	Vinyl tile	
Townsville	DB084	27-03-15	101	Ceiling	Cement sheet - representative sample 103 [ASB_00436]			Not Detected	Ceiling	Fibre cement product	
Townsville	DB084	27-03-15	102	Floor	Cream vinyl tiles 12" by 12". Representative samples taken in corridor [JT050213.22] and room 101 [ASB_00432].			Not Detected	Floor	Vinyl tile	
Townsville	DB084	27-03-15	102	Walls	Cement sheet		ASB_00433	Not Detected	Wall	Fibre cement product	
Townsville	DB084	27-03-15	102	Ceiling	Cement sheet - representative sample 103 [ASB_00436]			Not Detected			
Townsville	DB084	27-03-15	103	Floor	Cream vinyl tiles 12" by 12". Representative samples taken in corridor [JT050213.22] and room 101 [ASB_00432].			Not Detected	Floor	Vinyl tile	
Townsville	DB084	27-03-15	103	Walls	Cement sheet - representative sample 102 [ASB_00433]			Not Detected	Wall	Fibre cement product	
Townsville	DB084	27-03-15	103	Ceiling	Cement sheet		ASB_00436	Not Detected	Ceiling	Fibre cement product	
Townsville	DB084	27-03-15	104	Floor	Cream vinyl tiles 12" by 12". Representative samples taken in corridor [JT050213.22] and room 101 [ASB_00432].			Not Detected	Floor	Vinyl tile	
Townsville	DB084	27-03-15	104	Walls	Cement sheet	JT050213.25		Not Detected	Wall	Fibre cement product	
Townsville	DB084	27-03-15	Upper corridor	Floor	Cream vinyl tiles 12" x 12"	JT050213.22		Not Detected	Floor	Vinyl tile	
Townsville	DB085	25-03-15	003	North wall infill above block wall - representative sample taken 004 [ASB_00421]	Cement sheet			Not Detected	Wall	Fibre cement product	
Townsville	DB085	25-03-15	003	Ceiling	Cement sheet tiles	JT050213.09		Not Detected			
Townsville	DB085	25-03-15	004	Ceiling	Cement sheet tiles			Not Detected			
Townsville	DB085	25-03-15	004	North wall infill above block wall	Cement sheet		ASB_00421	Not Detected	Wall	Fibre cement product	
Townsville	DB085	25-03-15	005A	Walls East and South	Cement sheet	JT050213.11		Not Detected			
Townsville	DB085	25-03-15	005A	Ceiling	Cement sheet tiles			Not Detected			
Townsville	DB085	25-03-15	005B	Ceiling	Cement sheet tiles			Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB085	25-03-15	005B	Walls	Cement sheet			Not Detected			
Townsville	DB085	25-03-15	005C	Ceiling	Cement sheet tiles			Not Detected			
Townsville	DB085	25-03-15	005C	Walls	Cement sheet			Not Detected			
Townsville	DB085	25-03-15	006	Ceiling	Cement sheet tiles			Not Detected			
Townsville	DB085	25-03-15	007	Wall near entrance door west side	Cement sheet		ASB_004 19	Not Detected	Wall	Fibre cement product	
Townsville	DB085	25-03-15	007	West wall - Infill round air con unit	Cement sheet		ASB_004 20	Not Detected	Cladding	Fibre cement product	
Townsville	DB085	25-03-15	007A	Floor	Sheet vinyl	JT050213.12		Not Detected			
Townsville	DB085	25-03-15	007A	Walls	Cement sheet	JT050213.13		Not Detected			
Townsville	DB085	25-03-15	008	Entrance door - internal wall	Fibre Cement product		ASB_004 27	Not Detected	Wall	Fibre cement product	
Townsville	DB085	25-03-15	008	Entrance door - external wall	Fibre Cement product		ASB_004 28	Not Detected	Wall	Fibre cement product	
Townsville	DB085	26-03-15	008A	Ceiling	Cement sheet tiles - original			Not Detected			
Townsville	DB085	26-03-15	008A	New wall	Fibre Cement product			Not Detected			
Townsville	DB085	26-03-15	008A	Existing wall on west and south west original	Fibre Cement product representative sample taken 005A			Not Detected			
Townsville	DB085	26-03-15	009	Doorway to 010 informed by persons on site that material is new. Visually consistent with modern cellulose fibre cement.	Fibre Cement product			Not Detected			
Townsville	DB085	26-03-15	010	Ceiling	Fibre Cement product		ASB_004 29	Not Detected	Ceiling	Fibre cement product	
Townsville	DB085	26-03-15	010	Doorway to 008A informed by persons on site that material is new. Visually consistent with modern cellulose fibre cement.	Fibre Cement product			Not Detected			
Townsville	DB085	26-03-15	External	Infill between wall and roof - to keep possums out informed by on site person installed round 15years ago	Fibre Cement product			Not Detected			
Townsville	DB085	25-03-15	External west	Replacement sheet soffit	Cement sheet		ASB_004 23	Not Detected	Fascia	Fibre cement product	
Townsville	DB085	25-03-15	External west and south	Fascia and soffit material	Cement sheet		ASB_004 22	Not Detected	Eaves	Fibre cement product	
Townsville	DB086	25-03-15	001,002,004,005,006,007,008	Floor	Sheet vinyl through out. Green/grey epoxy (or similar) floor coating underneath in some areas, included in sample.		ASB_004 15	Not Detected	Floor	Vinyl sheet	
Townsville	DB086	25-03-15	003A	Ceiling	Suspended ceiling - Cement sheet			Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB086	25-03-15	003B	Joint round ducting	Jointing compound		ASB_00414	Not Detected	Sealant	Mastic	
Townsville	DB086	25-03-15	003B	Ceiling	Suspended ceiling - Cement sheet			Not Detected			
Townsville	DB086	25-03-15	003C	Ceiling	Suspended ceiling - Cement sheet			Not Detected			
Townsville	DB086	25-03-15	005	Wall west side - Infill panels over windows	Cement sheet		ASB_00413	Not Detected	Cladding	Fibre cement product	
Townsville	DB086	25-03-15	C003	Ceiling	Suspended ceiling - Cement sheet	AT130712.17		Not Detected			
Townsville	DB086	25-03-15	External - southern side	Soffit	Cement sheet	AT130712.15		Not Detected			
Townsville	DB087	30-03-15	0 ground floor C001	Floor	Previously documented mustard vinyl floor tiles removed and replaced with blue vinyl sheet with no backing. Inspected beneath sheeting in several locations.			Not Detected	Floor		
Townsville	DB087	04-04-15	006	Ceiling	Textured coating exposed		ASB_01034	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	15-04-15	011	Heater bank in supply vent	Internal lining to heater bank. Material not visually consistent with ACM heater bank lining.		ASB_00144	Not Detected	Insulation		
Townsville	DB087	04-04-15	013	Ceiling	Textured coating exposed		ASB_01035	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	04-04-15	023	Ceiling	Textured coating exposed		ASB_01036	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	13-04-15	031 (Switchboard room, external South)	Infill around doorframe			ASB_01039	Not Detected	Infill	Fibre cement product	
Townsville	DB087	30-03-15	100C	Floor	Previously documented mustard vinyl floor tiles removed and replaced with blue vinyl sheet with no backing. Inspected beneath sheeting in several locations.			Not Detected	Floor		
Townsville	DB087	04-04-15	101	Ceiling			ASB_01033	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	04-04-15	109	Ceiling	Textured coating exposed		ASB_01032	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	30-03-15	113B	Wall	Rear wall appears to be new sheet. Sampled and made sure not sheeted over old material, which it is not. Ceiling removed and replaced with plasterboard and also not sheeted onto old material.		ASB_01027	Not Detected	Wall	Fibre cement product	
Townsville	DB087	30-03-15	118	Wall	West wall, dividing 118 and 118B		ASB_01026	Not Detected	Wall	Fibre cement product	
Townsville	DB087	27-03-15	118	Floor	Previously reported mustard vinyl tiles removed. Replaced with new vinyl floor. No backing layer.			Not Detected			
Townsville	DB087	30-03-15	118A	Walls	Double layer, so sheeting present to 2 sides, inside 118 and 118B		ASB_01025	Not Detected	Wall	Fibre cement product	
Townsville	DB087	13-04-15	118B	Ceiling	Textured coating exposed		ASB_01038	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	30-03-15	118B	Wall	East wall, dividing 118 and 118B. Same as ASB_01026			Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DB087	27-03-15	118B, 118A, 118, 115(PC2), 111,110(PC2), 109, 108A, 107, 106, 105, 104, 103, 102, 023, 022A(PC2), 022 (PC2), 021A(PC2), 021(PC2), 019 & 012	Ceilings	Samples taken in various other similar rooms are taken as representative of sprayed textured coatings applied to ceilings in the rooms listed here.			Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	30-03-15	119A	Walls	North and East walls. Internal and external		ASB_010 28	Not Detected	Wall	Fibre cement product	
Townsville	DB087	04-04-15	124	Ceiling	Access to outside perimeter of PC3 lab, which has textured coating to ceiling		ASB_010 44	Not Detected	Ceiling	Fibre cement product	
Townsville	DB087	04-04-15	1st Floor, S101 (stairwell landing)	Sprayed coating to underside of stairs			ASB_010 37	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	27-03-15	200C	Floor	Previously documented mustard vinyl floor tiles removed and replaced with blue vinyl sheet with no backing. Inspected beneath sheeting in several locations.			Not Detected	Floor		
Townsville	DB087	04-04-15	201	Roof space	Sprayed coating to concrete beam. Look for yellow tab stuck to ceiling framework where tile removed. Different material to that applied to the clip lock. Appears to be a "classic" vermiculite application. More friable than material applied to clip lock. Material has fallen away from the beams and rests on top of the plaster board ceiling tiles.		ASB_010 30	Not Detected	Roof insulation	Vermiculite	
Townsville	DB087	27-03-15	205	Ceiling space	Sprayed coating		ASB_010 23	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DB087	04-04-15	206	Roof space	Sprayed coating to clip lock roof. Look for yellow tab stuck to ceiling framework where tile removed.		ASB_010 29	Not Detected	Roof insulation	Textured Coating	
Townsville	DB087	04-04-15	220	Roof space	Sprayed coating to clip lock roof. Look for yellow tab stuck to ceiling framework where tile removed.		ASB_010 31	Not Detected	Roof insulation	Textured Coating	
Townsville	DB087	15-04-15	229	Fire door E004640, to roof stairs, core of door sampled from behind handle	Not visually consistent with typical ACM door		ASB_001 45	Not Detected	Fire door	Low Density Fibre Board	
Townsville	DB087	13-04-15	External	Lining to Air compressor E006948 housing	South and west walls plus roof		ASB_010 41	Not Detected	Cladding	Fibre cement product	
Townsville	DB087	13-04-15	External	Expansion joint	Sealant between blockwork and paving, North side, adjacent to drain where ASB_01042 sampled.		ASB_010 43	Not Detected	Sealant	Mastic	
Townsville	DC054	23-03-15	003	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	004	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DC054	23-03-15	006	Ceiling	Western aspect. Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	006	Wall	West and north west wall			Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	008	Wall	West wall			Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	008	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	009	Walls	West wall			Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	009A	Walls	East wall			Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	011	Walls	East and South walls. Previously sampled in room 001	See AT160712.02		Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	011	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	012	Walls	North and East walls. Previously sampled in room 001	See AT160712.02		Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	012	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	013	Walls	All walls. Previously sampled in room 001	See AT160712.02		Not Detected	Wall	Fibre cement product	
Townsville	DC054	23-03-15	013	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	014	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	019	Ceiling	Same as ASB_01008			Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	020	Ceiling	Not previously sampled		ASB_01008	Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	021	Ceiling	Same as ASB_01008			Not Detected	Ceiling	Fibre cement product	
Townsville	DC054	23-03-15	External	Eave soffit to South East walkway	Not previously sampled		ASB_01007	Not Detected	Eaves	Fibre cement product	
Townsville	DC054	23-03-15	External	Eave soffit to South West walkway.	Same as ASB_01007			Not Detected	Eaves	Fibre cement product	
Townsville	DC055	25-03-15	016	Floor		AT160712.05		Not Detected	Floor	Fibre cement product	
Townsville	DC055	25-03-15	017	Floor	Cream vinyl tiles beneath carpet	AT160712.08		Not Detected	Floor	Vinyl tile	
Townsville	DC055	25-03-15	017	Ceiling			ASB_01010	Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	25-03-15	017	Wall	North, East and South walls. Same material as ASB_01010			Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DC055	25-03-15	020	Infill panel above and below window	South side only. Single layer so also an external feature. Sample [ASB_01014] taken as representative of this material.			Not Detected	Cladding	Fibre cement product	
Townsville	DC055	25-03-15	024 (male toilet)	Ceiling	2 sheets, southern aspect		ASB_01012	Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	25-03-15	024 (male toilet)	Wall	Dividing wall and partition to toilet		ASB_01013	Not Detected	Wall	Fibre cement product	
Townsville	DC055	25-03-15	025 (shower)	Wall	North and west. Same as ASB_01013			Not Detected	Wall	Fibre cement product	
Townsville	DC055	25-03-15	026 (female toilet)	Ceiling	2 sheets, Northern aspect. Same as ASB_01012			Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	25-03-15	027/028 (one room with 2 entries, with 2 numbers)	Infill panel above window	Single layer so also an external feature. Sample [ASB_01014] taken as representative of this material.			Not Detected	Cladding	Fibre cement product	
Townsville	DC055	25-03-15	029	Infill panel above and below window	South side only. Single layer so also an external feature. Sample [ASB_01014] taken as representative of this material.			Not Detected	Cladding	Fibre cement product	
Townsville	DC055	26-03-15	030	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	030	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	030	Infill above windows		See AT160712.09		Not Detected	Cladding	Fibre cement product	
Townsville	DC055	26-03-15	031	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	031	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	031A	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	031A	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	032	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	032	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	033	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	033	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DC055	26-03-15	033	Infill above windows		See AT160712.09		Not Detected	Cladding	Fibre cement product	
Townsville	DC055	26-03-15	034	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	034	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	034	Infill above windows		See AT160712.09		Not Detected	Cladding	Fibre cement product	
Townsville	DC055	26-03-15	034A	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	034A	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	034A	Infill above windows		See AT160712.09		Not Detected	Cladding	Fibre cement product	
Townsville	DC055	26-03-15	035	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product	
Townsville	DC055	26-03-15	035	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	26-03-15	035	Infill above windows		See AT160712.09		Not Detected	Cladding	Fibre cement product	
Townsville	DC055	26-03-15	External	Floor	Entrance to 029	See AT160712.05		Not Detected	Floor	Fibre cement product	
Townsville	DC055	26-03-15	External	Ceiling lining to alcove	South west entrance		ASB_01014	Not Detected	Ceiling	Fibre cement product	
Townsville	DC055	25-03-15	External, Northwest aspect	Ceiling of verandah outside room 018			ASB_01011	Not Detected	Ceiling	Fibre cement product	
Townsville	DC056	26-03-15	002 (Mechanics Office)	Infill panel	Above North door, both internal and external		ASB_01017	Not Detected	Infill	Fibre cement product	
Townsville	DC057	26-03-15	007	Walls		0285/07 DC057-06		Not Detected	Wall	Fibre cement product	
Townsville	DC057	26-03-15	007A	Walls		0285/07 DC057-06		Not Detected	Wall	Fibre cement product	
Townsville	DC057	26-03-15	011	Floor	Same as "oatmeal" in 013	See AT270712.11		Not Detected	Floor	Vinyl tile	
Townsville	DC057	26-03-15	011	Walls	A mixture of fibre cement sheet and particle board. Sample taken from North wall		ASB_01018	Not Detected	Wall	Fibre cement product	
Townsville	DC057	26-03-15	012 (toilets)	Walls		0285/07 DC057-06		Not Detected	Wall	Fibre cement product	
Townsville	DC057	26-03-15	013	Infill panel	Above South door	See AT270712.08		Not Detected	Cladding	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DC057	26-03-15	External	Infill above door to 007		AT270712.08		Not Detected	Cladding	Fibre cement product	
Townsville	DC058	23-03-15	001	Infill to top of west wall		See 0285/07 DC058-05		Not Detected	Cladding	Fibre cement product	
Townsville	DC058	23-03-15	002	Infill above louvres, South west and south east aspect		AT130712.20		Not Detected	Cladding	Fibre cement product	
Townsville	DC058	23-03-15	002A	Ceiling	Lower ceiling, west side		ASB_010 01	Not Detected	Ceiling	Fibre cement product	
Townsville	DC058	23-03-15	002A	Wall	North west aspect. Same as ASB_01002			Not Detected	Wall	Fibre cement product	
Townsville	DC058	23-03-15	002B	Wall			ASB_010 02	Not Detected	Wall	Fibre cement product	
Townsville	DC058	24-03-15	003	Wall	Cladding to South wall		ASB_010 03	Not Detected	Wall	Fibre cement product	
Townsville	DC058	24-03-15	003	Infill to top of west and east walls	Sampled from North East corner, via roof top storage. Some damage in North East corner		ASB_010 04	Not Detected	Cladding	Fibre cement product	
Townsville	DC058	24-03-15	003A	Ceiling			ASB_010 05	Not Detected	Ceiling	Fibre cement product	
Townsville	DC058	24-03-15	003B	Infill panel to doorway common to 003	Same material as ASB_01004			Not Detected	Cladding	Fibre cement product	
Townsville	DC058	24-03-15	003B	Infill around doorframe. Common to building 059	Same material as ASB_01004			Not Detected	Cladding	Fibre cement product	
Townsville	DC058	24-03-15	003B	Ceiling	Same as ASB_01005			Not Detected	Ceiling	Fibre cement product	
Townsville	DC058	23-03-15	External	Eaves. Northern half of East aspect		0285/07 DC058-04		Not Detected	Eaves	Fibre cement product	
Townsville	DC059	26-03-15	002	Ceiling		AT160712.16		Not Detected	Ceiling	Fibre cement product	
Townsville	DC059	26-03-15	002	Walls		See AT160712.15		Not Detected	Wall	Fibre cement product	
Townsville	DC059	26-03-15	003 (store dispensary)	Walls	Cladding to wall common with room 010 and 004. Same as ASB_01005 from building 058			Not Detected	Wall	Fibre cement product	
Townsville	DC059	26-03-15	004 (tea room)	Walls		See AT160712.15		Not Detected	Wall	Fibre cement product	
Townsville	DC059	26-03-15	005	Ceiling		AT160712.16		Not Detected	Ceiling	Fibre cement product	
Townsville	DC059	26-03-15	005	Walls		See AT160712.15		Not Detected	Wall	Fibre cement product	
Townsville	DC059	26-03-15	007 (mail sorting)	Walls		See AT160712.15		Not Detected	Wall	Fibre cement product	
Townsville	DC059	26-03-15	008	Ceiling		AT160712.16		Not Detected	Ceiling	Fibre cement product	
Townsville	DC059	26-03-15	008	Walls		See AT160712.15		Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DC059	26-03-15	009 (mail room)	Walls		See AT160712.15		Not Detected	Wall	Fibre cement product	
Townsville	DC059	26-03-15	010 (storeroom)	Infill above doorway to building 058	Same as ASB_01005 from building 058			Not Detected	Wall	Fibre cement product	
Townsville	DC060	26-03-15	001	Floor		AT030812.03		Not Detected	Floor	Vinyl tile	
Townsville	DC060	26-03-15	002	Wall	South wall	AT030812.02		Not Detected	Wall	Fibre cement product	
Townsville	DC060	26-03-15	003	Walls		AT030812.02		Not Detected	Wall	Fibre cement product	
Townsville	DC060	26-03-15	004	Walls		AT030812.02		Not Detected	Wall	Fibre cement product	
Townsville	DC060	26-03-15	005	Floor		See AT030812.03		Not Detected	Floor	Vinyl tile	
Townsville	DC060	26-03-15	External	Infill	3 panels on the North wall		ASB_01019	Not Detected	Infill	Fibre cement product	
Townsville	DC060	26-03-15	External	Eaves		AT030812.01		Not Detected	Eaves	Fibre cement product	
Townsville	DC066	30-03-15	External	Wall	South wall between the 2 rooms	AT030812.10		Not Detected	Wall	Fibre cement product	
Townsville	DC066	30-03-15	Poison room	Walls		AT030812.13		Not Detected	Wall	Fibre cement product	
Townsville	DD014	12-02-15	001A	Ceiling	Sprayed coating. Sampled in 001B [ASB_00060]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	12-02-15	001B	Ceiling	Sprayed coating		ASB_00060	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	12-02-15	002	Ceiling	Sprayed coating, sampled in 007 [AT210712.04] and 008 [ASB_00063].			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	12-02-15	002	Air conditioning bulkhead	Cladding		ASB_00061	Not Detected	Cladding	Fibre cement product	
Townsville	DD014	12-02-15	006	Ceiling	Sprayed coating, sampled in 007 [AT210712.04] and 008 [ASB_00063].			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	12-02-15	007	Ceiling	Sprayed coating. Previously sampled.	AT210712.04		Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	12-02-15	007	Infill above windows on South aspect	Timber/particle board. Also used throughout the laboratory.			Not Detected	Cladding		
Townsville	DD014	12-02-15	008	Ceiling	Sprayed coating		ASB_00063	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	101	Ceiling	Sprayed coating		ASB_00058	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	101A	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	101B	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	102	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	104	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	122 & 122B	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DD014	11-02-15	122A	Ceiling	Sprayed coating		ASB_00059	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	122B	Walls	Present to North wall and East wall. Used to partition off from main room 122. An internal sheet and an external sheet		ASB_00057	Not Detected	Wall	Fibre cement product	
Townsville	DD014	11-02-15	122C	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	123	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	123B	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	11-02-15	124	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	201	Sprayed coating to roof above plasterboard suspended ceiling	Different material to that sampled in S201. Some has fallen away and resting on top of ceiling panels		ASB_00053	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	202	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	203	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	204	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	205	Ceiling space	Sprayed coating above ceiling panels			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	206	Ceiling space	Sprayed coating above ceiling panels			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	207	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	208	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	209	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	210	Sprayed "limpet" coating to underside of roof, above plasterboard suspended ceiling	Also applied to beams. Beams are approximately 5m apart.		ASB_00056	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	211	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DD014	10-02-15	2nd Floor S201	Ceiling/stairwell	Sprayed coating		ASB_00049	Not Detected	Sprayed Coating	Vermiculite	
Townsville	DD014	10-02-15	3rd Floor, External Rooftop	Fibre cement sheet used as roofing/floor			ASB_00046	Not Detected	Roof	Fibre cement product	
Townsville	DD014	10-02-15	3rd Floor, External Rooftop	Broken fibre cement sheet sitting on bricks on bench, plus debris from the sheet			ASB_00048	Not Detected	Debris	Fibre cement product	
Townsville	DD014	13-02-15	External, Ground Level	Expansion joint	Sampled outside 006		ASB_00064	Not Detected	Sealant	Mastic	
Townsville	DD014	25-03-15	HVAC System	HVAC system was inspected for ACM Heater Banks and Fire Dampers on 25/03/2015 with Paul McDonald (Donair).	No heater banks or ACM fire dampers found. Review of old mechanical plans and visual inspection of system.			Not Detected			
Townsville	DD015	13-02-15	001	Walls	Same material as ASB_00304			Not Detected	Wall	Fibre cement product	
Townsville	DD015	13-02-15	001	Cladding to entrance	Same material as ASB_00304			Not Detected	Wall	Fibre cement product	
Townsville	DD015	13-02-15	002	Walls	Ceramic tiles and asbestos cement partitions removed. Appears to be refurbished. Sample taken from western wall.		ASB_00304	Not Detected	Wall	Fibre cement product	
Townsville	DD015	13-02-15	002	Infill panel above door	Same material as ASB_00304			Not Detected	Wall	Fibre cement product	
Townsville	DD015	13-02-15	002A	Walls	Same material as ASB_00304			Not Detected	Wall	Fibre cement product	
Townsville	DD015	25-03-15	005	Floor, gap sealant at perimeter	Black bituminous material		ASB_00134	Not Detected	Sealant	Bituminous product	
Townsville	DD015	20-02-15	011	South wall	Single skin wall so also has an external presence		ASB_00087	Not Detected	Wall	Fibre cement product	
Townsville	DD015	19-02-15	012	Floor	Green-grey vinyl tile.		ASB_00080	Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	20-02-15	012	South wall	Small infill panel above grille. South west corner		ASB_00088	Not Detected	Cladding	Fibre cement product	
Townsville	DD015	20-02-15	015	Walls	Same as that previously sampled in 016	See AT210712.25		Not Detected	Wall	Fibre cement product	
Townsville	DD015	20-02-15	015A	Walls	North and South walls. Same as that previously sampled in 016	See AT210712.25		Not Detected	Wall	Fibre cement product	
Townsville	DD015	19-02-15	016	South wall	Previously sampled	AT210712.25		Not Detected	Service Pit	Fibre cement product	
Townsville	DD015	15-04-15	016	Location of previous heater bank (small) as shown on MECH-T1134-101-REV-0	Section of duct still insitu, inspected internally and found to be clean.			Not Detected	Heater Bank		
Townsville	DD015	15-04-15	019, Southern End	Location of previous heater bank (small) as shown on MECH-T1134-101-REV-0	Entire section of duct previously containing heater bank has been replaced.			Not Detected	Heater Bank		
Townsville	DD015	24-02-15	019B	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	022A	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	022B	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DD015	26-02-15	023	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	15-04-15	023	Ceiling space, Redundant Heater Bank in SE corner.	Original duct still in situ, inspected internally, no heater bank or debris found (clean). Another HB appears to have been removed from this ceiling space, section of duct completely gone.			Not Detected	Heater Bank		
Townsville	DD015	26-02-15	024	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	025	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	15-04-15	025 plant room above	Three supply ducts appear to have previous Heater Banks sections of duct replaced with new.	Location of previous heater bank in SW corner inspected internally, found to be clean. Section of duct replaced.			Not Detected	Heater Bank		
Townsville	DD015	24-02-15	031	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	24-02-15	031	Walls above windows	Confirmed they are the same as in 032, with no asbestos detected in previous sample from 032	See AT210712.29		Not Detected	Wall	Fibre cement product	
Townsville	DD015	24-02-15	032	Walls		See AT210712.29		Not Detected	Wall	Fibre cement product	
Townsville	DD015	24-02-15	032	Floor	Same as ASB_00091. Also has oatmeal coloured tiles that were previously sampled with no asbestos detected.	AT210712.30		Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	032 Stairway to 157	Walls	First 2 sheets to west wall at top of stair are Masonite. Others are fibre cement		ASB_00092	Not Detected	Wall	Fibre cement product	
Townsville	DD015	15-04-15	032, Ceiling Space	Location of previous heater bank as shown on MECH-T1134-101-REV-0	Entire section of duct previously containing heater bank has been replaced. Inspected from ladder at side of 027.			Not Detected	Heater Bank		
Townsville	DD015	24-02-15	032A	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	24-02-15	032A	Infill above windows		See AT210712.29		Not Detected	Wall	Fibre cement product	
Townsville	DD015	24-02-15	032B	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	24-02-15	032C	Walls		See AT210712.29		Not Detected	Wall	Fibre cement product	
Townsville	DD015	13-02-15	111	Floor	Vinyl on concrete		ASB_00301	Not Detected	Floor	Vinyl sheet	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DD015	25-03-15	111 Staff Room	Heater Bank (2 of) shown on old plan MECH 271-A1-A	Original supply duct completely removed from this room, replaced with VAV system with flexi duct.			Not Detected	Heater Bank		
Townsville	DD015	13-02-15	116	Ceiling	Confirmed to be timber ceiling. Previous register by JTA had two conflicting entries, one entry indicated asbestos cement.			Not Detected	Ceiling		
Townsville	DD015	19-02-15	130 (corridor)	Floor	Green vinyl tiles		ASB_00077	Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	19-02-15	130A	Floor	Same as ASB_00077			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	19-02-15	130B	Floor	Same as ASB_00077			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	15-04-15	130C, Ceiling Space	Location of two (2) previous heater banks. As shown on MECH-T1134-103-REV-0	One HB completely replaced with new duct. Other inspected internally, found to be clean.			Not Detected	Heater Bank		
Townsville	DD015	19-02-15	130D	Floor	Grey vinyl sheet, not tiles		ASB_00076	Not Detected	Floor Covering	Vinyl sheet	
Townsville	DD015	19-02-15	132	Infill panel. East wall, North of door	Externally, there are infill panels above the metal louvres that are not visible from the outside. Runs along the length of the East and west aspect of the wing.		ASB_00078	Not Detected	Cladding	Fibre cement product	
Townsville	DD015	19-02-15	133	Infill panel, East wall.	Same as ASB_00078			Not Detected	Cladding	Fibre cement product	
Townsville	DD015	19-02-15	133	Infill panel to the north door			ASB_00079	Not Detected	Cladding	Fibre cement product	
Townsville	DD015	15-04-15	133	Location of four (4) previous heater banks. As shown on MECH-T1134-103-REV-0	Branches of duct that previously contained heater banks have been completely removed and replaced, e.g. with flexi duct.			Not Detected	Heater Bank		
Townsville	DD015	23-02-15	134	Floor	Grey vinyl floor tiles beneath carpet. Adhesive not suspected to be ACM.		ASB_00091	Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	136	Floor	Brown vinyl floor tiles. Adhesive not suspected to be ACM.		ASB_00089	Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	140	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	140A	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	141	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	143	Floor	Carpet tiles laid over vinyl tiles the same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	26-02-15	144	Floor	Same as ASB_00091			Not Detected	Floor	Vinyl tile	
Townsville	DD015	26-02-15	145	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	148	Floor	Grey vinyl tiles same as those in 134 [ASB_00091]			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	149	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DD015	15-04-15	149, Ceiling Space	Location of two (2) previous heater banks. As shown on MECH-T1134-103-REV-0	Both HB's completely replaced with new sections of duct.			Not Detected	Heater Bank		
Townsville	DD015	23-02-15	150	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	151	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	152	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	153	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	154	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	155	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	156	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	157	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	1st Floor, C106	Floor	Grey vinyl tiles same as those in 134 [ASB_00091]			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	23-02-15	1st floor, C107	Floor	Grey vinyl tiles same as those in 134 [ASB_00091]			Not Detected	Floor Covering	Vinyl tile	
Townsville	DD015	17-02-15	1st floor, External, walkway from room 130C to C104, East side	Floor	Fibre cement sheets used as floor to walkway		ASB_00074	Not Detected	Floor	Fibre cement product	
Townsville	DD015	17-02-15	External, mechanical engineering containing rooms 123 to 129	East wall near entrance to C104, expansion joint.			ASB_00075	Not Detected	Sealant	Mastic	
Townsville	DD015	17-02-15	External, mechanical engineering containing rooms 123 to 129	Sun shades	Same material as ASB_00074			Not Detected	Window Shade Panel	Fibre cement product	
Townsville	DD015	17-02-15	External, South Wing (Stage 2)	Eaves	3 slot profile. Applied to north		ASB_00073	Not Detected	Eaves	Fibre cement product	
Townsville	DD016	13-03-15	026	floor		0285/07 DD016-02		Not Detected	Floor	Vinyl tile	
Townsville	DF012	22-01-15	001 Dining room (Refectory)	Southeast wall	Pink fibre cement wall referred to by JTA is in southeast corner only. Previous experience with "pink sheet" has given positive results, so resampled.	AT310712.04	ASB_00003	Not Detected	Wall	Fibre cement product	
Townsville	DF012	22-01-15	001 Dining room (Refectory)	Roof space	Inspected and old wall partitioning observed. No suspected asbestos containing material observed.			Not Detected			
Townsville	DF012	27-01-15	002	Ceiling		AT310712.02		Not Detected	Wall	Fibre cement product	
Townsville	DF012	27-01-15	003	Ceiling		See AT310712.02		Not Detected	Wall	Fibre cement product	
Townsville	DF012	27-01-15	006A	East wall	Common with electrical services cupboard, stamped with "Versilux"		ASB_00016	Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DF012	22-01-15	014	Walls	Not previously documented.		ASB_00009	Not Detected	Wall	Fibre cement product	
Townsville	DF012	22-01-15	019	Ceiling	Centre of room with water damage. Protruding Textured coating to tile.		ASB_00010	Not Detected	Ceiling	Low Density Fibre Board	
Townsville	DF012	22-01-15	019	Ceiling	Flat matte finish tile sampled above ductwork west end of bar		ASB_00011	Not Detected	Ceiling	Fibre cement product	
Townsville	DF012	22-01-15	019	Ceiling	Inverted Textured coating to tile, sampled above ductwork west end of bar		ASB_00012	Not Detected	Ceiling	Low Density Fibre Board	
Townsville	DF012	22-01-15	C003	Floor covering	Beige vinyl tile. No asbestos detected. PLM & XRD analysis.	AT310712.06		Not Detected	Floor	Vinyl tile	
Townsville	DF012	22-01-15	C003	Ceiling	Visually consistent with ceiling in room 002.	See AT310712.02		Not Detected	Wall	Fibre cement product	
Townsville	DF012	22-01-15	EXTERNAL - Bludgers Bar	Walls	No suspected asbestos containing materials observed internally.	AT310712.09		Not Detected	Wall	Fibre cement product	
Townsville	DF012	22-01-15	EXTERNAL - Men's, Ladies & Disabled Toilets, Rear of Members Lounge	Eaves	Sample taken because the eaves have 3 slot profile, whereas the eaves around main building are 1 slot profile.		ASB_00007	Not Detected	Eaves	Fibre cement product	
Townsville	DF012	22-01-15	EXTERNAL - Toilets at Rear of Members Lounge	Cladding to covered walkway	Appears to be an addition to the main building and fibre cement sheet does not appear the same as the eaves. Different fixtures used. Some sheeting inaccessible for inspection because of height, but has same appearance and fixtures as that sampled. Sample taken at low end where it appears a sample may have been taken previously.		ASB_00008	Not Detected	Cladding	Fibre cement product	
Townsville	DF012	22-01-15	Female Toilets to Bar Area of Club	Ceiling	Sampled in male toilets [ASB_00006]. Same material used in female toilets			Not Detected	Ceiling	Fibre cement product	
Townsville	DF012	22-01-15	Male Toilets to Bar Area of Club	Ceiling	Inspected ceiling space in male toilets and fibreglass insulation on top of ceiling.		ASB_00006	Not Detected	Ceiling	Fibre cement product	
Townsville	DF013	27-01-15	Entrance way / Corridor	Walls	Sampled by JTA in 2012.	AT020312.21		Not Detected	Wall	Fibre cement product	
Townsville	DF013	27-01-15	Storage	Walls	Sample taken as representative of internal walls throughout DF013, with the exception of the toilet, which has plasterboard walls.		ASB_00018	Not Detected	Wall	Fibre cement product	
Townsville	DF131	17-04-15	002	Floor	Sampled by JTA circa 2012. Vinyl sheet with backing layer. No asbestos detected. PLM & XRD analysis. Contains SMF.	AT060812.01		Not Detected	Floor Covering	Vinyl sheet	
Townsville	DF131	16-04-15	010	Wall North	Fibre cement sheeting		ASB_00470	Not Detected	Wall	Fibre cement product	
Townsville	DF131	16-04-15	C001 outside room 010 South face	Wall		AT060812.03		Not Detected	Wall	Fibre cement product	
Townsville	DF131	17-04-15	Roof space	Hot Water service (in use) above Rm001	No suspected ACM found.		Not sampled	Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DF132	17-01-15	001	North wall around doors to Rm002.	Some sheets are hardboard/Masonite majority cement sheet		AW15011 7/10	Not Detected	Walls	Fibre cement product	
Townsville	DF132	17-01-15	006 laundry & 007 Toilet/shower	Wall cladding internal and external	External wall cladding previously sampled by JTA [AT300712.05] asbestos not detected. Internal cladding is visually identical to external.			Not Detected	Walls	Fibre cement product	
Townsville	DF132	17-01-15	008	Infill above doorway (folding door) to Rm003.			AW15011 7/09	Not Detected	Walls	Fibre cement product	
Townsville	DF132	17-01-15	008	Ceiling with perforated cement sheet		AT020312.14		Not Detected			
Townsville	DF132	17-01-15	008	Ceiling, flat sheet no perforations	This item does not include small brick walled room at East of 008 (see AW150117/06)	AT300712.07		Not Detected			
Townsville	DF132	17-01-15	009A	Internal North wall	Appears to be modern FC sheet, sampled to confirm, representative of all walls in 009a etc..		AW15011 7/07	Not Detected	Walls	Fibre cement product	
Townsville	DF132	17-01-15	011	Ceiling	perforated sheets. Also in 011A		AW15011 7/05	Not Detected	Ceiling	Fibre cement product	
Townsville	DF132	17-01-15	External, East, Awning over concrete deck.	Ceiling	Cement sheet.	AT020312.12		Not Detected	Ceiling	Fibre cement product	
Townsville	DF132	17-01-15	External, North, front entrance	Ceiling	Cement sheet.	AT300712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DF132	17-01-15	External, North, front entrance area	Walls	Fibrocement faux timber weatherboards. Previously sampled by JTA and Abscan.	AT300712.03		Not Detected	Walls	Fibre cement product	
Townsville	DF132	17-01-15	External, South	Wall cladding external to room 006.	Cement sheet.	AT300712.05		Not Detected	Walls	Fibre cement product	
Townsville	DF132	17-01-15	Roof space	Insulation over ceiling.	Synthetic mineral fibre	AT020312.17		Not Detected	Insulation		
Townsville	DF 132	13-03-19	002	Storeroom	Test to ceiling identified no acm			Not Detected	Ceiling	Fibre cement product	
Townsville	DG242	15-04-15	005	Floor	Light green	0285/07 DG242-03		Not Detected	Floor	Vinyl tile	
Townsville	DG242	15-04-15	007	Floor	Modern vinyl sheet. No backing layer. Not suspected to contain asbestos.			Not Detected	Floor	Vinyl sheet	
Townsville	DG242	15-04-15	011	West and South Walls	New fibre cement sheeting applied to west and south walls in October 2013.			Not Detected	Wall	Fibre cement product	
Townsville	DG242	15-04-15	External	Expansion joint		AT250712.40		Not Detected	Sealant	Mastic	
Townsville	DG243	25-07-12	002	Upper walls		AT250712.20		Not Detected	Wall	Fibre cement product	
Townsville	DG251	23-07-12	124	Ceiling	Ripple finish	AT230712.04		Not Detected	Ceiling	Fibre cement product	
Townsville	DG251	23-07-12	Stairs to First Floor	Floor under vinyl sheet		AT230712.02		Not Detected	Floor	Fibre cement product	
Townsville	DG252	24-07-12	001	Floor under carpet	Cream vinyl tiles	AT240712.03		Not Detected	Floor	Vinyl tile	
Townsville	DG252	24-07-12	001A	Floor covering	Grey vinyl tiles	AT240712.07		Not Detected	Floor	Vinyl tile	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DG252	24-07-12	002	Walls		AT240712.05		Not Detected	Wall	Fibre cement product	
Townsville	DG252	24-07-12	100C	Floor under floor covering	Grey vinyl tiles	AT240712.06		Not Detected	Floor	Vinyl tile	
Townsville	DG252	24-07-12	214	Door infill panel	Confirmed by Abscan 2007			Not Detected	Wall	Fibre cement product	
Townsville	DG252	24-07-12	EXTERNAL	Walls		AT240712.02		Not Detected	Wall	Fibre cement product	
Townsville	DG253	24-07-12	110	Floor covering	Cream vinyl tile	AT240712.14		Not Detected	Floor	Vinyl tile	
Townsville	DG253	24-07-12	110	Walls		AT240712.15		Not Detected	Wall	Fibre cement product	
Townsville	DG253	24-07-12	207	Floor covering	Cream vinyl tile. Confirmed by Abscan 2007.	0285/07 DG253-15		Not Detected	Floor	Vinyl tile	
Townsville	DG253	24-07-12	207	Walls	Confirmed by Abscan 2007	0285/07 DG253-16		Not Detected	Wall	Fibre cement product	
Townsville	DG253	24-07-12	001	Walls	Confirmed by Abscan 2007	0285/07 DG253-09		Not Detected	Wall	Fibre cement product	
Townsville	DG253	24-07-12	005	Walls		AT240712.10		Not Detected	Wall	Fibre cement product	
Townsville	DG253	24-07-12	005	Rear wall	Confirmed by Abscan 2007	0285/07 DG253-07		Not Detected	Wall	Fibre cement product	
Townsville	DG253	24-07-12	204	Floor covering	Confirmed by Abscan 2007	0285/07 DG253-18		Not Detected	Floor	Vinyl tile	
Townsville	DG253	24-07-12	213	Ceiling	Ripple finish	AT240712.16		Not Detected	Ceiling	Fibre cement product	
Townsville	DG253	24-07-12	Level 1 External Corridor	Window infills		AT240712.13		Not Detected	Wall	Fibre cement product	
Townsville	DG254	06-08-12	005A	Walls		AT060812.10		Not Detected	Wall	Fibre cement product	
Townsville	DG255	24-07-12	002A	Floor under carpet	Yellow vinyl tiles	AT240712.20		Not Detected	Floor	Vinyl tile	
Townsville	DG255	24-07-12	102	Walls		AT240712.21		Not Detected	Wall	Fibre cement product	
Townsville	DG255	24-07-12	203	Floor covering	Grey vinyl tiles. Presumed no asbestos detected by JTA. Sampled in Building 252. Abscan sampled in 2007 and no asbestos detected.	0285/07 DG255-14		Not Detected	Floor	Vinyl tile	
Townsville	DG255	24-07-12	External Level 2 Walkway	Walls		AT240712.22		Not Detected	Wall	Fibre cement product	
Townsville	DG256	25-07-12	002	Ceiling		AT250712.05		Not Detected	Ceiling	Fibre cement product	
Townsville	DG256	25-07-12	004	Floor under carpet		AT250712.06		Not Detected	Floor	Vinyl sheet	
Townsville	DG256	25-07-12	007	Walls		AT250712.04		Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DG256	25-07-12	007	Window infills	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG256-03		Not Detected	Cladding	Fibre cement product	
Townsville	DG256	25-07-12	204	Walls		AT250712.10		Not Detected	Wall	Fibre cement product	
Townsville	DG256	25-07-12	213	Floor covering	Cream vinyl tile.	AT250712.08		Not Detected	Floor	Vinyl tile	
Townsville	DG256	25-07-12	213	Floor under vinyl tiles	Black adhesive.	AT250712.09		Not Detected	Floor	Adhesive	
Townsville	DG256	25-07-12	EXTERNAL	Expansion joint	Black sealant	AT250712.01		Not Detected	Sealant	Mastic	
Townsville	DG256	25-07-12	EXTERNAL	Window infill panels	Pink cement sheet	AT250712.03		Not Detected	Wall	Fibre cement product	
Townsville	DG256	25-07-12	EXTERNAL	East wall awning & fascia	Some broken fascia pieces on ground.	AT250712.02		Not Detected	Awning	Fibre cement product	
Townsville	DG256	25-07-12	Level 1 External Walkway	Walls	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG256-11		Not Detected	Wall	Fibre cement product	
Townsville	DG257	06-08-12	012	Walls	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG257-11		Not Detected	Wall	Fibre cement product	
Townsville	DG257	06-08-12	EXTERNAL	Eave linings	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG257-01		Not Detected	Eaves	Fibre cement product	
Townsville	DG257	06-08-12	EXTERNAL	Awning linings		AT060812.12		Not Detected	Awning	Fibre cement product	
Townsville	DG257	06-08-12	EXTERNAL	Infills to rear wall surrounding ducting		AT060812.13		Not Detected	Infill panels	Fibre cement product	
Townsville	DH100	15-04-15	Corridor to Courts	Floor	Non-asbestos vinyl sheet. No backing layer.			Not Detected	Floor	Vinyl sheet	
Townsville	DH100	15-04-15	Corridor to Courts	Floor	Vinyl tiles beneath vinyl sheet	AT260712.21		Not Detected	Floor	Vinyl tile	
Townsville	DH100	15-04-15	External	Ceiling	Northern covered area	See AT260712.22		Not Detected	Ceiling	Fibre cement product	
Townsville	DH100	15-04-15	External	Eaves	South side eave soffit (upper). Appears to be new material. Photo in Abscan report circa 2010 indicates this eave soffit was previously clad with timber slats.		ASB_001 37	Not Detected	Eaves	Fibre cement product	
Townsville	DH100	15-04-15	Men's & Ladies Toilets	Partitions		AT260712.23		Not Detected	Partitions	Fibre cement product	
Townsville	DH100	15-04-15	Toilets on East Wall	Walls		See AT260712.22		Not Detected	Wall	Fibre cement product	
Townsville	DH100	14-04-15	Viewing area & courts	Walls		See AT260712.22		Not Detected	Wall	Fibre cement product	
Townsville	DH100	14-04-15	Viewing area & courts	Ceiling		AT260712.22		Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DH101	14-04-15	External	Infill, top of blockwork wall to roof	Previously sampled by Abscan (2007) and JTA (2012)	0285/07 DH101-01 & AT060812.20		Not Detected	Infill	Fibre cement product	
Townsville	DX191	03-11-15	003	Floor	Modern sheet vinyl on concrete, not suspected to be ACM			Not Detected	Floor Covering	Vinyl sheet	
Townsville	DX191	03-11-15	004	Ceiling to ladies toilet. Ceiling space accessed from this room.	Cement sheet	AT010312.04	ASB_032 83	Not Detected	Ceiling	Fibre cement product	
Townsville	DX191	03-11-15	External	Soffit & fascia	Cement sheet product	AT010312.01	ASB_032 85	Not Detected	Eaves	Fibre cement product	
Townsville	DX191	03-11-15	External	Walkway beams boxed in with identical product as soffit round admin building	Cement sheet product, representative samples taken at other nearby locations [AT010312.01 & ASB_03285]			Not Detected	Cladding	Fibre cement product	
Townsville	DX191	03-11-15	External	Support posts for covered walkway	Fibre cement pipe	AT010312.02	ASB_032 86	Not Detected	Column	Fibre cement product	
Townsville	DX191	03-11-15	External	Switchboard	Viewed inside switch cabinet. No visible suspected ACM.			Not Detected			
Townsville	DX191	03-11-15	Internal	Roof space	No suspected ACM found.			Not Detected			
Townsville	DX191	03-11-15	Internal corridor between ladies and men's toilet	Corridor between ladies and men's toilet Ceiling	Cement sheet		ASB_032 84	Not Detected	Ceiling	Fibre cement product	
Townsville	DX192	03-11-15	002	Sheet vinyl floor covering	Shows 004 on plan. Modern sheet vinyl on concrete, not suspected to be ACM			Not Detected	Floor Covering	Vinyl sheet	
Townsville	DX192	03-11-15	002	Ceiling	Cement sheeting		ASB_032 87	Not Detected	Debris	Fibre cement product	
Townsville	DX192	03-11-15	003	Ceiling	Cement sheeting	AT010312.05	ASB_032 88	Not Detected	Ceiling	Fibre cement product	
Townsville	DX192	03-11-15	External	Eave lining & fascia panels	Cement sheeting, sampled by JTA.	AZ010312.03		Not Detected	Eave & Fascia		
Townsville	DX192	03-11-15	Internal	Roof space	No suspected ACM found.			Not Detected			
Townsville	DX193 "B Block"	03-11-15	006	Ceiling boxed section to Ducting.	Painted cement sheet. Taken as representative of cladding around ducting throughout. Also sampled by JTA (location not recorded).	AT010312.10	ASB_032 90	Not Detected	Ceiling	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	009	Ceiling toilet /shower recess / vanity area	Painted cement sheet		ASB_032 89	Not Detected	Ceiling	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	109	Bathroom ceiling	Painted cement sheet. Same material as bathroom 213. (See sample ASB_03291)			Not Detected	Ceiling	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	207 & 208	Bathroom ceiling	Painted cement sheet. Same material as bathroom 213. (See sample ASB_03291)			Not Detected	Ceiling	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	212	Bathroom ceiling	Painted cement sheet. Same material as Room 213. (See sample ASB_03291)			Not Detected	Ceiling	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	213	Bathroom ceiling	Painted cement sheet		ASB_032 91	Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DX193 "B Block"	03-11-15	External	Support columns	Cement casing	AT010312.06	ASB_03295	Not Detected	Column	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	External	Gable infills under metal panels	Cement sheet, previously sampled by JTA.	AT010312.07		Not Detected	Cladding	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	External	Fascia	Cement sheeting		ASB_03294	Not Detected	Fascia	Fibre cement product	
Townsville	DX193 "B Block"	03-11-15	Internal	Roof Space	No suspected ACM found.			Not Detected			
Townsville	DX193 "B Block"	03-11-15	Top level balcony eastern side	Soffit lining	Cement sheeting. Taken as representative of all Balcony ceilings/soffits. Previously sampled by JTA.	AT010312.08	ASB_03293	Not Detected	Soffit	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	009	Ceiling	Toilet / Vanity /Shower. Material same as 109 (see sample ASB_03298)			Not Detected	Ceiling	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	109	Ceiling	Toilet / Vanity /Shower		ASB_03298	Not Detected	Ceiling	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	209	Ceiling	Shower / toilet / vanity area		ASB_03296	Not Detected	Ceiling	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	211	Ceiling	Shower area. Same material as 209 (see sample ASB03296).			Not Detected	Ceiling	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	212A	Balcony soffit	Cement sheeting. Previously sampled by JTA, precise location not recorded.	AT010312.09	ASB_03297	Not Detected	Soffit	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	Between block B & A to left of undercover walkway	Electrical pits	Concrete pits		ASB_03299	Not Detected	Service Pit	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	Between block B & A to left of undercover walkway	Overflow gully	Formwork		ASB_03300	Not Detected	Service Pit	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	External	Fascia	Same material as B block, (see sample ASB_03294)			Not Detected	Fascia	Fibre cement product	
Townsville	DX194 "A Block"	03-11-15	Internal	Roof Space	No suspected ACM found.			Not Detected			
Townsville	DY111	29-01-15	001	Walls	Plaster. No fibre cement sheet observed as reported by JTA. Nail punched through walls in several locations to check for cement sheet under new cladding.			Not Detected			
Townsville	DY111	29-01-15	001	Infill around door frame leading to 002. Continuation of wall in 005 (sampled)	Same as ASB_00022			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	002	Walls			ASB_00021	Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	002	Ceiling	Same as ASB_00021			Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	29-01-15	005	East wall			ASB_00022	Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	007	Shower recess walls	Inspected behind laminate to shower recess. Panels laid into timber frame. No fibre cement sheet observed.			Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY111	29-01-15	012	Walls	Toilet and storeroom have same material. Same as ASB_00023			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	015	Infill panels to western window			ASB_00024	Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	117	Ceiling	Sprayed coating		ASB_00028	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	29-01-15	164	Ceiling	Sprayed coating		ASB_00027	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	29-01-15	206	Ceiling	Sprayed coating		ASB_00029	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	29-01-15	258	Ceiling	Sprayed coating		ASB_00026	Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	17-04-15	A wing Roof Space	Roof space above Rm338. Settled dust on ceiling.	No visible evidence of suspect roofing insulation material.		ASB_00167	Not Detected	Dust	Dust	
Townsville	DY111	28-01-15	A337 Toilets	Wall cavity behind toilets	Quarter round of fibre cement pipe strapped to black Asbestos Cement pipe. Eastern most toilet cubicle.		ASB_00019	Not Detected	Patch	Fibre cement product	
Townsville	DY111	28-01-15	Bathroom - Room 301	Walls under ceramic tiles	Modern fibre cement sheet. Sampled by JTA in 2012 location description "1st floor Unisex Toilets"	AT260712.10		Not Detected	Wall	Fibre cement product	
Townsville	DY111	28-01-15	Corridor	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor corridor B-Wing, asbestos not detected.	See AT260712.08		Not Detected	Floor	Vinyl sheet	
Townsville	DY111	28-01-15	Corridor to Rooms 201 to 213 & 214 to 236	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing, asbestos not detected.	See AT260712.09		Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	29-01-15	East wing	Infill panels beneath southern windows	Same material as ASB_00024			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 003 (Kevin Hodson room)	West wall	Mixture of fibre cement and plasterboard		ASB_00025	Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	East bathroom	Fibre cement sheet behind laminate. Laminate laid on same material as ASB_00025			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	West corridor, step down from main living area. Walls	Fibre cement sheet similar to 00025 used to walls of corridor			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	West bathroom walls	Ceramic tiles laid on fibre cement sheet, similar to 00025			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	West bathroom ceiling	Fibre cement sheet similar to ASB_00025			Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	West toilet wall	Wall adjoining bathroom is fibre cement sheet similar to ASB_00025			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	West toilet ceiling	Fibre cement sheet similar to 00025			Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	Wall cladding to veranda	Fibre cement sheet similar to ASB_00025			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing 014	External wall cladding to end of west corridor	Fibre cement sheet similar to ASB_00025			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	East wing kitchen	External walls	Same material as ASB_00024			Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY111	27-01-15	EXTERNAL	Wall adjacent Laundry 008	Sampled by JTA in 2012.	AT260712.04		Not Detected	Wall	Fibre cement product	
Townsville	DY111	27-01-15	EXTERNAL	Upper infills above doors adjacent Room 003, Ground Floor	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712.02		Not Detected	Wall	Fibre cement product	
Townsville	DY111	27-01-15	EXTERNAL	Window - lower infills	Sampled by JTA in 2012.	AT260712.01		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	External	Veranda soffit between rooms 001 and 003	Same as ASB_00023			Not Detected			
Townsville	DY111	29-01-15	External	External facing walls of veranda to 001 and 003			ASB_00023	Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	External	Infill above doors to 001, 003 and 004	Same as ASB_00023			Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	External Toilet Adjacent to Room 003	Walls under ceramic tiles	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712.02		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	External Toilet Adjacent to Room 003	External walls	Cement sheet. No asbestos detected.	AT260712.05		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	External Toilet Adjacent to Room 003	Ceiling	Modern fibre cement sheet. Sample from wall considered representative.	See AT260712.05		Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	28-01-15	FIRST FLOOR Corridor - B Section	Floor under carpet	Cream vinyl sheet. No asbestos detected. PLM & XRD analysis.	AT260712.08		Not Detected	Floor	Vinyl sheet	
Townsville	DY111	28-01-15	FIRST FLOOR Corridor - B Section	Ceiling	Sprayed finish. No asbestos detected.	AT260712.09		Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	29-01-15	Ground Floor General	Upper infills to doors / windows	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712.02		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Kitchen Adjacent to Room 002	External wall	Modern fibre cement sheet, Representative sample taken external to Laundry 008.	See AT260712.04		Not Detected	Wall	Fibre cement product	
Townsville	DY111	28-01-15	Levels 1, 2 & 3	Fire doors	All inspected fire doors were labelled with installation date of 2009			Not Detected			
Townsville	DY111	29-01-15	Living Room; Kitchenette & Room 013	External wall, Room 013	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	AT260712.02		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 001 Living Area & Kitchenette	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 002	External wall	Modern fibre cement sheet, Representative sample taken external to Laundry 008.	See AT260712.04		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 002	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 002	Walls under ceramic tiles	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY111	29-01-15	Room 002	Ceiling	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	29-01-15	Room 003	Walls	Modern fibre cement sheet. Representative sample taken external to Laundry 008.	See AT260712.04		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 003	Window infills	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712.02		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 005	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 013 Toilets	Walls	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712.02		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Room 013 Toilets	Ceiling	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712.02		Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	29-01-15	Room 015	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Rooms 012; 011; 010	Floor under carpet	Green vinyl tiles. No asbestos detected. PLM & XRD analysis. Sample taken in Room 012.	AT260712.03		Not Detected	Floor	Vinyl tile	
Townsville	DY111	29-01-15	Rooms 012; 011; 010	Walls, sampled in room 012	Cement sheet. No asbestos detected.	AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	28-01-15	Rooms 101 to 136	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor corridor B-Wing, asbestos not detected.	See AT260712.08		Not Detected	Floor	Vinyl sheet	
Townsville	DY111	28-01-15	Rooms 101 to 136	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing, asbestos not detected.	See AT260712.09		Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	28-01-15	Rooms 158 to 137	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor corridor B-Wing, asbestos not detected.	See AT260712.08		Not Detected	Floor	Vinyl sheet	
Townsville	DY111	28-01-15	Rooms 158 to 137	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing, asbestos not detected.	See AT260712.09		Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	28-01-15	Rooms 177 to 162	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor corridor B-Wing, asbestos not detected.	See AT260712.08		Not Detected	Floor	Vinyl sheet	
Townsville	DY111	28-01-15	Rooms 177 to 162	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing, asbestos not detected.	See AT260712.09		Not Detected	Sprayed Coating	Textured Coating	
Townsville	DY111	27-01-15	Rooms 372 to 301	Floor covering	Vinyl carpet backing. No asbestos detected. Sample taken in Room 301 by JTA in 2012.	AT260712.12		Not Detected	Floor	Vinyl sheet	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY111	27-01-15	Rooms 372 to 301	Floor under carpet	Green vinyl sheet. No asbestos detected. PLM & XRD analysis. Sample taken in Room 312 by JTA in 2012.	AT260712.11A		Not Detected	Floor	Vinyl sheet	
Townsville	DY111	28-01-15	Rooms on Levels 1, 2 & 3	Flooring beneath carpet	All rooms inspected had either concrete or modern sheet vinyl beneath carpet. Some vinyl removal has taken place since JTA audit.			Not Detected			
Townsville	DY111	29-01-15	Store Room 008; 009; 009A	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Store Room to Room 006	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Toilet to Room 006	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Toilet to Room 006	Walls under ceramic tiles	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Wall	Fibre cement product	
Townsville	DY111	29-01-15	Toilet to Room 006	Ceiling	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712.06		Not Detected	Ceiling	Fibre cement product	
Townsville	DY111	28-01-15	Toilets - A Section	Walls under ceramic tiles	Modern fibre cement sheet. Sampled by JTA in 2012 location description "1st floor Unisex Toilets"	AT260712.10		Not Detected	Wall	Fibre cement product	
Townsville	DY111	28-01-15	Toilets - Central	Walls under ceramic tiles	Modern fibre cement sheet. Sampled by JTA in 2012 location description "1st floor Unisex Toilets"	AT260712.10		Not Detected	Wall	Fibre cement product	
Townsville	DY111	28-01-15	Toilets - West	Walls under ceramic tiles	Modern fibre cement sheet. Sampled by JTA in 2012 location description "1st floor Unisex Toilets"	AT260712.10		Not Detected	Wall	Fibre cement product	
Townsville	DY112	16-04-15	000B Plant room	Copper cables, four of, (disconnected) running from old switch cabinet, along ceiling & down west wall.	White powdery insulation between central copper wire and outer sheath.		ASB_00153	Not Detected	Electrical cable	Loose Fibre	
Townsville	DY112	03-02-15	004 outside the building, new fibre cement sheet to walls and ceiling		Room partitioned within last 5 years			Not Detected	Cladding	Fibre cement product	
Townsville	DY112	02-02-15	104	Infill panels to doorframe			ASB_00040	Not Detected	Wall	Fibre cement product	
Townsville	DY112	03-02-15	105	Floor	Cream vinyl tile beneath carpet	AT300712.16		Not Detected	Floor	Vinyl tile	
Townsville	DY112	03-02-15	105	Infill panels beneath windows on East wall, southern end	Same material as ASB_00041			Not Detected	Wall	Fibre cement product	
Townsville	DY112	03-02-15	106	Infill panels beneath windows on East wall			ASB_00041	Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY112	03-02-15	106	Floor	Cream vinyl tile beneath carpet	AT300712.16		Not Detected	Floor	Vinyl tile	
Townsville	DY112	03-02-15	107	Walls		AT300712.15		Not Detected	Wall	Fibre cement product	
Townsville	DY112	03-02-15	107	Ceiling		See AT300712.15		Not Detected	Ceiling	Fibre cement product	
Townsville	DY112	17-04-15	1st floor	Cement sheet panels sealing under expansion gaps	Panels installed to stop bitumen sealant dripping in hot conditions. Previously sampled by JTA in 2012.	AT300712.12		Not Detected	Ceiling	Fibre cement product	
Townsville	DY112	03-02-15	External	Roof/ceiling	Bituminous sealing compound	AT300712.13		Not Detected	Sealant	Bituminous product	
Townsville	DY112	03-02-15	External	Infill above windows on east wall		See AT300712.12		Not Detected	Wall	Fibre cement product	
Townsville	DY112	16-04-15	HVAC System	Ventilation system inspected with FCOM (Jake)	No ACM heater banks or firedampers located during inspection.			Not Detected	HVAC		
Townsville	DY112	17-04-15	Roof space	Over room 107	Cement sheeting over existing roof		ASB_00160	Not Detected	Roof	Fibre cement product	
Townsville	DY114	19-01-15	012	Outside the room	Electrical meter box and RCD switchboard visually inspected. Metal and plastic. Not suspected to contain asbestos.			Not Detected			
Townsville	DY114	19-01-15	013B (Living Area)	Floor	Modern vinyl sheet. No backing layer. Not suspected to contain asbestos.			Not Detected	Floor Covering	Vinyl sheet	
Townsville	DY114	19-01-15	014 (bathroom)	Panelling to shower recess	Inspected behind the laminate and it is timber battens. Laminate is particle board.			Not Detected	Cladding		
Townsville	DY114	19-01-15	Corridor	Small infills above bedroom doors	Sample was taken by JTA asbestos not detected. Material visually consistent with modern FC sheet. All instances inspected show same visual characteristics.	AT300712.22		Not Detected	Wall	Fibre cement product	
Townsville	DY114	19-01-15	External	Eaves	Sample of eaves was taken by JTA asbestos not detected. Eaves are same material around the perimeter.	AT300712.20		Not Detected	Eaves	Fibre cement product	
Townsville	DY114	19-01-15	External	Gable ends	Sample of gable end was taken by JTA asbestos not detected. Gable ends are same material and colour around the perimeter.	AT300712.21		Not Detected	Cladding	Fibre cement product	
Townsville	DY114	20-01-15	External	Veranda ceiling	Sampled from the east end. Similar material used on the west end.		AG20150120/6	Not Detected	Ceiling	Fibre cement product	
Townsville	DY114	19-01-15	External	Upper wall infills, where wall meets eave	Sample of eave soffit cladding considered to be representative of this material.	See AT300712.20		Not Detected	Wall	Fibre cement product	
Townsville	DY115	19-01-15	000V front/East veranda	Ceiling	Fibre cement sheet. Sampled because fixtures are different to those used in the rear veranda.		AG20150119/4	Not Detected	Ceiling	Fibre cement product	
Townsville	DY115	20-01-15	000V rear/west veranda	Dividing wall/doorway	Fibre cement sheet.		AG20150119/2	Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY115	19-01-15	000V rear/west veranda	Ceiling	Fibre cement sheet. All sheets appear to be the same as there are no different fittings used and the strips to hide the joins are the same.		AG20150 119/3	Not Detected	Ceiling	Fibre cement product	
Townsville	DY115	19-01-15	008 (laundry) and 008A (toilet)	Walls	Plasterboard, not fibre cement as previously reported. Not suspected to contain asbestos.			Not Detected			
Townsville	DY115	19-01-15	008B (bathroom)	North and East walls	Fibre cement sheet. North wall sampled.		AG20150 119/1	Not Detected	Wall	Fibre cement product	
Townsville	DY115	19-01-15	External	Gable ends	Visually inspected gable ends from within roof space. Same product at each end. Not suspected ACM found during roof space inspection.	AT020812.41		Not Detected	Cladding	Fibre cement product	
Townsville	DY115	19-01-15	External	Awning infill panel	Fibre cement sheet. Same material used at North end, same fixtures. Sample taken from South awning.		AG20150 119/5	Not Detected	Ceiling	Fibre cement product	
Townsville	DY115	19-01-15	External	Eaves	Sample was taken by JTA and confirmed as negative. All sheets appear similar in age and appearance. Damage as previously reported still present	AT020812.40		Not Detected	Eaves	Fibre cement product	
Townsville	DY116	20-01-15	109	Bathroom & laundry	Blue laminate to shower area. Removed top cover to laminate and timber visible behind the sheet from above.			Not Detected	Cladding		
Townsville	DY116	20-01-15	111	Bathroom & laundry	Blue laminate to shower area. Removed top cover to laminate and timber visible behind the sheet from above.			Not Detected	Cladding		
Townsville	DY116	20-01-15	009	Bathroom & laundry	Very light brown laminate to shower area. Removed top cover to laminate and timber visible behind the sheet from above.			Not Detected			
Townsville	DY116	20-01-15	010	Bathroom/toilet (disabled facility)	Infill panel above door. Previously sampled by JTA asbestos not detected.	AT270712.20		Not Detected	Wall	Fibre cement product	
Townsville	DY116	20-01-15	011	Cupboard	Infill panel above door. Previously sampled by JTA asbestos not detected.	See AT270712.20		Not Detected	Wall	Fibre cement product	
Townsville	DY116	20-01-15	011	Hot water service in cupboard adjacent 011	Infill panel above door. Previously sampled by JTA asbestos not detected.	See AT270712.20		Not Detected	Wall	Fibre cement product	
Townsville	DY116	20-01-15	100C (cupboard)	Infills above cupboard doors	Previously sampled by JTA. Asbestos not detected.	AT270712.20		Not Detected	Wall	Fibre cement product	
Townsville	DY116	20-01-15	112 (cupboard)	Infills above cupboard doors	Previously sampled by JTA. Asbestos not detected.	See AT270712.20		Not Detected	Wall	Fibre cement product	
Townsville	DY116	20-01-15	External	Eaves	Sample of eaves was taken by JTA Asbestos not detected. Eaves are same material around the perimeter.	AT270712.21		Not Detected	Eaves	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY116	20-01-15	External	Wall linings under eaves	Sample from eave soffit taken as representative of this material based on visual characteristics.	See AT270712.21		Not Detected	Wall	Fibre cement product	
Townsville	DY117	20-01-15	108	Behind laminate in shower recess	No fibre cement sheet observed from above. Where inspected, timber battens.			Not Detected			
Townsville	DY117	20-01-15	113	Behind laminate in shower recess	No fibre cement sheet observed from above. Where inspected, timber battens.			Not Detected			
Townsville	DY117	20-01-15	008	Shower wall lining under Laminex	Previously sampled by JTA in 2012. Visually confirmed. Note, not used in 013.	AT270712.23		Not Detected	Wall	Fibre cement product	
Townsville	DY117	20-01-15	008	Ceiling	Previously sampled by JTA in 2012 asbestos not detected. Visually confirmed.	AT270712.24		Not Detected	Ceiling	Fibre cement product	
Townsville	DY117	20-01-15	010	Ceiling	Same material as in 008	See AT270712.24		Not Detected	Ceiling	Fibre cement product	
Townsville	DY117	20-01-15	012	Ceiling	Same material as in 008	See AT270712.24		Not Detected	Ceiling	Fibre cement product	
Townsville	DY117	20-01-15	013	Ceiling	Same material as in 008	See AT270712.24		Not Detected	Ceiling	Fibre cement product	
Townsville	DY117	20-01-15	015 (kitchen)	Floor	Modern vinyl sheet. Not suspected to contain asbestos.			Not Detected	Floor	Vinyl sheet	
Townsville	DY117	20-01-15	100C (corridor)	Infill panels above bedroom doors in corridor	Previously sampled by JTA in 2012 asbestos not detected. Visually confirmed.	AT270712.27		Not Detected	Wall	Fibre cement product	
Townsville	DY117	20-01-15	100C (corridor)	Roof space access panel at west end	Fibre cement sheet		ASB_00001	Not Detected	Access Hatch	Fibre cement product	
Townsville	DY117	20-01-15	External	Eaves	Sample of eaves was taken by JTA in 2012 asbestos not detected. Eaves are same material around the perimeter and no sample collected.	AT270712.26		Not Detected	Eaves	Fibre cement product	
Townsville	DY117	20-01-15	External	Wall linings under eaves	Similar material to eaves. Not sampled.	See AT270712.26		Not Detected	Wall	Fibre cement product	
Townsville	DY117	20-01-15	External	First floor landing, East end	Fibre cement sheet used as flooring. Previously sampled by JTA in 2012 asbestos not detected. Visually confirmed.	AT270712.25		Not Detected	Wall	Fibre cement product	
Townsville	DY118	21-01-15	010	Shower area	No fibre cement sheeting observed behind the laminate where inspected. Laminate is particle board.			Not Detected			
Townsville	DY118	21-01-15	010	Ceiling		See AT270712.30		Not Detected	Ceiling	Fibre cement product	
Townsville	DY118	21-01-15	011	Ceiling		See AT270712.30		Not Detected	Ceiling	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DY118	21-01-15	014	Ceiling		See AT270712.30		Not Detected	Ceiling	Fibre cement product	
Townsville	DY118	21-01-15	015	Shower area	No fibre cement sheeting observed behind the laminate where inspected. Laminate is particle board.			Not Detected			
Townsville	DY118	21-01-15	015	Ceiling		AT270712.30		Not Detected	Ceiling	Fibre cement product	
Townsville	DY118	21-01-15	100C (corridor)	Infill panels above bedroom doors in corridor	Each panel 900mmx200mm. 8 in total, 1 above each bedroom door. Sampled above 109.		ASB_00002	Not Detected	Wall	Fibre cement product	
Townsville	DY118	21-01-15	110	Shower area	Where inspected behind laminate, no fibre cement sheeting observed. Laminate is particle board			Not Detected			
Townsville	DY118	21-01-15	115	Shower area	Where inspected behind laminate, no fibre cement sheeting observed. Laminate is particle board			Not Detected			
Townsville	DY118	21-01-15	EXTERNAL	Eaves		AT270712.31		Not Detected	Eaves	Fibre cement product	
Townsville	DY118	21-01-15	EXTERNAL	Wall linings under eaves		See AT270712.31		Not Detected	Wall	Fibre cement product	
Townsville	DY118	21-01-15	EXTERNAL	Floor, first floor landing		See AT270712.25		Not Detected	Floor	Fibre cement product	
Townsville	DY119	15-04-15	External East	Infill above window for air con	Fibre cement sheeting		ASB_00461	Not Detected	Cladding	Fibre cement product	
Townsville	DY119	15-04-15	External East	Infill panels to right of air con unit x 2	Fibre cement sheeting		ASB_00462	Not Detected	Cladding	Fibre cement product	
Townsville	DY119	15-04-15	Internal East	Infill above window for air con - representative sample taken external	Fibre cement sheeting			Not Detected	Cladding	Fibre cement product	
Townsville	DZ261	18-02-15	External	West wall, lower level	Different material to that used on the upper level.		ASB_00066	Not Detected	Wall	Fibre cement product	
Townsville	DZ261	18-02-15	External	Upper walls		AT010812.30		Not Detected	Wall	Fibre cement product	
Townsville	DZ261	18-02-15	External	Eastern switchboard/storage	2 green coloured infill panels similar to ASB_00066			Not Detected	Infill	Fibre cement product	
Townsville	DZ261	18-02-15	Ground floor TV room	Ceiling			ASB_00070	Not Detected	Ceiling	Fibre cement product	
Townsville	DZ261	18-02-15	Ground floor TV room	Wall panel to west wall	Same as ASB_00066			Not Detected	Wall	Fibre cement product	
Townsville	DZ261	18-02-15	Laundry	Ceiling	Recorded in previous register (JTA 2012) as a sprayed coating to concrete. Current ceiling is modern fibre cement sheet. No sign of sprayed coating or concrete from ceiling access hatch.		ASB_00067	Not Detected	Ceiling	Fibre cement product	
Townsville	DZ261	18-02-15	Laundry	North wall			ASB_00069	Not Detected	Wall	Fibre cement product	
Townsville	DZ262	31-07-12	106	Walls		AT310712.17		Not Detected	Wall	Fibre cement product	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DZ262	31-07-12	Air Handler Room	Air conditioning flange joints	Sealant.	AT310712.14		Not Detected	Sealant	Mastic	
Townsville	DZ262	31-07-12	Ground Floor Rooms	Wall infill panels		AT310712.13		Not Detected	Infill panels	Fibre cement product	
Townsville	DZ262	31-07-12	Ground Floor Rooms	Ceiling		AT310712.12		Not Detected	Ceiling	Textured Coating	
Townsville	DZ262	31-07-12	Stairwell	Floor covering	Blue vinyl sheet with backing layer	AT310712.15		Not Detected	Floor	Vinyl sheet	
Townsville	DZ263	31-01-12	225 - Kitchen	Walls		AT310712.23		Not Detected	Wall	Fibre cement product	
Townsville	DZ263	31-01-12	Ground Floor Hot Water Service Room	Ceiling		AT310712.20		Not Detected	Ceiling	Masonry	
Townsville	DZ263	31-01-12	Ground Reception & Office	Floor under carpet	Blue vinyl tile	AT310712.22		Not Detected	Floor	Vinyl tile	
Townsville	DZ263	31-01-12	Ground Reception & Office	Floor under carpet	Cream vinyl tile.	AT310712.21		Not Detected	Floor	Vinyl tile	
Townsville	DZ263	31-01-12	Level 1 Riser Room Adjacent to Toilets off Corridor	Ceiling	Presumed no asbestos detected by JTA from material in same building	See AT310712.20		Not Detected	Ceiling	Masonry	
Townsville	DZ263	31-01-12	Level 2 Riser Room adjacent to Toilets	Floor	Presumed no asbestos detected by JTA from material in same building	See AT310712.20		Not Detected	Ceiling	Masonry	
Townsville	DZ264	01-08-12	Conference Rooms	Floor under floor covering	Cream patterned vinyl tiles	AT010812.06		Not Detected	Floor	Vinyl tile	
Townsville	DZ264	01-08-12	Ground Floor West End Store Room	Walls		AT010812.02		Not Detected	Wall	Fibre cement product	
Townsville	DZ264	01-08-12	Hot Water Service Room (1)	Ceiling		AT010812.03		Not Detected	Ceiling	Masonry	
Townsville	DZ264	01-08-12	Level 1 Corridor	Floor under carpet	Green vinyl tiles	AT010812.07		Not Detected	Floor	Vinyl tile	
Townsville	DZ264	01-08-12	Stairwell	Floor covering	Blue specked vinyl sheet with backing layer	AT010812.04		Not Detected	Floor	Vinyl sheet	
Townsville	DZ264	01-08-12	Stairwell	Landing walls		AT010812.05		Not Detected	Wall	Fibre cement product	
Townsville	DZ265	14-04-15	012 Male toilets	Switchboard	Backing board		ASB_00452	Not Detected	Electrical mounting board		
Townsville	DZ265	14-04-15	012 Male toilets	Walls	Fibre cement sheeting		ASB_00450	Not Detected	Wall	Fibre cement product	
Townsville	DZ265	14-04-15	014	Walls East and west	Infill panels Fibre cement sheeting		ASB_00455	Not Detected	Infill panel	Fibre cement product	
Townsville	DZ265	14-04-15	015	External wall	Fibre cement sheeting		ASB_00456	Not Detected	Wall	Fibre cement product	
Townsville	DZ265	14-04-15	015	Wall North side internal	Fibre cement sheeting		ASB_00457	Not Detected	Wall	Fibre cement product	
Townsville	DZ265	14-04-15	Dining hall	Floor	Part of floor is sheet vinyl		ASB_00458	Not Detected	Floor	Vinyl sheet	
Townsville	DZ265	14-04-15	Dining hall	Floor	Vinyl tiles under carpet - Previous report sampled in dining room	AT020812.20		Not Detected			
Townsville	DZ265	15-04-15	HVAC System		HVAC system inspected with Jake from FCOM. No ACM heater banks or fire dampers located during inspection.			Not Detected			

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type	Status
Townsville	DZ265	14-04-15	Kitchen & office area	Floor	Vinyl tiles under carpet - representative sample in dining hall area [ASB 00458]			Not Detected	Floor Covering		
Townsville	DZ266	01-08-12	E1	Walls under ceramic tiles		AT010812.42		Not Detected	Wall	Fibre cement product	
Townsville	DZ266	01-08-12	EXTERNAL	Walls	"Weatherboard"	AT010812.40		Not Detected	Wall	Fibre cement product	
Townsville	DZ266	01-08-12	EXTERNAL	Eave linings		AT010812.41		Not Detected	Eaves	Fibre cement product	
Townsville	DZ267	01-08-12	Cleaner's Cupboard	Infill to door		AT010812.20		Not Detected	Infill	Fibre cement product	
Townsville	DZ267	01-08-12	Gymnasium	Walls		AT010812.21		Not Detected	Wall	Fibre cement product	
Townsville	DZ267	01-08-12	Level 1 Corridor	Floor under carpet	Blue vinyl tile	AT010812.23		Not Detected	Floor	Vinyl tile	
Townsville	DZ267	01-08-12	Level 2 Hot Water Service Room	Floor	Beige vinyl tile	AT010812.24		Not Detected	Floor	Vinyl tile	
Townsville	DZ267	01-08-12	Level 2 Hot Water Service Room	Walls	Beige vinyl tile	AT010812.24		Not Detected	Wall	Vinyl tile	
Townsville	DZ267	01-08-12	Pool Table Room	Floor under carpet	Cream vinyl tile	AT010812.22		Not Detected	Floor	Vinyl tile	