

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
CAIRNS	55 Greenslopes	11/10/2015	Infill panel	Entrance to toilet area	Cement sheeting		ASB_0335_5	Not Detected	Wall	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Main area South end	Adjacent to access door to patio	Cement sheeting		ASB_0335_3	Not Detected	Wall	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Patio South end	North west corner wall	Cement sheeting		ASB_0335_2	Not Detected	Wall	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Print room 1	Ceiling	Cement sheeting on raked ceilings		ASB_0334_7	Not Detected	Ceiling	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Print room 1	Top wall section on East side	Cement sheeting above gyprock - same on west side. Sample taken as		ASB_0334_6	Not Detected	Wall	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Roof gable	External & internal cladding to Gables and gable soffits.	Representative sample taken North side internal cladding.		ASB_0334_8	Not Detected	Gable cladding	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Wet area	Above window East side internal & external	Infill with cement sheeting - different construction method to other rooms		ASB_0335_0	Not Detected	Wall	Fibre cement product
CAIRNS	55 Greenslopes	11/10/2015	Wet area (small) at Southern end	East wall above window - internal	Cement sheeting. Taken as representative of southern Patio, west		ASB_0335_1	Not Detected	Wall	Fibre cement product
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 1	Rear yard	Eaves		ASB_0151_2	Not Detected	Eaves	Fibre cement product
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 1	Rear yard	Tiles at Entrance to rear door, same as kitchen floor tiles		ASB_0151_3	Not Detected	Floor Covering	
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 1	Rear yard	Loose tiles on ground, same as lounge and bedroom tiles		ASB_0151_4	Not Detected	Floor Covering	
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 1	Front Yard	Eaves		Same as ASB_0151	Not Detected	Eaves	Fibre cement product
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 1	Unit 4 Shed	At entrance to Unit 1 Eaves		ASB_0151_6	Not Detected	Eaves	Fibre cement product
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 1	Carport	Decorative fascia		ASB_0151_7	Not Detected	Fascia	Fibre cement product
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 2	Rear yard	Eaves		ASB_0151_5	Not Detected	Eaves	Fibre cement product
Remote	10 Duchess Road, Mt Isa	7/20/2015	Unit 2	Front Yard	Eaves		Same as ASB_0151	Not Detected	Eaves	Fibre cement product
Remote	19 Samsa St, Mt Isa	7/20/2015	Ensuite	Walls	Tiled and Fibre Cement Sheeting added in 2011	0138/13-ED04		Not Detected	Wall	Fibre cement product
Remote	19 Samsa St, Mt Isa	7/20/2015	Ensuite	Ceiling	Fibre Cement Sheet added 2011	See 0138/13-		Not Detected	Ceiling	Fibre cement product
Remote	19 Samsa St, Mt Isa	7/20/2015	External	Eaves	New renovation, north east corner. Hardiflex installed in 2011	0138/13-ED06		Not Detected	Eaves	Fibre cement product
Remote	19 Samsa St, Mt Isa	7/20/2015	Rear Patio	Ceiling	Fibre Cement Sheeting added 2010		ASB_0152_0	Not Detected	Ceiling	Fibre cement product
Remote	19 Samsa St, Mt Isa	7/20/2015	Walk in Robe	Walls	Combination of Block on North, South, West and Fibre Cement Sheeting	See ASB_0152		Not Detected	Wall	Fibre cement product
Remote	19 Samsa St, Mt Isa	7/20/2015	Walk in Robe	Ceiling	Fibre Cement Sheet added 2011	See ASB_0152		Not Detected	Ceiling	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Bedroom 1	Wall - North Panel	Textured panel		ASB_0153_4	Not Detected	Wall	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)		ASB_0153_3	Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Bedroom 2	Wall - South Panel	Textured panel (ASB01534)			Not Detected	Wall	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Laundry	Sheeting on East Wall	Fibre Cement Sheet		ASB_0153_6	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Laundry	Tub	Precast Concrete - original		ASB_01537	Not Detected	Sink	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 1, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 2, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 2, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 2, Laundry	Tub	Precast Concrete - original (ASB 01537)			Not Detected	Basin	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 2, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 3, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 3, Bedroom 1	Wall - North Panel	Textured Panel		ASB_01542	Not Detected	Wall	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 3, Bedroom 2	Wall - South Panel	Textured Panel (ASB01542)			Not Detected	Wall	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 3, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 3, Laundry	Tub	Precast Concrete - original (ASB 01537)			Not Detected	Basin	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 3, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 4, Bedroom 1	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 4, Bedroom 2	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
Remote	35 East St, Mt Isa	7/21/2015	Unit 4, Laundry	Tub	Precast Concrete - original (ASB 01537)			Not Detected	Basin	Fibre cement product
Remote	35 East St, Mt Isa	7/21/2015	Unit 4, Lounge/Dining Room/Kitchen	Kickboard	Vinyl Kickboard common to all bedrooms and living areas (ASB01533)			Not Detected	Wall	Vinyl sheet
REMOTE	48 Jack Street	11/9/2015	Access to seminar room	Ramp way ceiling	Cement sheeting - representative sample taken in store room		same as ASB_0333	Not Detected	Ceiling	Fibre cement product
REMOTE	48 Jack Street	11/9/2015	Bed 1	Floor	Floral patterned vinyl type sheeting glued to Masonite type product. Carpet		ASB_03342	Not Detected	Floor	Vinyl sheet
REMOTE	48 Jack Street	11/9/2015	Bed 1	Southern wall	Fibrous plaster		ASB_03341	Not Detected	Wall	
REMOTE	48 Jack Street Atherton	11/9/2015	Bed 2	Floor	Carpet on vinyl type sheeting on top of Masonite - pattern type vinyl thin layer glued to masonite type product - representative sample taken bed 1			Not Detected	Floor	Vinyl sheet
REMOTE	48 Jack Street Atherton	11/9/2015	External	Western wall	Cement sheeting with render over		ASB_03345	Not Detected	Wall	Fibre cement product
REMOTE	48 Jack Street Atherton	11/9/2015	Man hole cover	Ceiling entrance	Cement sheeting		ASB_03343	Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
REMOTE	48 Jack Street Atherton	11/9/2015	Seminar room	Above Ceiling old soffit southern end	Cement sheeting		ASB_0333_5	Not Detected	Eaves	Fibre cement product
REMOTE	48 Jack Street Atherton	11/9/2015	Seminar room	Above Ceiling old gable sheeting East end	Cement sheeting -debris in ceiling space from hole being smashed through gable end wall, debris sitting in ceiling over access way to seminar room		ASB_0333_6	Not Detected	Debris	Fibre cement product
REMOTE	48 Jack Street Atherton	11/9/2015	Store room attached to seminar room	Ceiling	Cement sheeting		ASB_0333_4	Not Detected	Ceiling	Fibre cement product
REMOTE	48 Jack Street Atherton	11/9/2015	Toilet laundry area - behind seminar room	Ceiling	Cement sheeting - representative sample taken in store room		same as ASB_0333_4	Not Detected	Ceiling	Fibre cement product
REMOTE	48 Jack Street Atherton	11/9/2015	Toilet off hallway	Top section of Walls	Plaster		ASB_0333_8	Not Detected	Wall	
Remote	Duncragan House	7/14/2015	Common kitchen	North wall, centre of to west wall	East side of wall is Masonite		ASB_0053_6	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Common kitchen	West wall, including diagonal to window			Same as ASB_0053	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Common kitchen	Bulk head ceiling panel	Rest of ceiling and bulkhead vertical infill panels are Masonite		Same as ASB_0053	Not Detected	Ceiling	Fibre cement product
Remote	Duncragan House	7/14/2015	Common kitchen	Northeast wall infill panel between cabinets (above	fibre cement sheet 1m x 1m		Same as ASB_0053	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	East entrance foyer	Floor between rooms 5 and 6	Under green carpet		ASB_0052_5	Not Detected	Floor Covering	Fibre cement product
Remote	Duncragan House	7/15/2015	External house	External wall between bathhouse and room 19			ASB_0054_6	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/15/2015	External house	Common kitchen - Infill panel around box air conditioner			ASB_0054_7	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/15/2015	External house	Common kitchen - serving hatch	Hinged perforated panel, no longer used		ASB_0054_8	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/15/2015	External house	Infill panel on PVC pipe at ground level - South side of			ASB_0054_9	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Hallway external to room 4	East wall panel around entrance door (North section	1 sheet only		Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Hallway to common kitchen, South end	Cupboard internal walls (x3)	Assumed all 3 walls the same. Adjacent room 11 outside of common kitchen door		ASB_0053_3	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Hallway to common kitchen, South end	Adjacent to room 20 door	2 sheets above and South side of door. Assume same material as other side of		Same as ASB_0053	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Hallway to common kitchen, South end	Inside hallway at South courtyard door	Brown vinyl sheet. Masonite underlay. No glue.		ASB_0053_5	Not Detected	Floor Covering	Vinyl sheet
Remote	Duncragan House	7/14/2015	Main hallway Nth end	Wall sheeting around door to West entry foyer (opposite	Around door with security screen, 850mm door		ASB_0052_6	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	North entry foyer	East wall	Same material as hallway on the other side, refer to sample 00526		Same as ASB_0052	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	Duncragan House	7/14/2015	NW bathroom	Toilet and bathroom hallway	Black and white chequered tiles, matching. Sampled black tile		ASB_0053_9	Not Detected	Floor Covering	Vinyl tile
Remote	Duncragan House	7/14/2015	NW bathroom	Shower room	Raised ceramic tile floor, fibre cement 16mm sheet underneath		ASB_0055_0	Not Detected	Floor Covering	Fibre cement product
Remote	Duncragan House	7/14/2015	NW kitchen	Partition walls	Behind fridge, both sides of wall		ASB_0053_7	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	NW kitchen	Pantry backing, east side	Both sides, reverse captured in living room		Same as ASB_0053	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	NW living room	Pantry rear wall / hallway to dining	Both sides, reverse captured in pantry for kitchen		Same as ASB_0053	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 11	Serving hatch infill panel, west internal wall	Vertical sheet between 11 and the common kitchen		ASB_0052_3	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 13	West wall infill panel of removed door, South side of	1 sheet		ASB_0052_4	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 18	South wall	Entire wall		ASB_0052_7	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 20	East wall	Cement sheeting only, excluding tongue and groove		ASB_0053_1	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 20	South door infill panel	Door removed		ASB_0053_2	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 3	North wall, air conditioning infill panel	Not painted		ASB_0052_1	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	Room 4	West wall panel around entrance door (North section)	1 sheet only		ASB_0052_2	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	Shower base floor panel-East shower adjacent	16mm sheeting. Now cleaners store		ASB_0052_8	Not Detected	Floor Covering	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	East shower (cleaner's store)			Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	West shower			Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	Bathroom internal partition	Sample taken next to sinks, behind paper towel holder.		ASB_0052_9	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	Laundry	First room to the left		Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	Store room, opposite toilets	Second room to the left; Shelves in room		Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	South toilet			Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	Centre toilet			Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	North toilet			Same as ASB_0052	Not Detected	Wall	Fibre cement product
Remote	Duncragan House	7/14/2015	South west bath house	Floor, all areas except store room	Sheet vinyl, marble colour. Sample taken in north toilet		ASB_0053_0	Not Detected	Floor Covering	Vinyl sheet
Remote	Fletcherview Station	7/16/2015	Main residence- internal	Hallway cupboard	mounted wall panel underneath lowest shelf, E side		ASB_0056_3	Not Detected	Wall	Fibre cement product
Remote	Fletcherview Station	7/16/2015	Storage yard, external to sheds	30m SE of dongas laying against JCU fire truck	2x partial sheets plus debris on the ground (local)		ASB_0055_9	Not Detected	Debris	Fibre cement product
Remote	Fletcherview Station	7/16/2015	Student accommodation- ATCO dongas	Room 8, cupboard	Different colour sheet vinyl to rest of building		ASB_0055_6	Not Detected	Floor Covering	Vinyl sheet
Remote	Fletcherview Station	7/16/2015	Student accommodation- ATCO dongas	All rooms and hallway	Light pink vinyl sheeting		ASB_0055_8	Not Detected	Floor Covering	Vinyl sheet
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Lab walls - all	Sample taken behind fume cupboard		ASB_0225_1	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Instrument room	Room northeast of lab		Same as ASB_0225	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Store room	2nd room northeast of lab		Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Office A	3rd room northeast of lab		Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Office B	4th room northeast of lab		Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Hallway			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Tea room			Same as ASB_0225_1	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Toilet - East			Same as ASB_0225_1	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Toilet - West			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	General office / foyer			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	Vinyl tiles- all rooms	Light green colour, damage near door		ASB_0225_2	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	External siding	Unpainted walls and eaves same material		ASB_0225_3	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building A - Lab / Admin	External eaves	Unpainted walls and eaves same material		Same as ASB_0225	Not Detected	Eaves	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Kitchen - all walls	Sample taken on west wall		ASB_0225_4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Laundry - all walls			Same as ASB_0225_4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Dining / recreation			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Dining / recreation, partition wall	Painted blue, centre of room. Both sides of wall		Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Hallway for bedrooms			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Bunk room - West side, north end			Same as ASB_0225_4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Bunk room - West, centre			Same as ASB_0225_4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Bunk room - West side, south end			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Bunk room - East side, North end			Same as ASB_0225_4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Male bathroom			Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Male bathroom - partition walls	Toilets and shower cubicles		ASB_0225_5	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	Horn Island	7/29/2015	Building B - accommodation	Female bathroom			Same as ASB_0225 4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Female bathroom - partition walls	Toilets and shower cubicles		Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Vinyl tiles - hallway centre only	Grey colour		ASB_0225 6	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/29/2015	Building B - accommodation	Vinyl tiles - all building	Cream colour. Except for 3 of the dorms		ASB_0225 7	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/29/2015	Building B - accommodation	Shower base - male shower	Sample of damaged section, broken through to bathroom ceramic tiles		ASB_0225 8	Not Detected	Flooring Underlay	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Shower base - female shower			Same as ASB_0225 8	Not Detected	Flooring Underlay	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	External siding	Unpainted walls and eaves same material. Some damage.		ASB_0225 9	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	External eaves	Unpainted walls and eaves same material		Same as ASB_0225 9	Not Detected	Eaves	Fibre cement product
Remote	Horn Island	7/29/2015	Building B - accommodation	Underneath floor, debris	Various pieces. Found large piece in SE corner under female bathroom. Assume same material as walls by		Same as ASB_0225 9	Not Detected	Debris	Fibre cement product
Remote	Horn Island	7/29/2015	Building B1 - single accomm	External siding	Unpainted walls and eaves same material. Some damage.		Same as ASB_0225 9	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B1 - single accomm	External eaves	Unpainted walls and eaves same material		Same as ASB_0225 9	Not Detected	Eaves	Fibre cement product
Remote	Horn Island	7/29/2015	Building B1 - single accomm	Internal walls	Unpainted, same as external siding		Same as ASB_0225	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building B1 - single accomm	Ceiling	Unpainted, same as external siding		Same as ASB_0225 9	Not Detected	Ceiling	Fibre cement product
Remote	Horn Island	7/30/2015	Building C - house	Vinyl tiles - all building	Cream colour. Except for 3 of the dorms		ASB_0226 2	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/30/2015	Building C - house	Bathroom floor	Sample from pipe hole; can see underside of shower base, fibreglass		ASB_0226 3	Not Detected	Floor Covering	Fibre cement product
Remote	Horn Island	7/30/2015	Building C - house	External siding	Sample northwest corner in damaged area; Unpainted walls and eaves same		ASB_0226 4	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/30/2015	Building C - house	External eaves	Unpainted walls and eaves same material. Some damage.		Same as ASB_0226	Not Detected	Eaves	Fibre cement product
Remote	Horn Island	7/30/2015	Building C - house	Underneath floor, debris	Various pieces. Found piece East side under bathroom + sheets in northwest corner. Assume same material as walls		Same as ASB_0226 4	Not Detected	Debris	Fibre cement product
Remote	Horn Island	7/30/2015	Building C - house	Yard, debris	2 pieces East side under roof sheeting. Assume same material a under		Same as ASB_0226	Not Detected	Debris	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	Horn Island	7/30/2015	Building D - units	South unit - shower floor	Same as C block bathroom		Same as ASB_0226 4	Not Detected	Floor Covering	Fibre cement product
Remote	Horn Island	7/30/2015	Building D - units	South unit - vinyl tile floor	Same as C block		Same as ASB_0226 3	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/30/2015	Building D - units	North unit - shower floor	Same as C block bathroom		Same as ASB_0226	Not Detected	Floor Covering	Fibre cement product
Remote	Horn Island	7/30/2015	Building D - units	North unit - vinyl tile floor	Same as C block		Same as ASB_0226	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/30/2015	Building D - units	Laundry floor	Same as C block		Same as ASB_0226	Not Detected	Floor Covering	Vinyl tile
Remote	Horn Island	7/30/2015	Building D - units	External siding	Same as C block		Same as ASB_0226	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/30/2015	Building D - units	External eaves	Same as C block		Same as ASB_0226	Not Detected	Eaves	Fibre cement product
Remote	Horn Island	7/30/2015	Building E - garage	Store A & B - fascia	Brown paint		ASB_0226 5	Not Detected	Fascia	Fibre cement product
Remote	Horn Island	7/29/2015	Building F - flammable store	Internal walls	Unpainted, same as external		Same as ASB_0226 0	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building F - flammable store	Ceiling	Unpainted, same as external		Same as ASB_0226	Not Detected	Ceiling	Fibre cement product
Remote	Horn Island	7/29/2015	Building F - flammable store	External walls	Sample next to door		ASB_0226 0	Not Detected	Wall	Fibre cement product
Remote	Horn Island	7/29/2015	Building F - flammable store	Fascia	Unpainted, same as external		Same as ASB_0226	Not Detected	Fascia	Fibre cement product
Remote	Kirrama Research Hut	7/23/2015	External	Window Putty	Putty visually consistent on all windows. No other suspected items of ACM found. Structure is timber, no		ASB_0019 5	Not Detected	Window putty	Mastic
Remote	Orpheus Island,	7/22/2015	External	Northern Veranda Floor	Thick compressed fibre cement sheet. Confirmed by Abscan 2010.	1466/09-16		Not Detected	Floor	Fibre cement product
Remote	Orpheus Island,	7/22/2015	Food Storage	Floor panels at south side	Visible from underneath immediately west of walkway to toilets/showers		ASB_0017 8	Not Detected	Floor	Fibre cement product
Remote	Orpheus Island, Communal Building	7/22/2015	South East Corner Kitchen	Floor panels at SE corner	Thick compressed fibre cement sheet		ASB_0017 7	Not Detected	Floor	Fibre cement product
Remote	Orpheus Island,	7/22/2015	Subfloor	Packers to timber floor joists and debris on ground. Vinyl	Sampled from under southern food storage area.		ASB_0017 9	Not Detected	Packers and Debris	Vinyl tile
Remote	Orpheus Island, Dry Lab	7/22/2015	External	Walls	All external walls clad with wood grain pattered fibre cement weather boards. Confirmed by Abscan 2010.	1466/09-12		Not Detected	Wall	Fibre cement product
Remote	Orpheus Island, Dry	7/22/2015	External	Eave Soffits to South, East and West sides.	Re-sampled to confirm.	1466/09-19	ASB_0018 4	Not Detected	Eaves	Fibre cement product
Remote	Orpheus Island, Dry	7/22/2015	Floor	Fibre cement structural floor panels	Floor panels visually consistent throughout. Re-sampled to confirm.	1466/09-13	ASB_0018 3	Not Detected	Floor	Fibre cement product
Remote	Orpheus Island, Dry	7/22/2015	Internal Ceilings	All Rooms	All internal ceilings visually consistent. Confirmed by Abscan 2010.	1466/09-11		Not Detected	Ceiling	Fibre cement product
Remote	Orpheus Island, Dry	7/22/2015	Internal Walls	All Rooms	All internal walls visually consistent. Confirmed by Abscan 2010.	1466/09-10		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	Orpheus Island, Dry	7/22/2015	Sub Floor	Packers to timber Joists	Sampled at Southern side.		ASB_0018_2	Not Detected	Packer	Fibre cement product
Remote	Orpheus Island, Manager's	7/22/2015	Bathroom	NE wall, next to shower	Location of water damage, exposed joint. Cement sheet visually consistent with other internal wall sheeting.		ASB_0019_3	Not Detected	Wall	Fibre cement product
Remote	Orpheus Island, Manager's	7/22/2015	External, Eastern corner of Bathroom	External Wall Cladding	Wood grain patterned fibre cement vertical boards. Sampled by Abscan 2010, no asbestos detected. Re-	1466/09-07	ASB_0018_5	Not Detected	Wall	Fibre cement product
Remote	Orpheus Island, Manager's	7/22/2015	External, Front Veranda	Floor Panels	Thick fibre cement sheet floor panels	1466/09-06		Not Detected	Floor	Fibre cement product
Remote	Orpheus Island,	7/22/2015	External, landing to stairs to Rear Office/First Aid.	Floor	Thick fibre cement sheet floor panel		ASB_0018_6	Not Detected	Floor	Fibre cement product
Remote	Orpheus Island, Manager's	7/22/2015	Front Office	Ceiling	Taken as representative of all ceilings and eave soffits. Double skinned, polystyrene sandwich panels.	1466/09-09	ASB_0018_7	Not Detected	Ceiling	Fibre cement product
Remote	Orpheus Island,	7/22/2015	Front Office	Floor Covering, Under Modern Sheet Vinyl.			ASB_0018_8	Not Detected	Floor Covering	Vinyl sheet
Remote	Orpheus Island, Manager's Residence	7/22/2015	Front Office	South West Wall	Taken as representative of all walls in this room.		ASB_0018_9	Not Detected	Wall	Fibre cement product
Remote	Orpheus Island, Manager's	7/22/2015	Kitchen	Floor Covering, Under Modern Sheet Vinyl. Patterned vinyl with fibrous	Same material observed in other rooms.		ASB_0019_2	Not Detected	Floor Covering	Vinyl sheet
Remote	Orpheus Island,	7/22/2015	Laundry	Ceiling	Taken as representative of all ceilings and eave soffits. Double skinned,	1466/09-09	ASB_0019_4	Not Detected	Ceiling	Fibre cement product
Remote	Orpheus Island,	7/22/2015	Living Room	North West wall	sampled in Northern Corner, taken as representative of all walls in this room.		ASB_0019_1	Not Detected	Wall	Fibre cement product
Remote	Orpheus Island,	7/22/2015	Rear Office/First Aid Room & Store	Floor	Thick fibre cement sheet floor panel		ASB_0019_0	Not Detected	Floor	Fibre cement product
Remote	Paluma, 34 Mt Spec Rd	7/24/2015	House, Internal	Dining Room, wall cladding East and above French	Appears to be modern FC sheet		ASB_0019_7	Not Detected	Wall	Fibre cement product
Remote	Paluma, 34 Mt Spec Rd	7/24/2015	Lab/Station	Sub-Floor Area	Flat sheet debris		ASB_0019_9	Not Detected	Debris	Fibre cement product
Remote	Roxmere Station	7/19/2015	Class room	Floor	Vinyl		ASB_0151_0	Not Detected	Floor	Vinyl sheet
Remote	Roxmere Station	7/19/2015	Female Ablutions	Eastern toilet cubicle, eastern wall	Taken from Lino, same covering whole floor		ASB_0150_1	Not Detected	Floor Covering	Vinyl sheet
Remote	Roxmere Station	7/19/2015	Male Ablutions	Shower partition, south west	Beneath towel rail		ASB_0150_2	Not Detected	Wall	Fibre cement product
Remote	Roxmere Station	7/19/2015	Male Ablutions	Shower partition, north west	Beneath towel rail, west end		ASB_0150_3	Not Detected	Wall	Fibre cement product
Remote	Roxmere Station	7/19/2015	Male Ablutions	Shower partition, north east	Near floor west side		ASB_0150_4	Not Detected	Wall	Fibre cement product
Remote	Roxmere Station	7/19/2015	Ringer's house	West interior wall	Replaced with hardiflex in 1999		ASB_0150_9	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Remote	Roxmere Station	7/19/2015	Ringer's house	West interior ceiling	Replaced with hardiflex in 1999			Not Detected	Ceiling	Fibre cement product
Remote	Roxmere Station	7/19/2015	Storerooms	Floor	Vinyl tile		ASB_01511	Not Detected	Floor Covering	Vinyl tile
Remote	RV James Kirby	7/9/2015	Crew berth	Floor	Glued to steel floor		ASB_00518	Not Detected	Floor Covering	Vinyl sheet
Remote	RV James Kirby	7/9/2015	Scientist berth	Floor	Covering below carpet. Floating wood panelling floor. Same material as crew bunks		Same as ASB_00518	Not Detected	Floor Covering	Vinyl sheet
Remote	RV James Kirby	7/9/2015	Store room	Floor	Covering below carpet. Floating wood panelling floor. Same material as crew		Same as ASB_00518	Not Detected	Floor Covering	Vinyl sheet
Remote	RV James Kirby	7/9/2015	Store room	Spare parts dry store	1x partial roll of TBA oil jointing		ASB_00519	Not Detected	Gasket	Compressed Fibre Gasket
Remote	RV James Kirby	7/9/2015	Top wheelhouse deck	Exhaust riser on rear of wheelhouse	Captain believes it is original material. Uniform on both the primary and		ASB_00517	Not Detected	Insulation	Lagging (Friable)
Townsville	DA001	1/15/2015	000C	Wall	Infill adjacent to Rm 001	AT100712.05		Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	002	Walls		AT100712.02		Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	003	Air conditioning flange joint		AT100712.01		Not Detected	Gasket	Compressed Fibre Gasket
Townsville	DA001	1/14/2015	006	Ceiling			AG20150114/30	Not Detected	Ceiling	Textured Coating
Townsville	DA001	1/14/2015	012	Walls		AT100712.02		Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	012A	South wall			AG20150114/17	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	013	Wall cladding			AG20150114/21	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	013	Shelving	Fibre cement sheet cut into regular shape		AG20150114/22	Not Detected	Debris	Fibre cement product
Townsville	DA001	1/14/2015	014	Floor	Grey vinyl tile beneath carpet. Same as that observed in 015.			Not Detected	Floor Covering	Vinyl tile
Townsville	DA001	1/14/2015	015	Wall common with 016 and partitions			AG20150114/18	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	015	Walls, ceiling and boxing in of air conditioning ductwork			AG20150114/19	Not Detected	Wall	Low Density Fibre Board
Townsville	DA001	1/14/2015	015	Floor	Grey vinyl tile beneath carpet. Result confirmed by XRD.		AG20150114/23	Not Detected	Floor Covering	Vinyl tile
Townsville	DA001	1/14/2015	016	Walls		AT100712.04		Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	018	Wall cladding			AG20150114/24	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	018	Floor		AT100712.06		Not Detected	Floor Covering	Vinyl sheet

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA001	1/14/2015	018A	Wall cladding	Same as AG20150114/24			Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	018B	Wall cladding	Same as AG20150114/24			Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	019	Penetration infill panel			AG20150114/28	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	020	21/02/2015	Same as AG20150114/19			Not Detected	Wall	Low Density Fibre Board
Townsville	DA001	1/14/2015	021	Wall cladding	Same as AG20150114/19			Not Detected	Wall	Low Density Fibre Board
Townsville	DA001	1/14/2015	021	Wall cladding	West wall.		AG20140114/27	Not Detected	Wall	Low Density Fibre Board
Townsville	DA001	1/14/2015	022	Wall cladding	Same as AG20150114/19			Not Detected	Wall	Low Density Fibre Board
Townsville	DA001	1/14/2015	024	Shower recess		AT100712.07		Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	100C	Floor, outside 115	Red vinyl sheet with no backing		AG20150114/15	Not Detected	Floor Covering	Vinyl sheet
Townsville	DA001	1/13/2015	101	Ceiling	Brown grey suspended ceiling tile		AG20150113/6	Not Detected	Ceiling	Fibre cement product
Townsville	DA001	10/30/2015	103	Floor	Green vinyl sheet (modern) approx. 1 square meter.		ASB_00569	Not Detected	Floor Covering	Vinyl sheet
Townsville	DA001	1/14/2015	103A	Ceiling			AG20150114/12	Not Detected	Ceiling	Textured Coating
Townsville	DA001	1/13/2015	104	Floor	Green vinyl tile beneath carpet. Same as AG20150113/5.			Not Detected	Floor Covering	Vinyl tile
Townsville	DA001	1/13/2015	104A	Floor	Green vinyl beneath blue vinyl beneath carpet.		AG20150113/5	Not Detected	Floor Covering	Vinyl tile
Townsville	DA001	1/13/2015	106	Floor	Green vinyl tile beneath carpet. Same as AG20150113/5.			Not Detected	Floor Covering	Vinyl tile
Townsville	DA001	1/13/2015	118	Walls		AT100712.08		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA001	1/14/2015	119B	Ceiling			AG201501 14/14	Not Detected	Ceiling	Textured Coating
Townsville	DA001	1/14/2015	120	Ceiling			AG201501 14/16	Not Detected	Ceiling	Textured Coating
Townsville	DA001	1/14/2015	128B	Partition wall, left hand side of doorway			AG201501 14/11	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/13/2015	202A	Floor level	Fibrous insulation to penetrations and also as debris on the floor.		AG201501 13/4	Not Detected	Insulation	Loose Fibre
Townsville	DA001	1/13/2015	320	Wall cladding	Sampled from roof space above.		AG201501 13/9	Not Detected	Wall	Fibre cement product
Townsville	DA001	1/14/2015	Foyer, main entrance	Packing finish under cornice near entrance	Appears to be ceiling spray coat applied to the glass bricks		AG201501 14/10	Not Detected	Ceiling	Textured Coating
Townsville	DA001	1/13/2015	Roof space	Underside of copper roofing and debris	Original roof sarking		AG201501 13/8	Not Detected	Insulation	Loose Fibre
Townsville	DA001	1/14/2015	Stairwell adjacent to 011	Underside of stairs			AG201501 14/31	Not Detected	Ceiling	Textured Coating
Townsville	DA001	1/12/2015	Stairwell adjacent to 217	Underside of stairs			AG201501 12/3	Not Detected	Ceiling	Textured Coating
Townsville	DA002	1/9/2015	0 C001	Infill panels	Used on west wall		AG201501 09/12	Not Detected	Wall	Fibre cement product
Townsville	DA002	1/16/2015	001	Ceiling			ASB_0025 6	Not Detected	Sprayed Coating	Textured Coating
Townsville	DA002	1/9/2015	003	Floor	Cream vinyl sheet beneath blue vinyl sheet		AG201501 09/5	Not Detected	Floor	Vinyl sheet
Townsville	DA002	1/8/2015	010	Ceiling			AG201501 08/3	Not Detected	Sprayed Coating	Textured Coating
Townsville	DA002	1/16/2015	1st floor C101	Suspended ceiling panels	White fibrous under layer of glass wool panels		AG201501 16/8	Not Detected	Ceiling	Low Density Fibre Board
Townsville	DA002	1/9/2015	EXTERNAL	Ceiling, Level 1 entrances	Present to both north and south entrances	AT100712 .15		Not Detected	Ceiling	Fibre cement product
Townsville	DA003	2/5/2015	001 Lecture Theatre	Floor Area in front of stage	Fibre cement sheeting		ASB_0028 2	Not Detected	Floor	Fibre cement product
Townsville	DA003	2/9/2015	001 Lecture Theatre	Front stage area floor under carpet	300mm x 300mm green vinyl square tiles laid on cream vinyl (unable to confirm if sheet or tile)		ASB_0028 4	Not Detected	Floor	Vinyl tile
Townsville	DA003	2/9/2015	001B Projector Room	Ceiling	Fibre cement sheeting indicates on old report that old sheeting had been replaced		ASB_0028 3	Not Detected	Ceiling	Fibre cement product
Townsville	DA003	2/4/2015	102	Wall sections on East and west wall	Fibre cement sheeting		ASB_0028 0	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA003	2/3/2015	103	Small infill wall section between block work	Fibre cement sheeting		ASB_00274	Not Detected	Wall	Fibre cement product
Townsville	DA003	2/4/2015	104	Infill under window	Fibre cement sheeting representative sample taken room 105 [ASB_00278]			Not Detected	Wall	Fibre cement product
Townsville	DA003	2/4/2015	105	Ceiling	Textured finish representative sample taken in 206A [ASB_00314]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	2/4/2015	105	Wall near entrance way	Fibre cement sheeting		ASB_00277	Not Detected	Wall	Fibre cement product
Townsville	DA003	2/4/2015	105	Infill under window (next to doorway)	Fibre cement sheeting (painted Blue)		ASB_00278	Not Detected	Wall	Fibre cement product
Townsville	DA003	2/4/2015	105	Infill under window	Fibre cement sheeting (painted white) sampled from behind black plastic skirting.		ASB_00279	Not Detected	Wall	Fibre cement product
Townsville	DA003	2/3/2015	109	Infill panel under beam	Fibre cement sheeting		ASB_00272	Not Detected	Wall	Fibre cement product
Townsville	DA003	2/3/2015	109	Ceiling	Fibre cement sheeting		ASB_00273	Not Detected	Ceiling	Fibre cement product
Townsville	DA003	2/4/2015	113	Ceiling	Textured finish representative sample taken in 206A [ASB_00314]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	2/2/2015	202A, 202B, 202C	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected		
Townsville	DA003	2/24/2015	203A	Roof space	Vermiculite sprayed on concrete above suspended ceiling representative sample [ASB_00314] taken in 206A.			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	1/21/2015	203A & 204	North wall	Infill under windows		ASB_00262	Not Detected	Walls	Fibre cement product
Townsville	DA003	1/21/2015	203A & 204	Ceiling space	Sprayed on product. Representative sample already taken from rm 302 [ASB_00258]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	1/21/2015	206, 206A	Floor under floor covering	black adhesive, previously sampled in room 103, Not detected.			Not Detected	Floor	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA003	2/23/2015	206A	ceiling space	Coating sprayed to underside of concrete slab along northern side of		ASB_00314	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	2/24/2015	210	Roof space	Vermiculite sprayed on concrete above suspended ceiling representative			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	1/21/2015	211	Lower window infills	Cement sheeting		ASB_00264	Not Detected	Walls	Fibre cement product
Townsville	DA003	2/2/2015	213	Floor under carpet	Carpet on floor levelling compound		ASB_00268	Not Detected	Floor	
Townsville	DA003	1/21/2015	213	Wall	Cement sheet		ASB_00265	Not Detected	Walls	Fibre cement product
Townsville	DA003	1/21/2015	213 & 214	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected		
Townsville	DA003	1/21/2015	213, 214, 215, 216, 219	Walls	Cement sheet. JTA [AT110712.11] No asbestos detected. Location of JTA sample not indicated. Representative sample taken in 213 [ASB_00265]			Not Detected		
Townsville	DA003	2/2/2015	214	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected		
Townsville	DA003	2/2/2015	215	Lower window infills	Cement sheeting - representative sample taken in room 211 [ASB_00264]			Not Detected	Cladding	
Townsville	DA003	2/3/2015	219	Lower window infills	Cement sheeting - representative sample taken in room 211			Not Detected		
Townsville	DA003	2/3/2015	220	Lower window infills	Cement sheeting - representative sample taken in room 211	AT060812.50		Not Detected		
Townsville	DA003	2/3/2015	2nd floor Corridor (C201). Western Section from Rm 220 to Stairway S202.	Floor covering	Carpet laid on cream sheet vinyl from rm 220 to Western Stairs. Representative sample taken outside room 220.		ASB_00270	Not Detected	Floor	Vinyl sheet
Townsville	DA003	2/13/2015	301 External Roof	Top of building above 301 Plant Room.	Waterproofing membrane over concrete slab		ASB_00300	Not Detected	Water Proofing	Bituminous product
Townsville	DA003	2/23/2015	301 Plant Room	Inside ventilation duct from AHU 4	Original section of duct below plant room floor level, brown fibrous		ASB_00317	Not Detected	Insulation	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA003	2/23/2015	301 Plant Room	Inside ventilation duct from AHU 4	Duct elbow leading into service riser below plant room floor, woven cover over glass wool insulation lining		ASB_00318	Not Detected	Insulation	
Townsville	DA003	2/23/2015	301 Plant Room	Inside ventilation duct from AHU 4	Impacted dust sampled from duct elbow blades, elbow leading down into service riser below plant room floor.		ASB_00319	Not Detected	Dust	
Townsville	DA003	1/21/2015	302	Ceiling	Sprayed textured finish		ASB_00258	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA003	1/21/2015	302	Aircon unit surround	Fibre cement sheeting		ASB_00259	Not Detected	Walls	Fibre cement product
Townsville	DA003	2/13/2015	B001 Basement Plant Room	Ventilation plant	Flexible joints - original joints on all plant external and internal - 4 air con		ASB_00299	Not Detected		Woven fibre
Townsville	DA003	1/21/2015	Eastern Stairwell	Floor covering	Vinyl sheet, blue grey in colour		ASB_00260	Not Detected	Flooring	Vinyl sheet
Townsville	DA003	2/13/2015	HVAC System	HVAC system was inspected for ACM Heater Banks and	No heater banks or ACM fire dampers found. Review of old mechanical plans			Not Detected		
Townsville	DA003	1/21/2015	Western Stairwell	Floor covering	Vinyl sheet, blue grey in colour, consistent with vinyl in eastern stairwell. Representative sample			Not Detected	Flooring	Vinyl sheet
Townsville	DA004	1/20/2015	031	Floor under first layer of vinyl sheet	Grey sheet vinyl		ASB_00251	Not Detected	Flooring	Vinyl sheet
Townsville	DA004	1/20/2015	0 ground floor C002	Adjacent room 029	Vinyl sheet - blue		ASB_00252	Not Detected	Flooring	Vinyl sheet
Townsville	DA004	3/23/2015	0 Ground level	Ceiling area under walkway	Cement sheeting - previous sample taken opposite room 32	AT170712.02	ASB_00388	Not Detected	Ceiling	Fibre cement product
Townsville	DA004	3/23/2015	0 Ground level	External	Window infill - adjacent Room 033B	AT170712.03		Not Detected		
Townsville	DA004	3/23/2015	004	Collections room	Heater bank lining		ASB_00387	Not Detected	Insulation	Millboard
Townsville	DA004	1/19/2015	029	Walls	Cement sheet	AT170712.06		Not Detected		
Townsville	DA004	1/19/2015	032	Ceiling	cement sheet tiles. Taken as representative of ceilings in rooms 042	AT170712.05		Not Detected		
Townsville	DA004	1/19/2015	033	Room 033, air-conditioning ducting	Flange Joints	AT170712.11		Not Detected		
Townsville	DA004	2/19/2015	034 Lift Motor Room	Fire door	Internal core of door. Sampled from handle penetration.		ASB_00085	Not Detected	Fire door	Insulation
Townsville	DA004	2/19/2015	034 Lift Motor Room	Electrical backing board		AT170712.04		Not Detected		
Townsville	DA004	1/19/2015	037	Partitions	Cement sheet. No asbestos detected. Sample taken in Room 037.	AT170712.07		Not Detected		
Townsville	DA004	1/20/2015	042	Packer underneath HWS			ASB_00254	Not Detected	Packer	Fibre cement product
Townsville	DA004	1/20/2015	042	Gaskets	black wrap seal round release valves		ASB_00253	Not Detected	Pipe insulation	Bituminous product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA004	1/16/2015	116	Lab sink	Black bituminous material under sink. Taken to be representative of similar		CH201501 16/18	Not Detected	Insulation	Bituminous product
Townsville	DA004	1/16/2015	116	Small tank base	Fibre cement product		CH201501 16/17	Not Detected	Packer	Fibre cement product
Townsville	DA004	1/19/2015	116	Ducting	Ducting adjacent fume cupboard, mastic round duct. This is		CH201501 16/19	Not Detected	Caulking compound	Mastic
Townsville	DA004	1/19/2015	116A off corridor	Service Cupboard	Cement sheeting placed behind cable rack going up wall		CH201501 16/21	Not Detected	Cladding	Fibre cement product
Townsville	DA004	1/19/2015	117	electrical cabinet floor	Vermiculite material	AT170712 .09		Not Detected		
Townsville	DA004	1/19/2015	121	Walls	Cement sheet. No asbestos detected.	AT170712 .08		Not Detected		
Townsville	DA004	1/19/2015	121	Shower	Cement sheeting behind shower		CH201501 16/20	Not Detected	Walls	Fibre cement product
Townsville	DA004	1/19/2015	142	Floor	Sheet vinyl floor		CH201501 16/22	Not Detected	Flooring	Vinyl sheet
Townsville	DA004	3/23/2015	1st Level	AHU1.2 In duct heater bank	Heater bank. Inspected internally, material visually identical to lining in			Not Detected	Insulation	Millboard
Townsville	DA004	1/15/2015	244	Partitions	Compressed cement sheet. Taken as representative of partitions in 122.		CH201501 14/11	Not Detected	Walls	Fibre cement product
Townsville	DA004	1/15/2015	244	Ceiling	Cement sheeting panel. Taken as representative of ceiling in room 122.	AT170712 .10	CH201501 14/12	Not Detected	Ceiling	Fibre cement product
Townsville	DA004	1/15/2015	244	Floor jointing	Jointing compound		CH201501 14/14	Not Detected	Caulking compound	Mastic
Townsville	DA004	1/15/2015	260	jointing compound	CH 260 - jointing compound between block work and concrete columns		CH201501 15/6	Not Detected	Caulking compound	Mastic
Townsville	DA004	1/15/2015	260	Ceiling	Ceiling panels		CH201501 15/5	Not Detected	Suspended ceiling	
Townsville	DA004	1/14/2015	261	Walls	Blockwork, concrete, plaster, laminated particle board - (CH 261 only, rooms 261 A&B walls consist of carpet glued to walls which appear to be fibrous		CH201501 14/1	Not Detected	Wall	Fibre cement product
Townsville	DA004	1/14/2015	261	Ceiling	Ceilings in 261 A&B are a sound proof product which are glued in position		CH201501 14/2	Not Detected	Ceiling	Fibre cement product
Townsville	DA004	1/15/2015	261	Ceiling	Cement sheeting panel		CH201501 15/4	Not Detected	Ceiling	Fibre cement product
Townsville	DA004	1/15/2015	261 to 262	Floor	Sheet vinyl light green speckle		CH201501 15/10	Not Detected	Flooring	Vinyl sheet
Townsville	DA004	1/15/2015	262 & 262A	Floor covering	Non-asbestos vinyl sheet. No backing layer. CH green sheet vinyl		CH201501 15/7	Not Detected	Flooring	Vinyl sheet
Townsville	DA004	1/15/2015	266B	Window sill	Jointing compound		CH201501 15/8	Not Detected	Caulking compound	Mastic
Townsville	DA004	3/27/2015	2nd Level	AHU 2-12	In duct heater bank		ASB_0043 0	Not Detected	Insulation	Millboard
Townsville	DA004	3/27/2015	2nd Level	AHU 2-12	In duct heater bank		ASB_0043 1	Not Detected	Insulation	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA004	1/20/2015	External	Infill panels over windows - adjacent Room 032	Cement sheet. No asbestos detected.	AT170712.01		Not Detected		
Townsville	DA004	1/20/2015	External	Eaves lining	Sampled by Abscan in 2007.	285/07.DA004-11		Not Detected	Eaves	Fibre cement product
Townsville	DA004	1/20/2015	External	Fascia	Sampled by Abscan in 2007.	285/07.DA004-10		Not Detected	Fascia	Fibre cement product
Townsville	DA004	1/20/2015	External	Potential Flue Pipe	Previous Survey by JTA noted an external flue pipe that was assumed to			Not Detected		
Townsville	DA004	1/16/2015	Level 3 Roof space	Underside of roof	Plaster joint round fire seal		CH20150116/15	Not Detected	Sprayed fire rating/insulation	Insulation
Townsville	DA004	1/15/2015	Telecom Cupboard Adjacent to Room 222 &	Floor	Infill in concrete floor		CH20150115/9	Not Detected	Flooring	Vermiculite
Townsville	DA005	3/19/2015	002 Storeroom	Floor	Tile Adhesive		ASB_00106B	Not Detected	Floor Covering	
Townsville	DA005	3/20/2015	External East side, C000	Facia to front awning	Appears to be new material		ASB_00108	Not Detected	Cladding	Fibre cement product
Townsville	DA005	3/20/2015	External East Side, covered walkway between main building and toilet block.	Facias to awning including at garden/ courtyard	Appears to be new material. Visually identical to sample ASB_00108			Not Detected		
Townsville	DA005	3/19/2015	Undercroft below 001	Doorway in northern end of west wall	Fibre cement cladding as doorway infill		ASB_00107	Not Detected	Wall	Fibre cement product
Townsville	DA006	2/3/2015	001	Infill panels above servery		AT120712.03		Not Detected	Infill	Fibre cement product
Townsville	DA006	7/17/2017	001	Central partition	Previously sampled by JTA	AT120712.05		Not Detected	Wall	Fibre cement product
Townsville	DA006	2/3/2015	007	Panelling	Infill panel to range hood. Same as ASB_00038			Not Detected	Cladding	Fibre cement product
Townsville	DA006	2/3/2015	008	Infill panels above refrigerators/cool room		See AT120712.03		Not Detected	Infill	Fibre cement product
Townsville	DA006	2/3/2015	008	Infill panels above servery		AT120712.03		Not Detected	Infill	Fibre cement product
Townsville	DA006	2/3/2015	009	Walls		AT120712.07		Not Detected	Wall	Fibre cement product
Townsville	DA006	7/17/2017	001	Infill panels above eastern (main) entrance	Not sampled previously		ASB_00031	Not Detected	Infill	Fibre cement product
Townsville	DA006	7/18/2017	011	East wall, southern end	Cream painted sheeting		ASB_00033	Not Detected	Wall	Fibre cement product
Townsville	DA006	2/2/2015	External	Expansion Joints	Expansion joint. 2 locations on South wall, 1 on the west wall. 3 linear metres each. Sampled at South Wall.		ASB_00034	Not Detected	Sealant	Mastic
Townsville	DA006	2/3/2015	012	Ceiling	Sample taken from southern half. Northern half is MDF tile		ASB_00035	Not Detected	Ceiling	Fibre cement product
Townsville	DA006	2/3/2015	012	Wall	One sheet to South west corner. Different to other sheeting		ASB_00037	Not Detected	Wall	Fibre cement product
Townsville	DA006	7/18/2017	007	Panelling	Panelling to air conditioning bulkhead at rear of kitchen area		ASB_00038	Not Detected	Cladding	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA006	7/17/2017	001	Expansion joint under running North-south (directly			ASB_03049	Not Detected	Sealant	Bituminous product
Townsville	DA006	7/17/2017	001	1x hole in slab 1200mm Nth of central partition wall	Hole approx 20mm in slab with black resin filling the hole		ASB_03050	Not Detected	Sealant	Bituminous product
Townsville	DA006	7/17/2017	01	Adhesive layer throughout, above expansion joints in slab and beneath sheet vinyl.	Black adhesive <5mm thick. Adhered to sheet vinyl. Qty is an estimate as could be under ceramic tiles.		ASB_03051	Not Detected	Sealant	Mastic
Townsville	DA006	7/17/2017	01	Sealant at boarder of ceramic tiles and sheet vinyl (west end of room).	Grey material along channel		ASB_03052	Not Detected	Sealant	Mastic
Townsville	DA006	7/18/2017	External (west aspect)	External to 009 cold room			ASB_03053	Not Detected	Wall	Fibre cement product
Townsville	DA006	7/18/2017	External (East aspect)	Infill panels above East entry doors to 001			ASB_03054	Not Detected	Infill	Fibre cement product
Townsville	DA007	2/10/2015	External	Infill beside air conditioner southern wall	Cement sheeting		ASB_00288	Not Detected	Cladding	Fibre cement product
Townsville	DA007	2/11/2015	External & internal	Soffit lining and ceiling lining	Plywood with a layer of wood type material bonded on thin paper like		ASB_00291	Not Detected	Eaves	
Townsville	DA007	2/10/2015	Internal	Infill beside air conditioner - different thickness sheeting	Cement sheeting		ASB_00289	Not Detected	Cladding	Fibre cement product
Townsville	DA008	2/5/2015	001	South wall	Air conditioning unit on the other (external) side of the wall. Same			Not Detected	Wall	Fibre cement product
Townsville	DA008	2/5/2015	External	Gable end infill sheets. South end of building, West side.	Material appears to be not original. Likely installed at same time as		ASB_00044	Not Detected	Cladding	Fibre cement product
Townsville	DA008	2/5/2015	External	Expansion joint	Previously sampled	AT110712.20		Not Detected	Sealant	Bituminous product
Townsville	DA008	2/5/2015	Internal	Ceiling space	Suspended plasterboard ceiling. No manhole. Inspected ceiling space in			Not Detected		
Townsville	DA009	2/5/2015	000C (entry corridor)	Ceiling space	Removed 2 plaster ceiling panels to inspect for presence of heater banks.			Not Detected		
Townsville	DA009	2/5/2015	001	Ceiling space	Removed 6 plaster ceiling panels to inspect for presence of heater banks. None observed.			Not Detected		
Townsville	DA009	2/5/2015	002	Ceiling space	Removed 6 plaster ceiling panels to inspect for presence of heater banks.			Not Detected		
Townsville	DA009	2/5/2015	006	Ceiling space	Removed 4 plaster ceiling panels to inspect for presence of heater banks. None observed.			Not Detected		
Townsville	DA009	2/5/2015	014	Door	No fibre cement lining to door as previously observed by JTA. Removed latch and inspected cross section of			Not Detected	Door	
Townsville	DA010	2/5/2015	External	Eaves	Visual assessment confirms previous analysis of fibre cement. Plastic strips	AT120712.15		Not Detected	Eaves	Fibre cement product
Townsville	DA010	2/5/2015	External	North wall	Mastic to expansion joint		ASB_00045	Not Detected	Sealant	Mastic
Townsville	DA018	3/24/2015	0 Ground Floor	Ceilings in stage 1 and 2	Sprayed Vermiculite suspected above new plaster ceilings. Material visually			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018		0 Ground Floor. Passageway to Teaching	Walls	Item sampled by JTA 17/07/2012	AT170712.23		Not Detected	Cladding	Fibre cement product
Townsville	DA018	3/24/2015	029 Closed Compactus	Ceiling	Sprayed coating. White powdery material (not vermiculite) Coated with paint. Also found in other rooms		ASB_00126	Not Detected	Ceiling	Textured Coating
Townsville	DA018		041	Walls	Item sampled by JTA 17/07/2012	AT170712.22		Not Detected	Cladding	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA018		063	External wall	Item sampled by JTA 17/07/2012	AT170712.21		Not Detected	Cladding	Fibre cement product
Townsville	DA018	3/22/2015	103 (including A to G)	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	105 & 105A	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	107 "Ladies" Toilet (stage 1)	South and East walls with bent metal batons on	Sample from South wall. Only fibre cement walls in this room. Other walls		ASB_0012_2	Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	108 "Gentlemen" Toilet (stage 1)	North and East walls with bent metal batons on	Sample from North wall. Only fibre cement walls in this room. Other walls		ASB_0012_1	Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	110	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	111 office	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	112 plant room	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	113 male toilet	North and West walls with bent metal battens onto cast	Walls and cladding appear to be a later addition.		ASB_0011_6	Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	114 female toilet	South and West walls with bent metal battens onto cast concrete.	Walls and cladding appear to be a later addition.		ASB_0011_7	Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	115 (stage 1)	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018		120	HVAC Flange Joints	Item sampled by JTA 17/07/2012	AT170712.28		Not Detected	Sealant	Mastic
Townsville	DA018	3/22/2015	1st Level, central stairs (stage 1)	Ceiling at western side of stairs	Sprayed coating, darker shade than Stage 2 side.		ASB_0012_0	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	1st Level, data rack room East of fire stairs.	Ceiling	Same as library. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	1st Level, eastern end (stage 2)	Ceiling, sampled above southern duct above book	Sprayed coating.		ASB_0011_9	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018		1st Level, Library	Floor under floor covering, middle stripe section of floor	Item sampled by JTA 17/07/2012	AT170712.27		Not Detected	Floor	Fibre cement product
Townsville	DA018	3/20/2015	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately south of Toilet	Wiring to heater bank elements. White woven wire insulation. Wiring is		ASB_0011_1	Not Detected	Wire Insulation	Woven fibre
Townsville	DA018	3/20/2015	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately south of Toilet	Wiring to heater bank elements. Brown woven wire insulation. Wiring is		ASB_0011_2	Not Detected	Wire Insulation	Woven fibre
Townsville	DA018	3/20/2015	1st Level, Library, Eastern end (Stage 2)	Ceiling immediately south of Toilet 114	Thick sprayed vermiculite coating on underside of slab.		ASB_0011_3	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/20/2015	1st Level, Library, Eastern end (Stage 2)	HVAC duct immediately North of Fire Stairs & Toilets	Flange sealant/mastic. Grey flexible mastic, appears to contain fibre.		ASB_0011_5	Not Detected	Sealant	Mastic
Townsville	DA018	3/20/2015	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately North of Fire	Wiring to heater bank elements. White woven wire insulation. Wiring is			Not Detected	Wire Insulation	Woven fibre

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DA018	3/20/2015	1st Level, Library, Eastern end (Stage 2)	Heater Bank in HVAC duct immediately North of Fire Stairs & Toilets. Location	Wiring to heater bank elements. Brown woven wire insulation. Wiring is redundant. Same as ASB_00112			Not Detected	Wire Insulation	Woven fibre
Townsville	DA018	3/22/2015	210 "Ladies" Toilet (stage 1)	South and East walls with bent metal batons on concrete.	Only fibre cement walls in this room. As for ASB_00121 & ASB_00122. Other walls are clad with timber boards			Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	210 "Ladies" Toilet (stage 1)	Ceiling	Same as level 1 sprayed coating. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	211 "Gentlemen" Toilet (stage 1)	Ceiling	Same as level 1 sprayed coating. see [ASB_00119 & ASB_00120]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	211 "Gentlemen" Toilet (stage 1)	North and East walls with bent metal batons on	Only fibre cement walls in this room. As for ASB_00121 & ASB_00122. Other			Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	226 gentlemen toilet	North and West walls with bent metal battens onto cast	Walls and cladding appear to be a later addition. Visually identical material to			Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	227 ladies toilet	South and West walls with bent metal battens onto cast concrete.	Walls and cladding appear to be a later addition. Visually identical material to ASB_00117.			Not Detected	Wall	Fibre cement product
Townsville	DA018	3/22/2015	2nd Level, Central Stairs, Stage 1 west of stairs	Ceiling	Tan coloured vermiculite sprayed coating on compressed straw ceiling panels		ASB_0012_4	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018	3/22/2015	2nd Level, near Central Stairs, Stage 2 East of stairs	Ceiling	Brown wood shaving and vermiculite sprayed coating on compressed straw ceiling panels. Throughout Stage 2		ASB_0012_5	Not Detected	Sprayed Coating	Vermiculite
Townsville	DA018		Entrance way to Room A006	Ceiling to alcove	Item sampled by JTA 17/07/2012	AT170712.20		Not Detected	Sprayed Coating	Textured Coating
Townsville	DA018		External. Lower south wall	Window shade panels	Item sampled by JTA 17/07/2012	AT170712.25		Not Detected	Shade Panels	Fibre cement product
Townsville	DA018		External. South wall.	window shade and upper panel over central entrance	Item sampled by JTA 17/07/2012	AT170712.24		Not Detected	Cladding	Fibre cement product
Townsville	DA018		External. Upper south wall	Window shade panels	Item sampled by JTA 17/07/2012	AT170712.26		Not Detected	Shade Panels	Fibre cement product
Townsville	DA018	3/25/2015	Roof Space, Eastern End (Stage 2)	Decommissioned heater banks have wire insulation				Not Detected		
Townsville	DA018	3/25/2015	Roof Space, Eastern End (Stage 2)	Heater banks (decommissioned) Six (6) Locations as shown on	Location of previous heater banks inspected internally. Heater elements and insulation lining no longer in place,			Not Detected	Heater Bank	
Townsville	DA018	3/24/2015	Roof Space, Western End (Stage 1)	Heater bank (decommissioned) in central	Location of previous heater bank inspected internally. Heater elements			Not Detected	Heater Bank	
Townsville	DA018	3/25/2015	Roof Space, Western End (Stage 1)	Heater bank (decommissioned) in duct heading North from main	Location of previous heater bank inspected internally. Heater elements and insulation lining no longer in place,			Not Detected	Heater Bank	
Townsville	DA018	3/25/2015	Roof Space, Western End (Stage 1)	Heater bank (decommissioned) at South side of concrete slab in duct	Location of previous heater bank inspected internally. Heater elements and insulation lining no longer in place,			Not Detected	Heater Bank	
Townsville	DB017	3/17/2015	022	Pipe work	Lagging representative sample taken in room 122 [ASB_00367]			Not Detected	Insulation	Woven fibre
Townsville	DB017	3/16/2015	028	Ceiling	Sprayed texture finish on concrete		ASB_0037_2	Not Detected	Sprayed Coating	Vermiculite
Townsville	DB017	3/16/2015	028A	Floor	Clear/Amber adhesive, Carpet glued over - appears to be remnant vinyl in corners of room and black glue under		ASB_0037_3	Not Detected	Adhesive	Adhesive

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB017	3/16/2015	028B	Floor	Amber adhesive. Carpet glued to concrete - appears to be remnant vinyl		ASB_0037 1	Not Detected	Adhesive	
Townsville	DB017	3/17/2015	038C	Wall	2 x small Infill sections on west wall		ASB_0037 5	Not Detected	Cladding	Fibre cement product
Townsville	DB017	3/17/2015	038D	Wall	1 small Infill sections on west wall - representative sample taken 38C [ASB_00375]			Not Detected	Cladding	Fibre cement product
Townsville	DB017	3/23/2015	040A	Walls	Infill round door cement sheeting representative sample taken 040D [ASB_00390]			Not Detected	Wall	Fibre cement product
Townsville	DB017	3/23/2015	040A	Fascia	Cement sheeting 9mm sheeting representative sample taken in			Not Detected	Fascia	Fibre cement product
Townsville	DB017	3/23/2015	040A	Windows South face	Jointing compound round all windows		ASB_0039 2	Not Detected	Sealant	Mastic
Townsville	DB017	3/23/2015	040C	Floor	Sheet vinyl on concrete		ASB_0038 9	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB017	3/23/2015	040D	Columns	Formwork representative sample taken North wing west face [ASB_00393]			Not Detected	Formwork	Fibre cement product
Townsville	DB017	3/23/2015	040D	Walls	Cement sheeting		ASB_0039 0	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/17/2015	047	East wall	Fibre cement sheeting - representative sample taken in 048 [ASB_00374]	AT180712 .40		Not Detected	Wall	
Townsville	DB017	3/17/2015	047A	West & East wall	Fibre cement sheeting - representative sample taken in 048 [ASB_00374]			Not Detected	Wall	Fibre cement product
Townsville	DB017	3/17/2015	048	West wall	Fibre cement sheeting		ASB_0037 4	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/17/2015	052	Roof Space	Inspected, no signs of remnant ACM.			Not Detected	NA	
Townsville	DB017	3/18/2015	060 plant room	Ceiling	Sprayed texture finish		ASB_0038 4	Not Detected	Sprayed Coating	Vermiculite
Townsville	DB017	3/18/2015	068	Roof Space	Suspended ceiling - steel roof structure above no signs of ACM			Not Detected	NA	
Townsville	DB017	3/18/2015	069	Roof Space	Suspended ceiling - steel roof structure above no signs of ACM			Not Detected	NA	
Townsville	DB017	3/18/2015	071	Roof Space	Suspended ceiling - steel roof frame above no sign of ACM			Not Detected	NA	
Townsville	DB017	3/18/2015	071	Walls	Fibre board fixed to Plasterboard which is then fixed to fibre cement sheeting South west Cnr.. near air return vent		ASB_0038 2	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/18/2015	071A	Floor	Cream vinyl tiles (black adhesive under tiles assumed to contain asbestos.	AT180712 .37		Not Detected	Floor Covering	Vinyl tile
Townsville	DB017	3/18/2015	071A	Ceiling	Cement sheeting - sampled previously in 077A	See AT180712		Not Detected	Ceiling	
Townsville	DB017	3/18/2015	071A	Walls	Cement sheeting	See AT180712		Not Detected	Wall	
Townsville	DB017	3/18/2015	071B	Ceiling	Cement sheeting	See AT180712		Not Detected	Ceiling	
Townsville	DB017	3/18/2015	071B	Walls	Cement sheeting - sampled previously in 077A	See AT180712 .36		Not Detected	Wall	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB017	3/18/2015	077A	Walls	Cement sheeting	AT180712.36		Not Detected	Wall	
Townsville	DB017	3/17/2015	078	Walls	Cement sheeting	AT180712.32		Not Detected	Wall	
Townsville	DB017	3/17/2015	078A	Walls internal lining	Cement sheeting		ASB_00378	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/17/2015	078A	Walls external lining	Cement sheeting		ASB_00379	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/4/2015	101 lecture room	Top section of all walls and ceiling	Sprayed textured finish		ASB_00355	Not Detected	Sprayed Coating	Vermiculite
Townsville	DB017	3/5/2015	121	Ceiling	Old duct with black jointing material - sample taken room 247 [ASB_00331]			Not Detected	Sealant	Bituminous product
Townsville	DB017	3/5/2015	122	Water pipe	Wrapped with insulation material		ASB_00367	Not Detected	Pipe Lagging	Woven fibre
Townsville	DB017	3/4/2015	128	Roof space through suspended plasterboard	Inspected, safety mesh, modern insulation, no signs of ACM			Not Detected	NA	
Townsville	DB017	3/4/2015	129C	Eastern wall	Infill section		ASB_00357	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/4/2015	131	Walls	Infill above windows		ASB_00358	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/4/2015	139 & 138	Roof space through suspended plasterboard	Inspected, safety mesh, modern insulation, no signs of remnant ACM			Not Detected	NA	
Townsville	DB017	3/5/2015	164A	Wall - northern side	Fibre cement sheeting - previously sampled	AT180712.42		Not Detected	Wall	
Townsville	DB017	3/5/2015	165	Wall - southern side	Fibre cement sheeting - previously sampled room 164A	See AT180712		Not Detected	Wall	
Townsville	DB017	3/5/2015	1st floor S102	Walkway from bldg. 017 to bldg. 34 - southern side wall	Cement sheeting same as under window ledge sample [ASB_00362]			Not Detected	Wall	Fibre cement product
Townsville	DB017	2/25/2015	201 lecture room	Roof space	Inspected for remnant ACM, no suspect material found. Steel structure			Not Detected	NA	
Townsville	DB017	3/3/2015	220	Near emergency exit door S205	Mastic against door frame		ASB_00348	Not Detected	Sealant	Mastic
Townsville	DB017	3/3/2015	220	Roof space	Inspected for remnant ACM. Viewed safety mesh, modern insulation, box gutter, no signs of remnant limpet or			Not Detected	NA	
Townsville	DB017	3/3/2015	221	Roof space	Inspected for remnant ACM. Viewed safety mesh, modern insulation, no			Not Detected	NA	
Townsville	DB017	3/3/2015	225	Floor	Sheet vinyl on concrete kitchen area		ASB_00351	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB017	2/26/2015	247	Southern wall Plant room	Old duct with black jointing material		ASB_00331	Not Detected	Sealant	Mastic
Townsville	DB017	2/26/2015	247	Floor Various locations	Jointing mastic attached to floor grey in colour		ASB_00334	Not Detected	Sealant	Mastic
Townsville	DB017	2/26/2015	247	Floor Various locations	Amber adhesive coating on floor hard brittle product		ASB_00335	Not Detected	Surface Coating	Paint
Townsville	DB017	2/26/2015	247	West wall section and various locations	Material coated on concrete column edge		ASB_00336	Not Detected	Surface Coating	Bituminous product
Townsville	DB017	2/26/2015	247	West Wall - old insulation	Wool type material flame.		ASB_00337	Not Detected	Insulation	Woven fibre

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB017	2/26/2015	248	West wall below insulation	Fibre cement sheeting		ASB_00338	Not Detected	Cladding	Fibre cement product
Townsville	DB017	2/26/2015	248	Drain	Infill round drain		ASB_00339	Not Detected	Sealant	Mastic
Townsville	DB017	2/26/2015	249	Walls	Cement sheet	AT180712.43A		Not Detected	Wall	
Townsville	DB017	3/2/2015	249 radioactive room	Roof/ceiling of structure	Cement sheet (over timber frame)		ASB_00347	Not Detected	Roof	Fibre cement product
Townsville	DB017	3/2/2015	302 outside room	Concrete deck area	Waterproof membrane over joints & cracks		ASB_00340	Not Detected	Sealant	
Townsville	DB017	3/17/2015	C001	Floor west end	Different grey tiles - brighter tile with more white and black throughout		ASB_00376	Not Detected	Floor Covering	Vinyl tile
Townsville	DB017	3/4/2015	C101	Ceiling space	Ceiling space inspected for remnant ACM. No suspect materials found.			Not Detected	NA	
Townsville	DB017	3/4/2015	C101	Ceiling	Sprayed texture finish sample taken previously taken from ground floor.		ASB_00354	Not Detected	Sprayed Coating	Vermiculite
Townsville	DB017	2/25/2015	C201	Top of access stair ceiling	Suspended ceiling tiles compressed fibre material (SMF)		ASB_00326	Not Detected	Ceiling	Low Density Fibre Board
Townsville	DB017	2/26/2015	C201	Floor	Vinyl sheet on concrete		ASB_00330	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB017	3/4/2015	C201	High section of suspended ceiling - roof space	Inspected for remnant ACM. Viewed safety mesh, modern insulation, no			Not Detected	NA	
Townsville	DB017	3/18/2015	F001 entrance South side	Pipes outside coming out of ground west wall - external	Pipes have black bituminous insulation		ASB_00385	Not Detected	Insulation	Bituminous product
Townsville	DB017	3/23/2015	North wing - North face	DT surround	Formwork		ASB_00394	Not Detected	Formwork	Fibre cement product
Townsville	DB017	3/23/2015	North wing - West face	Columns	Formwork		ASB_00393	Not Detected	Formwork	Fibre cement product
Townsville	DB017	3/23/2015	S001	Foyer & East wall	Cement sheet with pebble finish	AT180712.31		Not Detected	Wall	Fibre cement product
Townsville	DB017	3/5/2015	S102	Walkway from bldg. 017 to bldg. 34 - fascia on external	9mm sheeting - this is different from other fascia material used on building		ASB_00360	Not Detected	Fascia	Fibre cement product
Townsville	DB017	3/5/2015	S102	Walkway from bldg. 017 to bldg. 34 - wall under window	Cement sheeting		ASB_00362	Not Detected	Wall	Fibre cement product
Townsville	DB017	3/5/2015	S102	Walkway from bldg. 017 to bldg. 34 - ceiling	Cement sheeting		ASB_00363	Not Detected	Ceiling	Fibre cement product
Townsville	DB017	3/5/2015	S102	Walkway from bldg. 017 to bldg. 34 - floor	Vinyl sheet on concrete		ASB_00364	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB017	3/5/2015	S102	Walkway from bldg. 017 to bldg. - window ledge joins	Joins filled with jointing compound		ASB_00365	Not Detected	Sealant	Mastic
Townsville	DB017	2/26/2015	S201 top of stairs	Slab edge	Sprayed texture finish		ASB_00329	Not Detected	Sprayed Coating	Vermiculite
Townsville	DB017	3/20/2015	South wing bottom level work shop	West and east gutter Box gutter on roof	Lined with rubber product		ASB_00386	Not Detected	Guttering	
Townsville	DB017	3/2/2015	Top platform weather station above lift motor	Floor	Black bituminous product with stones laid over		ASB_00341	Not Detected	Adhesive	Bituminous product
Townsville	DB017	3/2/2015	Top platform weather station above lift motor	Edge board	Fibre cement sheeting		ASB_00342	Not Detected	Cladding	Fibre cement product
Townsville	DB020	3/24/2015	000C	Walls	Cement sheet		ASB_00400	Not Detected	Wall	Fibre cement product
Townsville	DB020	3/24/2015	003	Ceiling entrance external	Cement sheet		ASB_00405	Not Detected	Ceiling	Fibre cement product
Townsville	DB020	3/24/2015	008	Ceiling	Cement sheet		ASB_00397	Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB020	3/24/2015	009	Walls	Cement sheet		ASB_00398	Not Detected	Wall	Fibre cement product
Townsville	DB020	3/24/2015	011	Walls	Cement sheet	AT120712.23		Not Detected	Wall	Fibre cement product
Townsville	DB020	3/24/2015	012	Ceiling	Cement sheet		ASB_00401	Not Detected	Ceiling	Fibre cement product
Townsville	DB020	3/24/2015	016	Plant room	Remnant cement sheeting		ASB_00402	Not Detected	Ceiling	Fibre cement product
Townsville	DB020	3/24/2015	022	Walls	Cement sheet	AT120712.22		Not Detected	Wall	Fibre cement product
Townsville	DB020	3/24/2015	C000	Duct	Jointing		ASB_00399	Not Detected	Sealant	Mastic
Townsville	DB020	3/24/2015	External	Block walls	Control joint		ASB_00404	Not Detected	Sealant	Mastic
Townsville	DB020	3/24/2015	External	Eaves west end	Cement sheet, resampled as previous description of location was incomplete.	AT120712.20	ASB_00406	Not Detected	Eaves	Fibre cement product
Townsville	DB021	12/12/2015	002E	Ceiling	Plaster			Not Detected	Ceiling	
Townsville	DB021	12/12/2015	003	Ceiling	Above both entrances. Ceilings are plaster board. Glass fibre ceiling within			Not Detected	Ceiling	
Townsville	DB021	7/8/2017	004A	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	7/19/2012	004A	Walls	Same material as ASB_00210			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	006	Walls	Same material as ASB_00211			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	006	South wall Infill above exit door	Same material as ASB_00211			Not Detected	Cladding	Fibre cement product
Townsville	DB021	7/6/2017	006	Walls	Same as ASB_00211			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	010	Entrance area ceiling	Suspended fibre cement sheets with a white textured surface. Same as			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	7/19/2012	010	Walls	Same as ASB_00211			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	010B	Entrance area ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB_00205.			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/12/2015	012B	Walls	North wall has cladding beneath the Windows and west wall. Same as 213.			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	012C	Wall	South wall only. Same as 213			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	012D	Wall	South wall to stairs leading down to door. Same as 213			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	012D	Infill	Infill panel above door. Same as 213.			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	012F	Walls	North wall has cladding beneath the Windows and west wall. Same as 213.			Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB021	12/12/2015	012H	Walls	North wall has cladding beneath the Windows and west wall. Same as 213.			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	015	Floor covering	Blue vinyl tile. Presumed no asbestos detected by JTA from sample taken	See AT190712		Not Detected	Floor	Vinyl tile
Townsville	DB021	12/12/2015	015	Ceiling		AT190712 .07		Not Detected	Ceiling	Fibre cement product
Townsville	DB021	7/8/2017	017	Partitions (not found)	Presumed asbestos by JTA from sample taken in 018. No partitions in	See AT190712		Not Detected	Wall	
Townsville	DB021	7/8/2017	017	Ceiling	Presumed asbestos by JTA cross referencing Abscan 2007 sample. Ceiling to 017 is cast concrete.	See 0285/07 DB021-23		Not Detected	Ceiling	
Townsville	DB021	7/8/2017	022	Flues / vent pipes	Presumed asbestos by JTA cross referencing Abscan 2007 sample. Item not found at this location.	See 0285/07 DB021-11		Not Detected	Flue	Fibre cement product
Townsville	DB021	7/19/2012	022	Walls	Presumed no asbestos detected by JTA from sample taken from walls in	See AT190712		Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	022	Ceiling	Presumed no asbestos detected by JTA from sample taken from ceiling in 015	See AT190712 .07		Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/6/2015	100C	Walls	Cladding outside entrance to Room 116. Same as ASB209.			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	100C	Floor	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile
Townsville	DB021	12/6/2015	100C	Wall	Infill to doorways of Rooms 119 and 120. Same as ASB_00209			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	102	Infill panels to top of fume cupboard	Fibre cement sheet the same as ASB_00205			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	103 Chemistry Lab	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/6/2015	103	Infill panels to top of fume cupboard	Fibre cement sheet the same as ASB205			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	103A	Walls	Same as ASB_00206.			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	103A	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/6/2015	103A	Wall	Wall panelling abutting northern entrance to Room 103. Same as			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	110	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/6/2015	110	Infill panels to top of fume cupboard				Not Detected	Wall	Fibre cement product
Townsville	DB021	7/10/2017	110A	South Wall				Not Detected	Wall	Fibre cement product
Townsville	DB021	7/9/2017	112B	North Wall	Modern fibre cement. Same as ASB_00209			Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	113	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as			Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB021	12/6/2015	116	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	7/9/2017	119	Ceiling	Suspended ceiling panels with smooth finish. Plaster panels. Previously			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	7/19/2012	119	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile
Townsville	DB021	12/6/2015	120	Ceiling	Suspended fibre cement sheets with a white textured surface. Same as ASB205.			Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/6/2015	120	Floor	Vinyl tile beneath carpet	Same as AT190712		Not Detected	Floor	Vinyl tile
Townsville	DB021	7/7/2017	206	Splashback wall	Presumed asbestos by JTA from sample of wall from 121. Item not	See AT190712		Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	209A	Floor under floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile
Townsville	DB021	11/5/2015	224A	Floor	Sheet vinyl on concrete floor with carpet laid over - representative			Not Detected	Floor	Vinyl sheet
Townsville	DB021	7/19/2012	228	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile
Townsville	DB021	11/5/2015	230	Floor	Sheet vinyl on concrete floor with carpet laid over - representative			Not Detected	Floor	Vinyl sheet
Townsville	DB021	11/6/2015	231	Undertook intrusive inspection of floor and from	No ACM found. Walls are cast concrete or masonry block. No suspect			Not Detected		
Townsville	DB021	7/19/2012	232	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile
Townsville	DB021	7/19/2012	103C Corridor approaching 119	Floor covering	Grey vinyl tile. Same as ASB_03318			Not Detected	Floor	Vinyl tile
Townsville	DB021	6/18/2015	External	AHU2. E000003	Red Flexible duct connector to original yellow ducting on east side. See			Not Detected	Vinyl	
Townsville	DB021	7/8/2017	008B	Walls	As for 008A			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/10/2017	HVAC System	Heater banks in Supply Ducts	A review of historical plans, visual inspection of the plant room and ceiling			Not Detected		
Townsville	DB021	7/11/2017	003	Ceiling	Above both entrances. Ceilings are plaster board. Glass fibre ceiling within			Not Detected	Ceiling	
Townsville	DB021	7/11/2017	003	Ceiling	Above both entrances. Ceilings are plaster board. Glass fibre ceiling within			Not Detected	Ceiling	
Townsville	DB021	7/6/2017	005A	South section east wall				Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	005A	South section southern wall				Not Detected		Fibre cement product
Townsville	DB021	7/9/2017	120	South Wall	Two sheet types. Same as rm 119.			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/9/2017	112A	North Wall.	Same material as sampled on 112 side.			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/11/2017	220A	Floor	Carpet on vinyl tiles - representative sample taken in Room 223			Not Detected	Floor Covering	Vinyl tile
Townsville	DB021	12/6/2015	115	Floor	Vinyl tile beneath carpet. Grey.	AT190712 .12		Not Detected	Floor	Vinyl tile
Townsville	DB021	7/9/2017	114	Floor	Vinyl tile beneath carpet. Grey.	AT190712 .12		Not Detected	Floor	Vinyl tile

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB021	7/10/2017	225C	East wall	Representative sample taken from 225			Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	203	Internal partition wall				Not Detected	Wall	Fibre cement product
Townsville	DB021	7/19/2012	206	Walls				Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	005	Western upper Wall	Sample taken between panels 1 & 2		ABS_0235 2	Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	102	Ceiling	Suspended fibre cement sheets with a white textured surface		ASB_0020 5	Not Detected	Ceiling	Fibre cement product
Townsville	DB021	12/6/2015	103	East Wall	Wall panelling abutting northern entrance to Room 103A		ASB_0020 6	Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	116	Walls	North, south and east walls. Internal & external cladding.		ASB_0020 9	Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	004	Walls	North, south and west walls are fibre cement. East wall is plasterboard, no sheeting behind it.		ASB_0021 0	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	005A	South section, partition Wall to 005	Unpainted surface.		ASB_0021 1	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	005A	Main section, south Wall	Upper infill above masonry block wall. White surface.		ASB_0021 2	Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	010B	East Wall near fire extinguisher	South, east and west walls. North wall is concrete	AT190712 .06	ASB_0021 3	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/8/2017	023 plant room	A/C AUX UNIT 3. E001278	Flexible duct connector, red colour. Present to join on north end of unit and		ASB_0051 3	Not Detected	Vinyl	
Townsville	DB021	6/18/2015	External	Radio chem lab AHU. E001330	Grey flexible duct connectors on top of unit.		ASB_0051 4	Not Detected	Vinyl	
Townsville	DB021	6/18/2015	241 plant rm	Room 241. Internal lining to AHU E001412.			ASB_0051 5	Not Detected	Cladding	Fibre cement product
Townsville	DB021	6/18/2015	241 External	On top of AHU below old heater bank locations.	Brown micaceous millboard debris. Also present as lining to part of the		ASB_0051 6	Not Detected	Insulation	
Townsville	DB021	1/18/2016	Lift motor room	Brake shoe	Appears to be metallic		ASB_0227 7	Not Detected	Brake	Friction Product
Townsville	DB021	2/18/2016	107	Floor	Blue vinyl floor tile		ASB_0228 1	Not Detected	Floor Covering	Vinyl tile
Townsville	DB021	2/18/2016	107	Walls	Internal and external walls, southern and eastern aspect and door frame		ASB_0228 2	Not Detected	Wall	Fibre cement product
Townsville	DB021	12/12/2015	012	North Wall near fire extinguisher	Fibre cement infill to door frames of 012H and 012I and between 012G and		ASB_0228 3	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/6/2017	005	Western lower wall	Second sheet from western wall. Wall switch g1/29		ASB_0234 9	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB021	7/6/2017	005	South Wall	Sampled under the sink in corner. Representative of both sides of door.		ASB_0235 1	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/7/2017	008A	North wall outer layer. PCR room.	Reddish.		ASB_0235 8	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/7/2017	008A	North wall. Inner layer. PCR room.	Grey		ASB_0235 9	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/8/2017	003	East side HVAC supply duct.	Settled dust at base of duct		ASB_0236 0	Not Detected	Dust	Dust
Townsville	DB021	7/6/2017	005 & 005A	Ceiling to south section.	Suspended ceiling panels with smooth finish.		ASB_0236 2	Not Detected	Ceiling	Fibre cement product
Townsville	DB021	7/8/2017	029C	ground floor corridors	Blue 300mm vinyl tiles		ASB_0236 3	Not Detected	Floor Covering	Vinyl tile
Townsville	DB021	7/8/2017	012D	Walls	Outer cladding to all walls, sampled at vent riser.		ASB_0236 6	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/8/2017	023 plant room	Two steel armoured cables running from back of main	Tar impregnated woven fibre outer layer		ASB_0236 9	Not Detected	Cable	Woven fibre
Townsville	DB021	7/9/2017	119	North Wall	Two types of fibre cement. Sample from older looking Hardy's Versilux.		ASB_0237 3	Not Detected	Wall	Fibre cement product
Townsville	DB021	12/6/2015	112	Wall to 112A	common with 112A. Appears to be modern fibre cement.		ASB_0237 4	Not Detected	Wall	Fibre cement product
Townsville	DB021	7/11/2017	223	Floor	Grey flexible vinyl tiles with yellow adhesive.		ASB_0237 9	Not Detected	Floor	Vinyl tile
Townsville	DB021	11/5/2015	209A	Floor	Carpet on vinyl sheet		ASB_0331 7	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB021	11/5/2015	203	Floor	Vinyl tiles 300mm x 300mm grey on North side of room		ASB_0331 8	Not Detected	Floor Covering	Vinyl tile
Townsville	DB021	11/5/2015	206	Floor	Sheet vinyl on concrete floor.		ASB_0332 0	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB021	7/10/2017	207	Door way sheeted over	Cement sheeting		ASB_0332 1	Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB021	11/5/2015	225	West wall	Cement sheeting		ASB_0332_3	Not Detected	Wall	Fibre cement product
Townsville	DB021	11/5/2015	221	Southern wall	Cement sheeting		ASB_0332_4	Not Detected	Wall	Fibre cement product
Townsville	DB021	11/5/2015	221	Eastern wall	Cement sheeting - appears different to southern wall gyprock on top section		ASB_0332_5	Not Detected	Wall	Fibre cement product
Townsville	DB021	11/6/2015	222	West wall to 221	Cement sheeting		ASB_0332_7	Not Detected	Wall	Fibre cement product
Townsville	DB021	11/6/2015	219	Floor	Vinyl sheet on concrete joins are butted not welded		ASB_0332_9	Not Detected	Floor	Vinyl sheet
Townsville	DB021	11/6/2015	017	Cleaners cupboard Floor	Vinyl sheet on concrete - pieces only most has been removed		ASB_0333_3	Not Detected	Floor	Vinyl sheet
Townsville	DB025	4/13/2015	004	Walls	Fibre cement	AT220212.03		Not Detected	Wall	Fibre cement product
Townsville	DB025	4/13/2015	018	Infill over glass entrance	Fibre cement		ASB_0044_5	Not Detected	Wall	Fibre cement product
Townsville	DB025	2/19/2015	019	Ceiling		AT220212.07	ASB_0008_3	Not Detected	Ceiling	Fibre cement product
Townsville	DB025	4/13/2015	019	Fascia outside room	Fibre cement	AT220212.01	ASB_0044_6	Not Detected	Fascia	Fibre cement product
Townsville	DB025	4/13/2015	019	Ceiling outside representative of above	Fibre cement		ASB_0044_7	Not Detected	Ceiling	Fibre cement product
Townsville	DB025	4/13/2015	101	Walls	Fibre cement	AT220212.04		Not Detected	Wall	Fibre cement product
Townsville	DB025	4/13/2015	101A	Outside balcony walls	Expansion joint		ASB_0044_4	Not Detected	Sealant	Mastic
Townsville	DB025	4/13/2015	111	Plant room	Infill above door		ASB_0044_2	Not Detected	Wall	Fibre cement product
Townsville	DB025	4/13/2015	113A	Fire service cupboard opposite	Dividing wall - fibre cement		ASB_0044_1	Not Detected	Wall	Fibre cement product
Townsville	DB025	4/13/2015	117	Floor	Green vinyl sheet - different from main area		ASB_0044_3	Not Detected	Floor	Vinyl sheet
Townsville	DB025	4/13/2015	119	Male toilet	Partition wall	AT220212.06		Not Detected	Wall	Fibre cement product
Townsville	DB025	4/14/2015	1st Floor	Air conditioning duct boxing	Sampled by JTA 2012	AT220212.05		Not Detected	Cladding	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB025	4/13/2015	226	Service duct area	Jointing compound		ASB_00439	Not Detected	Sealant	Mastic
Townsville	DB025	4/13/2015	226	Service duct area	Insulation/Fire Stopping round pipe		ASB_00440	Not Detected	Insulation	
Townsville	DB025	4/13/2015	C201	Floor	Green Vinyl sheet		ASB_00438	Not Detected	Floor	Vinyl sheet
Townsville	DB025	4/13/2015	External	Soffit and Fascia	Representative sample taken outside room 019. [ASB_00447]			Not Detected	Cladding	Fibre cement product
Townsville	DB025	4/14/2015	External	Awning linings	Sampled by JTA 2012	AT220212.02		Not Detected	Cladding	Fibre cement product
Townsville	DB025	4/14/2015	Hole in the wall	Plant room	Infill panels round duct work 9mm fibre cement		ASB_00448	Not Detected	Cladding	Fibre cement product
Townsville	DB025	4/14/2015	Hole in the wall	Plant room	Infill panels fibre cement sheeting		ASB_00449	Not Detected	Cladding	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	041E	Telecom service duct walls	North & East		ASB_03306	Not Detected	Wall	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	041F	Electrical switchboard ceiling	Cement sheet		ASB_03307	Not Detected	Ceiling	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	041F	Electrical switchboard wall west side	Cement sheet		ASB_03308	Not Detected	Ceiling	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	129A & 130	Northern wall	Wall built out metal frame cement sheeting in behind gyprock		ASB_03301	Not Detected	Wall	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	41A / 41B / 41D	Floor	Carpet on sheet vinyl representative sample of vinyl taken from 41A		ASB_03309	Not Detected	Floor Covering	Vinyl sheet
Townsville	DB028 Nth Annex	11/4/2015	C107	Service duct western wall	Cement sheeting		ASB_03303	Not Detected	Wall	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	External	Northern Soffit sheeting	Able to access Soffit sheeting in ceiling space		ASB_03302	Not Detected	Wall	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	External	Upper Fascade sheeting	Cement sheeting		ASB_03305	Not Detected	Fascia	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	External East	Cement sheeting cladding	Middle section of building, plastic joining strip		ASB_03313	Not Detected	Wall	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	External North	Window awnings	Cement sheeting	AT190712.26	ASB_03310	Not Detected	Cladding	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	External North	Cement sheeting pieces scattered round	Representative samples taken		ASB_03312	Not Detected	Debris	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	External North / Southside	Cement sheeting cladding	Middle section of building, metal joining strip		ASB_03311	Not Detected	Wall	Fibre cement product
Townsville	DB028 Nth Annex	11/4/2015	X101	Ceiling	Cement sheeting		ASB_03304	Not Detected	Wall	Fibre cement product
Townsville	DB035	3/24/2015	001 (DB035)	Ceiling	Spray on textured finish		ASB_00407	Not Detected	Ceiling	Vermiculite
Townsville	DB035	7/17/2017	Entrance Fire door (E004717)	Core Insulation.	Intrusive inspection undertaken of door on 11/7/2017, holes drilled through full depth of door in multiple locations, core			Not Detected	Fire door	

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB036	3/24/2015	001 (DB036)	Ceiling	Cement sheet, taken as representative of ceilings throughout DB036.		ASB_00409	Not Detected	Ceiling	Fibre cement product
Townsville	DB036	3/24/2015	001 - (DB036)	Ceiling - man hole	Cement sheet		ASB_00408	Not Detected	Ceiling	Fibre cement product
Townsville	DB036	3/24/2015	001 External (DB036)	Fascia	Cement sheet		ASB_00411	Not Detected	Fascia	Fibre cement product
Townsville	DB036	3/24/2015	001 External (DB036)	Infill North wall	Cement sheet		ASB_00412	Not Detected	Cladding	Fibre cement product
Townsville	DB036	3/24/2015	001A (DB036)	Floor	Vinyl on concrete		ASB_00410	Not Detected	Floor	Vinyl sheet
Townsville	DB067	2/11/2015	017	Walls	Considered representative of other fibre cement internal walls in DB067.	AT130712.12		Not Detected	Wall	Fibre cement product
Townsville	DB067	2/12/2015	External	Ceilings in walkways			ASB_00297	Not Detected	Eaves	Fibre cement product
Townsville	DB067	2/12/2015	External	Eaves		AT130712.10		Not Detected	Eaves	Fibre cement product
Townsville	DB067	2/12/2015	External	walls	Hardiplank Boards	AT130712.11		Not Detected	Wall	Fibre cement product
Townsville	DB067	2/12/2015	External	walls	Infill panels to walls where old air conditioning units were removed	AT130712.13		Not Detected	Cladding	Fibre cement product
Townsville	DB067	2/12/2015	Roof space	Accessed roof space from rooms 0011,003D,020	Observed SMF insulation over ceiling space, foil insulation to underside of roof, hardwood trusses, did not			Not Detected		
Townsville	DB067	2/12/2015	Room 001	Floor	Vinyl sheet covered up walls same as room 003 except it is laid over vinyl - sample taken from bottom layer		ASB_00296	Not Detected	Floor	Vinyl sheet
Townsville	DB067	2/11/2015	Room 003	Floor	Vinyl sheet covered up walls laid on Masonite on top of timber		ASB_00293	Not Detected	Floor	Vinyl sheet
Townsville	DB067	2/11/2015	Room 014	Floor	Vinyl sheet covered up walls		ASB_00292	Not Detected	Floor	Vinyl sheet
Townsville	DB067	2/11/2015	Room 026	Infill where old conditioner was located	Fibre cement		ASB_00290	Not Detected	Wall	Fibre cement product
Townsville	DB067	2/12/2015	Subfloor Space	Accessed from sides of building	Steel beams and joists attached to steel posts - floor raised approx. 1m to 1.5 metres off ground. Observed			Not Detected		
Townsville	DB068	2/12/2015	Room 002	Floor	Sheet vinyl under carpet. Sample representative of material in room 1 also.		ASB_00298	Not Detected	Floor	Vinyl sheet
Townsville	DB082	4/13/2015	001	Cladding	West end, to washing up area		ASB_1056	Not Detected	Cladding	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB082	4/13/2015	002	Walls	All walls, double skinned on South wall as it fronts onto main area. Sampled from North wall		ASB_01054	Not Detected	Wall	Fibre cement product
Townsville	DB082	4/13/2015	002	Ceiling			ASB_1055	Not Detected	Ceiling	Fibre cement product
Townsville	DB082	4/13/2015	003	Ceiling	Representative sample taken in room 004 [ASB_1057]			Not Detected	Ceiling	Fibre cement product
Townsville	DB082	4/13/2015	003	Walls	East and west ends. Representative sample taken in room 004 [ASB_1058]			Not Detected	Wall	Fibre cement product
Townsville	DB082	4/13/2015	004	Ceiling			ASB_1057	Not Detected	Ceiling	Fibre cement product
Townsville	DB082	4/13/2015	004	Walls			ASB_1058	Not Detected	Wall	Fibre cement product
Townsville	DB083	4/13/2015	003	North walls, upper level. Cladding to 002 and 003A			ASB_01048	Not Detected	Wall	Fibre cement product
Townsville	DB083	4/13/2015	003a	Upper infill above walls to North and west			ASB_01049	Not Detected	Infill	Fibre cement product
Townsville	DB083	4/13/2015	101	East wall			ASB_01050	Not Detected	Wall	Fibre cement product
Townsville	DB084	3/27/2015	101	Wall	Cement sheet - representative sample 102 [ASB_00433]			Not Detected	Wall	Fibre cement product
Townsville	DB084	3/27/2015	101	Floor	Cream vinyl tiles 12" x 12"		ASB_00432	Not Detected	Floor	Vinyl tile
Townsville	DB084	3/27/2015	101	Ceiling	Cement sheet - representative sample 103 [ASB_00436]			Not Detected	Ceiling	Fibre cement product
Townsville	DB084	3/27/2015	102	Floor	Cream vinyl tiles 12" by 12". Representative samples taken in corridor [JT050213.22] and room 101			Not Detected	Floor	Vinyl tile
Townsville	DB084	3/27/2015	102	Walls	Cement sheet		ASB_00433	Not Detected	Wall	Fibre cement product
Townsville	DB084	3/27/2015	102	Ceiling	Cement sheet - representative sample 103 [ASB_00436]			Not Detected		
Townsville	DB084	3/27/2015	103	Floor	Cream vinyl tiles 12" by 12". Representative samples taken in			Not Detected	Floor	Vinyl tile
Townsville	DB084	3/27/2015	103	Walls	Cement sheet - representative sample 102 [ASB_00433]			Not Detected	Wall	Fibre cement product
Townsville	DB084	3/27/2015	103	Ceiling	Cement sheet		ASB_00436	Not Detected	Ceiling	Fibre cement product
Townsville	DB084	3/27/2015	104	Floor	Cream vinyl tiles 12" by 12". Representative samples taken in corridor [JT050213.22] and room 101			Not Detected	Floor	Vinyl tile
Townsville	DB084	3/27/2015	104	Walls	Cement sheet	JT050213.25		Not Detected	Wall	Fibre cement product
Townsville	DB084	3/27/2015	Upper corridor	Floor	Cream vinyl tiles 12" x 12"	JT050213.22		Not Detected	Floor	Vinyl tile
Townsville	DB085	3/25/2015	003	North wall infill above block wall - representative sample	Cement sheet			Not Detected	Wall	Fibre cement product
Townsville	DB085	3/25/2015	003	Ceiling	Cement sheet tiles	JT050213.09		Not Detected		
Townsville	DB085	3/25/2015	004	Ceiling	Cement sheet tiles			Not Detected		

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB085	3/25/2015	004	North wall infill above block wall	Cement sheet		ASB_00421	Not Detected	Wall	Fibre cement product
Townsville	DB085	3/25/2015	005A	Walls East and South	Cement sheet	JT050213.11		Not Detected		
Townsville	DB085	3/25/2015	005A	Ceiling	Cement sheet tiles			Not Detected		
Townsville	DB085	3/25/2015	005B	Ceiling	Cement sheet tiles			Not Detected		
Townsville	DB085	3/25/2015	005B	Walls	Cement sheet			Not Detected		
Townsville	DB085	3/25/2015	005C	Ceiling	Cement sheet tiles			Not Detected		
Townsville	DB085	3/25/2015	005C	Walls	Cement sheet			Not Detected		
Townsville	DB085	3/25/2015	006	Ceiling	Cement sheet tiles			Not Detected		
Townsville	DB085	3/25/2015	007	Wall near entrance door west side	Cement sheet		ASB_00419	Not Detected	Wall	Fibre cement product
Townsville	DB085	3/25/2015	007	West wall - Infill round air con unit	Cement sheet		ASB_00420	Not Detected	Cladding	Fibre cement product
Townsville	DB085	3/25/2015	007A	Floor	Sheet vinyl	JT050213.12		Not Detected		
Townsville	DB085	3/25/2015	007A	Walls	Cement sheet	JT050213.13		Not Detected		
Townsville	DB085	3/25/2015	008	Entrance door - internal wall	Fibre Cement product		ASB_00427	Not Detected	Wall	Fibre cement product
Townsville	DB085	3/25/2015	008	Entrance door - external wall	Fibre Cement product		ASB_00428	Not Detected	Wall	Fibre cement product
Townsville	DB085	3/26/2015	008A	Ceiling	Cement sheet tiles - original			Not Detected		
Townsville	DB085	3/26/2015	008A	New wall	Fibre Cement product			Not Detected		
Townsville	DB085	3/26/2015	008A	Existing wall on west and south west original	Fibre Cement product representative sample taken 005A			Not Detected		
Townsville	DB085	3/26/2015	009	Doorway to 010 informed by persons on site that material	Fibre Cement product			Not Detected		
Townsville	DB085	3/26/2015	010	Ceiling	Fibre Cement product		ASB_00429	Not Detected	Ceiling	Fibre cement product
Townsville	DB085	3/26/2015	010	Doorway to 008A informed by persons on site that	Fibre Cement product			Not Detected		
Townsville	DB085	3/26/2015	External	Infill between wall and roof - to keep possums out	Fibre Cement product			Not Detected		
Townsville	DB085	3/25/2015	External west	Replacement sheet soffit	Cement sheet		ASB_00423	Not Detected	Fascia	Fibre cement product
Townsville	DB085	3/25/2015	External west and south	Fascia and soffit material	Cement sheet		ASB_00422	Not Detected	Eaves	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB086	3/25/2015	001,002,004,005,006,007,008	Floor	Sheet vinyl through out. Green/grey epoxy (or similar) floor coating		ASB_00415	Not Detected	Floor	Vinyl sheet
Townsville	DB086	3/25/2015	003A	Ceiling	Suspended ceiling - Cement sheet			Not Detected		
Townsville	DB086	3/25/2015	003B	Joint round ducting	Jointing compound		ASB_00414	Not Detected	Sealant	Mastic
Townsville	DB086	3/25/2015	003B	Ceiling	Suspended ceiling - Cement sheet			Not Detected		
Townsville	DB086	3/25/2015	003C	Ceiling	Suspended ceiling - Cement sheet			Not Detected		
Townsville	DB086	3/25/2015	005	Wall west side - Infill panels over windows	Cement sheet		ASB_00413	Not Detected	Cladding	Fibre cement product
Townsville	DB086	3/25/2015	C003	Ceiling	Suspended ceiling - Cement sheet	AT130712.17		Not Detected		
Townsville	DB086	3/25/2015	External - southern side	Soffit	Cement sheet	AT130712.15		Not Detected		
Townsville	DB087	3/30/2015	0 ground floor C001	Floor	Previously documented mustard vinyl floor tiles removed and replaced with			Not Detected	Floor	
Townsville	DB087	4/4/2015	006	Ceiling	Textured coating exposed		ASB_01034	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	4/15/2015	011	Heater bank in supply vent	Internal lining to heater bank. Material not visually consistent with ACM heater		ASB_00144	Not Detected	Insulation	
Townsville	DB087	4/4/2015	013	Ceiling	Textured coating exposed		ASB_01035	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	4/4/2015	023	Ceiling	Textured coating exposed		ASB_01036	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	4/13/2015	031 (Switchboard room, external South)	Infill around doorframe			ASB_01039	Not Detected	Infill	Fibre cement product
Townsville	DB087	3/30/2015	100C	Floor	Previously documented mustard vinyl floor tiles removed and replaced with			Not Detected	Floor	
Townsville	DB087	4/4/2015	101	Ceiling			ASB_01033	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	4/4/2015	109	Ceiling	Textured coating exposed		ASB_01032	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	3/30/2015	113B	Wall	Rear wall appears to be new sheet. Sampled and made sure not sheeted over old material, which it is not. Ceiling		ASB_01027	Not Detected	Wall	Fibre cement product
Townsville	DB087	3/30/2015	118	Wall	West wall, dividing 118 and 118B		ASB_01026	Not Detected	Wall	Fibre cement product
Townsville	DB087	3/27/2015	118	Floor	Previously reported mustard vinyl tiles removed. Replaced with new vinyl floor. No backing layer.			Not Detected		
Townsville	DB087	3/30/2015	118A	Walls	Double layer, so sheeting present to 2 sides, inside 118 and 118B		ASB_01025	Not Detected	Wall	Fibre cement product
Townsville	DB087	4/13/2015	118B	Ceiling	Textured coating exposed		ASB_01038	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	3/30/2015	118B	Wall	East wall, dividing 118 and 118B. Same as ASB_01026			Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DB087	3/27/2015	118B, 118A, 118, 115(PC2), 111,110(PC2), 109, 108A, 107, 106, 105,	Ceilings	Samples taken in various other similar rooms are taken as representative of sprayed textured coatings applied to ceilings in the rooms listed here.			Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	3/30/2015	119A	Walls	North and East walls. Internal and external		ASB_01028	Not Detected	Wall	Fibre cement product
Townsville	DB087	4/4/2015	124	Ceiling	Access to outside perimeter of PC3 lab, which has textured coating to ceiling		ASB_01044	Not Detected	Ceiling	Fibre cement product
Townsville	DB087	4/4/2015	1st Floor, S101 (stairwell landing)	Sprayed coating to underside of stairs			ASB_01037	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	3/27/2015	200C	Floor	Previously documented mustard vinyl floor tiles removed and replaced with blue vinyl sheet with no backing. Inspected beneath sheeting in several			Not Detected	Floor	
Townsville	DB087	4/4/2015	201	Roof space	Sprayed coating to concrete beam. Look for yellow tab stuck to ceiling		ASB_01030	Not Detected	Roof insulation	Vermiculite
Townsville	DB087	3/27/2015	205	Ceiling space	Sprayed coating		ASB_01023	Not Detected	Sprayed Coating	Textured Coating
Townsville	DB087	4/4/2015	206	Roof space	Sprayed coating to clip lock roof. Look for yellow tab stuck to ceiling framework where tile removed.		ASB_01029	Not Detected	Roof insulation	Textured Coating
Townsville	DB087	4/4/2015	220	Roof space	Sprayed coating to clip lock roof. Look for yellow tab stuck to ceiling		ASB_01031	Not Detected	Roof insulation	Textured Coating
Townsville	DB087	4/15/2015	229	Fire door E004640, to roof stairs, core of door sampled from behind handle	Not visually consistent with typical ACM door		ASB_00145	Not Detected	Fire door	Low Density Fibre Board
Townsville	DB087	4/13/2015	External	Lining to Air compressor E006948 housing	South and west walls plus roof		ASB_01041	Not Detected	Cladding	Fibre cement product
Townsville	DB087	4/13/2015	External	Expansion joint	Sealant between blockwork and paving, North side, adjacent to drain		ASB_01043	Not Detected	Sealant	Mastic
Townsville	DC054	3/23/2015	003	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	004	Ceiling	Previously sampled in room 001	See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	006	Ceiling	Western aspect. Previously sampled in room 001	See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	006	Wall	West and north west wall			Not Detected	Wall	Fibre cement product
Townsville	DC054	3/23/2015	008	Wall	West wall			Not Detected	Wall	Fibre cement product
Townsville	DC054	3/23/2015	008	Ceiling	Previously sampled in room 001	See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	009	Walls	West wall			Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DC054	3/23/2015	009A	Walls	East wall			Not Detected	Wall	Fibre cement product
Townsville	DC054	3/23/2015	011	Walls	East and South walls. Previously sampled in room 001	See AT160712.02		Not Detected	Wall	Fibre cement product
Townsville	DC054	3/23/2015	011	Ceiling	Previously sampled in room 001	See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	012	Walls	North and East walls. Previously sampled in room 001	See AT160712.02		Not Detected	Wall	Fibre cement product
Townsville	DC054	3/23/2015	012	Ceiling	Previously sampled in room 001	See AT160712.02		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	013	Walls	All walls. Previously sampled in room 001	See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC054	3/23/2015	013	Ceiling	Previously sampled in room 001	See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	014	Ceiling	Previously sampled in room 001	See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	019	Ceiling	Same as ASB_01008			Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	020	Ceiling	Not previously sampled		ASB_01008	Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	021	Ceiling	Same as ASB_01008			Not Detected	Ceiling	Fibre cement product
Townsville	DC054	3/23/2015	External	Eave soffit to South East walkway	Not previously sampled		ASB_01007	Not Detected	Eaves	Fibre cement product
Townsville	DC054	3/23/2015	External	Eave soffit to South West walkway.	Same as ASB_01007			Not Detected	Eaves	Fibre cement product
Townsville	DC055	3/25/2015	016	Floor		AT160712.05		Not Detected	Floor	Fibre cement product
Townsville	DC055	3/25/2015	017	Floor	Cream vinyl tiles beneath carpet	AT160712.08		Not Detected	Floor	Vinyl tile
Townsville	DC055	3/25/2015	017	Ceiling			ASB_01010	Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/25/2015	017	Wall	North, East and South walls. Same material as ASB_01010			Not Detected	Wall	Fibre cement product
Townsville	DC055	3/25/2015	020	Infill panel above and below window	South side only. Single layer so also an external feature. Sample [ASB_01014] taken as representative of this material.			Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/25/2015	024 (male toilet)	Ceiling	2 sheets, southern aspect		ASB_01012	Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DC055	3/25/2015	024 (male toilet)	Wall	Dividing wall and partition to toilet		ASB_01013	Not Detected	Wall	Fibre cement product
Townsville	DC055	3/25/2015	025 (shower)	Wall	North and west. Same as ASB_01013			Not Detected	Wall	Fibre cement product
Townsville	DC055	3/25/2015	026 (female toilet)	Ceiling	2 sheets, Northern aspect. Same as ASB_01012			Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/25/2015	027/028 (one room with 2 entries, with 2 numbers)	Infill panel above window	Single layer so also an external feature. Sample [ASB_01014] taken as representative of this material.			Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/25/2015	029	Infill panel above and below window	South side only. Single layer so also an external feature. Sample [ASB_01014]			Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/26/2015	030	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	030	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	030	Infill above windows		See AT160712		Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/26/2015	031	Wall		See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	031	Ceiling		See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	031A	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	031A	Ceiling		See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	032	Wall		See AT160712.09		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	032	Ceiling		See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	033	Wall		See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	033	Ceiling		See AT160712.09		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	033	Infill above windows		See AT160712		Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/26/2015	034	Wall		See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	034	Ceiling		See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	034	Infill above windows		See AT160712		Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/26/2015	034A	Wall		See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	034A	Ceiling		See AT160712		Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DC055	3/26/2015	034A	Infill above windows		See AT160712		Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/26/2015	035	Wall		See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC055	3/26/2015	035	Ceiling		See AT160712		Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/26/2015	035	Infill above windows		See AT160712		Not Detected	Cladding	Fibre cement product
Townsville	DC055	3/26/2015	External	Floor	Entrance to 029	See AT160712 .05		Not Detected	Floor	Fibre cement product
Townsville	DC055	3/26/2015	External	Ceiling lining to alcove	South west entrance		ASB_0101 4	Not Detected	Ceiling	Fibre cement product
Townsville	DC055	3/25/2015	External, Northwest aspect	Ceiling of verandah outside room 018			ASB_0101 1	Not Detected	Ceiling	Fibre cement product
Townsville	DC056	3/26/2015	002 (Mechanics Office)	Infill panel	Above North door, both internal and external		ASB_0101 7	Not Detected	Infill	Fibre cement product
Townsville	DC057	3/26/2015	007	Walls		0285/07 DC057-06		Not Detected	Wall	Fibre cement product
Townsville	DC057	3/26/2015	007A	Walls		0285/07 DC057-06		Not Detected	Wall	Fibre cement product
Townsville	DC057	3/26/2015	011	Floor	Same as "oatmeal" in 013	See AT270712		Not Detected	Floor	Vinyl tile
Townsville	DC057	3/26/2015	011	Walls	A mixture of fibre cement sheet and particle board. Sample taken from		ASB_0101 8	Not Detected	Wall	Fibre cement product
Townsville	DC057	3/26/2015	012 (toilets)	Walls		0285/07 DC057-06		Not Detected	Wall	Fibre cement product
Townsville	DC057	3/26/2015	013	Infill panel	Above South door	See AT270712		Not Detected	Cladding	Fibre cement product
Townsville	DC057	3/26/2015	External	Infill above door to 007		AT270712 .08		Not Detected	Cladding	Fibre cement product
Townsville	DC058	3/23/2015	001	Infill to top of west wall		See 0285/07 DC058-05		Not Detected	Cladding	Fibre cement product
Townsville	DC058	3/23/2015	002	Infill above louvres, South west and south east aspect		AT130712 .20		Not Detected	Cladding	Fibre cement product
Townsville	DC058	3/23/2015	002A	Ceiling	Lower ceiling, west side		ASB_0100 1	Not Detected	Ceiling	Fibre cement product
Townsville	DC058	3/23/2015	002A	Wall	North west aspect. Same as ASB_01002			Not Detected	Wall	Fibre cement product
Townsville	DC058	3/23/2015	002B	Wall			ASB_0100 2	Not Detected	Wall	Fibre cement product
Townsville	DC058	3/24/2015	003	Wall	Cladding to South wall		ASB_0100 3	Not Detected	Wall	Fibre cement product
Townsville	DC058	3/24/2015	003	Infill to top of west and east walls	Sampled from North East corner, via roof top storage. Some damage in North East corner		ASB_0100 4	Not Detected	Cladding	Fibre cement product
Townsville	DC058	3/24/2015	003A	Ceiling			ASB_0100 5	Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DC058	3/24/2015	003B	Infill panel to doorway common to 003	Same material as ASB_01004			Not Detected	Cladding	Fibre cement product
Townsville	DC058	3/24/2015	003B	Infill around doorframe. Common to building 059	Same material as ASB_01004			Not Detected	Cladding	Fibre cement product
Townsville	DC058	3/24/2015	003B	Ceiling	Same as ASB_01005			Not Detected	Ceiling	Fibre cement product
Townsville	DC058	3/23/2015	External	Eaves. Northern half of East aspect		0285/07 DC058-04		Not Detected	Eaves	Fibre cement product
Townsville	DC059	3/26/2015	002	Ceiling		AT160712 .16		Not Detected	Ceiling	Fibre cement product
Townsville	DC059	3/26/2015	002	Walls		See AT160712 .15		Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	003 (store dispensary)	Walls	Cladding to wall common with room 010 and 004. Same as ASB_01005			Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	004 (tea room)	Walls		See AT160712 .15		Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	005	Ceiling		AT160712 .16		Not Detected	Ceiling	Fibre cement product
Townsville	DC059	3/26/2015	005	Walls		See AT160712 .15		Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	007 (mail sorting)	Walls		See AT160712 .15		Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	008	Ceiling		AT160712 .16		Not Detected	Ceiling	Fibre cement product
Townsville	DC059	3/26/2015	008	Walls		See AT160712 .15		Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	009 (mail room)	Walls		See AT160712		Not Detected	Wall	Fibre cement product
Townsville	DC059	3/26/2015	010 (storeroom)	Infill above doorway to building 058	Same as ASB_01005 from building 058			Not Detected	Wall	Fibre cement product
Townsville	DC060	3/26/2015	001	Floor		AT030812 .03		Not Detected	Floor	Vinyl tile
Townsville	DC060	3/26/2015	002	Wall	South wall	AT030812 .02		Not Detected	Wall	Fibre cement product
Townsville	DC060	3/26/2015	003	Walls		AT030812 .02		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DC060	3/26/2015	004	Walls		AT030812.02		Not Detected	Wall	Fibre cement product
Townsville	DC060	3/26/2015	005	Floor		See AT030812.03		Not Detected	Floor	Vinyl tile
Townsville	DC060	3/26/2015	External	Infill	3 panels on the North wall		ASB_01019	Not Detected	Infill	Fibre cement product
Townsville	DC060	3/26/2015	External	Eaves		AT030812.01		Not Detected	Eaves	Fibre cement product
Townsville	DC066	3/30/2015	External	Wall	South wall between the 2 rooms	AT030812.10		Not Detected	Wall	Fibre cement product
Townsville	DC066	3/30/2015	Poison room	Walls		AT030812.13		Not Detected	Wall	Fibre cement product
Townsville	DD014	2/12/2015	001A	Ceiling	Sprayed coating. Sampled in 001B [ASB_00060]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/12/2015	001B	Ceiling	Sprayed coating		ASB_00060	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/12/2015	002	Ceiling	Sprayed coating, sampled in 007 [AT210712.04] and 008 [ASB_00063].			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/12/2015	002	Air conditioning bulkhead	Cladding		ASB_00061	Not Detected	Cladding	Fibre cement product
Townsville	DD014	2/12/2015	006	Ceiling	Sprayed coating, sampled in 007 [AT210712.04] and 008 [ASB_00063].			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/12/2015	007	Ceiling	Sprayed coating. Previously sampled.	AT210712.04		Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/12/2015	007	Infill above windows on South aspect	Timber/particle board. Also used throughout the laboratory.			Not Detected	Cladding	
Townsville	DD014	2/12/2015	008	Ceiling	Sprayed coating		ASB_00063	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	101	Ceiling	Sprayed coating		ASB_00058	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	101A	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	101B	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	102	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	104	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	122 & 122B	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	122A	Ceiling	Sprayed coating		ASB_00059	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	122B	Walls	Present to North wall and East wall. Used to partition off from main room		ASB_00057	Not Detected	Wall	Fibre cement product
Townsville	DD014	2/11/2015	122C	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DD014	2/11/2015	123	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	123B	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/11/2015	124	Ceiling	Sprayed coating, sampled in 122A [ASB_00059]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	201	Sprayed coating to roof above plasterboard	Different material to that sampled in S201. Some has fallen away and		ASB_00053	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	202	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	203	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	204	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	205	Ceiling space	Sprayed coating above ceiling panels			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	206	Ceiling space	Sprayed coating above ceiling panels			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	207	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	208	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample [ASB_00053 & ASB_00056]			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	209	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	210	Sprayed "limpet" coating to underside of roof, above	Also applied to beams. Beams are approximately 5m apart.		ASB_00056	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	211	Ceiling space	Sprayed "limpet" coating above ceiling panels. Representative sample			Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	2nd Floor S201	Ceiling/stairwell	Sprayed coating		ASB_00049	Not Detected	Sprayed Coating	Vermiculite
Townsville	DD014	2/10/2015	3rd Floor, External Rooftop	Fibre cement sheet used as roofing/floor			ASB_00046	Not Detected	Roof	Fibre cement product
Townsville	DD014	2/10/2015	3rd Floor, External Rooftop	Broken fibre cement sheet sitting on bricks on bench, plus debris from the sheet			ASB_00048	Not Detected	Debris	Fibre cement product
Townsville	DD014	2/13/2015	External, Ground Level	Expansion joint	Sampled outside 006		ASB_00064	Not Detected	Sealant	Mastic
Townsville	DD014	3/25/2015	HVAC System	HVAC system was inspected for ACM Heater Banks and	No heater banks or ACM fire dampers found. Review of old mechanical plans			Not Detected		
Townsville	DD015	2/13/2015	001	Walls	Same material as ASB_00304			Not Detected	Wall	Fibre cement product
Townsville	DD015	2/13/2015	001	Cladding to entrance	Same material as ASB_00304			Not Detected	Wall	Fibre cement product
Townsville	DD015	2/13/2015	002	Walls	Ceramic tiles and asbestos cement partitions removed. Appears to be refurbished. Sample taken from		ASB_00304	Not Detected	Wall	Fibre cement product
Townsville	DD015	2/13/2015	002	Infill panel above door	Same material as ASB_00304			Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DD015	2/13/2015	002A	Walls	Same material as ASB_00304			Not Detected	Wall	Fibre cement product
Townsville	DD015	3/25/2015	005	Floor, gap sealant at perimeter	Black bituminous material		ASB_00134	Not Detected	Sealant	Bituminous product
Townsville	DD015	2/20/2015	011	South wall	Single skin wall so also has an external presence		ASB_00087	Not Detected	Wall	Fibre cement product
Townsville	DD015	2/19/2015	012	Floor	Green-grey vinyl tile.		ASB_00080	Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/20/2015	012	South wall	Small infill panel above grille. South west corner		ASB_00088	Not Detected	Cladding	Fibre cement product
Townsville	DD015	2/20/2015	015	Walls	Same as that previously sampled in 016	See AT210712.25		Not Detected	Wall	Fibre cement product
Townsville	DD015	2/20/2015	015A	Walls	North and South walls. Same as that previously sampled in 016	See AT210712.25		Not Detected	Wall	Fibre cement product
Townsville	DD015	2/19/2015	016	South wall	Previously sampled	AT210712.25		Not Detected	Service Pit	Fibre cement product
Townsville	DD015	4/15/2015	016	Location of previous heater bank (small) as shown on	Section of duct still insitu, inspected internally and found to be clean.			Not Detected	Heater Bank	
Townsville	DD015	4/15/2015	019, Southern End	Location of previous heater bank (small) as shown on	Entire section of duct previously containing heater bank has been			Not Detected	Heater Bank	
Townsville	DD015	2/24/2015	019B	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	022A	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	022B	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	023	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	4/15/2015	023	Ceiling space, Redundant Heater Bank in SE corner.	Original duct still in situ, inspected internally, no heater bank or debris			Not Detected	Heater Bank	
Townsville	DD015	2/26/2015	024	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	025	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	4/15/2015	025 plant room above	Three supply ducts appear to have previous Heater Banks	Location of previous heater bank in SW corner inspected internally, found to be			Not Detected	Heater Bank	
Townsville	DD015	2/24/2015	031	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/24/2015	031	Walls above windows	Confirmed they are the same as in 032, with no asbestos detected in previous	See AT210712		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DD015	2/24/2015	032	Walls		See AT210712		Not Detected	Wall	Fibre cement product
Townsville	DD015	2/24/2015	032	Floor	Same as ASB_00091. Also has oatmeal coloured tiles that were	AT210712 .30		Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	032 Stairway to 157	Walls	First 2 sheets to west wall at top of stair are Masonite. Others are fibre cement		ASB_0009 2	Not Detected	Wall	Fibre cement product
Townsville	DD015	4/15/2015	032, Ceiling Space	Location of previous heater bank as shown on	Entire section of duct previously containing heater bank has been			Not Detected	Heater Bank	
Townsville	DD015	2/24/2015	032A	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/24/2015	032A	Infill above windows		See AT210712		Not Detected	Wall	Fibre cement product
Townsville	DD015	2/24/2015	032B	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/24/2015	032C	Walls		See AT210712		Not Detected	Wall	Fibre cement product
Townsville	DD015	2/13/2015	111	Floor	Vinyl on concrete		ASB_0030 1	Not Detected	Floor	Vinyl sheet
Townsville	DD015	3/25/2015	111 Staff Room	Heater Bank (2 of) shown on old plan MECH 271-A1-A	Original supply duct completely removed from this room, replaced with			Not Detected	Heater Bank	
Townsville	DD015	2/13/2015	116	Ceiling	Confirmed to be timber ceiling. Previous register by JTA had two			Not Detected	Ceiling	
Townsville	DD015	2/19/2015	130 (corridor)	Floor	Green vinyl tiles		ASB_0007 7	Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/19/2015	130A	Floor	Same as ASB_00077			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/19/2015	130B	Floor	Same as ASB_00077			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	4/15/2015	130C, Ceiling Space	Location of two (2) previous heater banks. As shown on MECH-T1134-103-REV-0	One HB completely replaced with new duct. Other inspected internally, found to be clean.			Not Detected	Heater Bank	
Townsville	DD015	2/19/2015	130D	Floor	Grey vinyl sheet, not tiles		ASB_0007 6	Not Detected	Floor Covering	Vinyl sheet
Townsville	DD015	2/19/2015	132	Infill panel. East wall, North of door	Externally, there are infill panels above the metal louvres that are not visible from the outside. Runs along the length		ASB_0007 8	Not Detected	Cladding	Fibre cement product
Townsville	DD015	2/19/2015	133	Infill panel, East wall.	Same as ASB_00078			Not Detected	Cladding	Fibre cement product
Townsville	DD015	2/19/2015	133	Infill panel to the north door			ASB_0007 9	Not Detected	Cladding	Fibre cement product
Townsville	DD015	4/15/2015	133	Location of four (4) previous heater banks. As shown on	Branches of duct that previously contained heater banks have been			Not Detected	Heater Bank	
Townsville	DD015	2/23/2015	134	Floor	Grey vinyl floor tiles beneath carpet. Adhesive not suspected to be ACM.		ASB_0009 1	Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	136	Floor	Brown vinyl floor tiles. Adhesive not suspected to be ACM.		ASB_0008 9	Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	140	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	140A	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DD015	2/26/2015	141	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	143	Floor	Carpet tiles laid over vinyl tiles the same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/26/2015	144	Floor	Same as ASB_00091			Not Detected	Floor	Vinyl tile
Townsville	DD015	2/26/2015	145	Floor	Same as ASB_00091			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	148	Floor	Grey vinyl tiles same as those in 134 [ASB_00091]			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	149	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	4/15/2015	149, Ceiling Space	Location of two (2) previous heater banks. As shown on	Both HB's completely replaced with new sections of duct.			Not Detected	Heater Bank	
Townsville	DD015	2/23/2015	150	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	151	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	152	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	153	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	154	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	155	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	156	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	157	Floor	Vinyl tiles beneath carpet. Same as ASB_00089 (brown)			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	1st Floor, C106	Floor	Grey vinyl tiles same as those in 134 [ASB_00091]			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/23/2015	1st floor, C107	Floor	Grey vinyl tiles same as those in 134 [ASB_00091]			Not Detected	Floor Covering	Vinyl tile
Townsville	DD015	2/17/2015	1st floor, External, walkway from room 130C	Floor	Fibre cement sheets used as floor to walkway		ASB_0007_4	Not Detected	Floor	Fibre cement product
Townsville	DD015	2/17/2015	External, mechanical engineering containing	East wall near entrance to C104, expansion joint.			ASB_0007_5	Not Detected	Sealant	Mastic
Townsville	DD015	2/17/2015	External, mechanical engineering containing rooms 123 to 129	Sun shades	Same material as ASB_00074			Not Detected	Window Shade Panel	Fibre cement product
Townsville	DD015	2/17/2015	External, South Wing (Stage 2)	Eaves	3 slot profile. Applied to north		ASB_0007_3	Not Detected	Eaves	Fibre cement product
Townsville	DD016	3/13/2015	026	floor		0285/07 DD016-02		Not Detected	Floor	Vinyl tile
Townsville	DF012	1/22/2015	001 Dining room (Refectory)	Southeast wall	Pink fibre cement wall referred to by JTA is in southeast corner only.	AT310712 .04	ASB_0000_3	Not Detected	Wall	Fibre cement product
Townsville	DF012	1/22/2015	001 Dining room (Refectory)	Roof space	Inspected and old wall partitioning observed. No suspected asbestos			Not Detected		

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DF012	1/27/2015	002	Ceiling		AT310712.02		Not Detected	Wall	Fibre cement product
Townsville	DF012	1/27/2015	003	Ceiling		See AT310712.02		Not Detected	Wall	Fibre cement product
Townsville	DF012	1/27/2015	006A	East wall	Common with electrical services cupboard, stamped with "Versilux"		ASB_00016	Not Detected	Wall	Fibre cement product
Townsville	DF012	1/22/2015	014	Walls	Not previously documented.		ASB_00009	Not Detected	Wall	Fibre cement product
Townsville	DF012	1/22/2015	019	Ceiling	Centre of room with water damage. Protruding Textured coating to tile.		ASB_00010	Not Detected	Ceiling	Low Density Fibre Board
Townsville	DF012	1/22/2015	019	Ceiling	Flat matte finish tile sampled above ductwork west end of bar		ASB_00011	Not Detected	Ceiling	Fibre cement product
Townsville	DF012	1/22/2015	019	Ceiling	Inverted Textured coating to tile, sampled above ductwork west end of		ASB_00012	Not Detected	Ceiling	Low Density Fibre Board
Townsville	DF012	1/22/2015	C003	Floor covering	Beige vinyl tile. No asbestos detected. PLM & XRD analysis.	AT310712.06		Not Detected	Floor	Vinyl tile
Townsville	DF012	1/22/2015	C003	Ceiling	Visually consistent with ceiling in room 002.	See AT310712		Not Detected	Wall	Fibre cement product
Townsville	DF012	1/22/2015	EXTERNAL - Bludgers Bar	Walls	No suspected asbestos containing materials observed internally.	AT310712.09		Not Detected	Wall	Fibre cement product
Townsville	DF012	1/22/2015	EXTERNAL - Men's, Ladies & Disabled	Eaves	Sample taken because the eaves have 3 slot profile, whereas the eaves		ASB_00007	Not Detected	Eaves	Fibre cement product
Townsville	DF012	1/22/2015	EXTERNAL - Toilets at Rear of Members Lounge	Cladding to covered walkway	Appears to be an addition to the main building and fibre cement sheet does not appear the same as the eaves. Different fixtures used. Some sheeting		ASB_00008	Not Detected	Cladding	Fibre cement product
Townsville	DF012	1/22/2015	Female Toilets to Bar Area of Club	Ceiling	Sampled in male toilets [ASB_00006]. Same material used in female toilets			Not Detected	Ceiling	Fibre cement product
Townsville	DF012	1/22/2015	Male Toilets to Bar Area of Club	Ceiling	Inspected ceiling space in male toilets and fibreglass insulation on top of		ASB_00006	Not Detected	Ceiling	Fibre cement product
Townsville	DF013	1/27/2015	Entrance way / Corridor	Walls	Sampled by JTA in 2012.	AT020312.21		Not Detected	Wall	Fibre cement product
Townsville	DF013	1/27/2015	Storage	Walls	Sample taken as representative of internal walls throughout DF013, with		ASB_00018	Not Detected	Wall	Fibre cement product
Townsville	DF131	4/17/2015	002	Floor	Sampled by JTA circa 2012. Vinyl sheet with backing layer. No asbestos detected. PLM & XRD analysis.	AT060812.01		Not Detected	Floor Covering	Vinyl sheet
Townsville	DF131	4/16/2015	010	Wall North	Fibre cement sheeting		ASB_00470	Not Detected	Wall	Fibre cement product
Townsville	DF131	4/16/2015	C001 outside room 010 South face	Wall		AT060812.03		Not Detected	Wall	Fibre cement product
Townsville	DF131	4/17/2015	Roof space	Hot Water service (in use) above Rm001	No suspected ACM found.		Not sampled	Not Detected		
Townsville	DF132	1/17/2015	001	North wall around doors to Rm002.	Some sheets are hardboard/Masonite majority cement sheet		AW150117/10	Not Detected	Walls	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DF132	1/17/2015	006 laundry & 007 Toilet/shower	Wall cladding internal and external	External wall cladding previously sampled by JTA [AT300712.05] asbestos not detected. Internal cladding is visually identical to external.			Not Detected	Walls	Fibre cement product
Townsville	DF132	1/17/2015	008	Infill above doorway (folding door) to Rm003.			AW15011 7/09	Not Detected	Walls	Fibre cement product
Townsville	DF132	1/17/2015	008	Ceiling with perforated cement sheet		AT020312 .14		Not Detected		
Townsville	DF132	1/17/2015	008	Ceiling, flat sheet no perforations	This item does not include small brick walled room at East of 008 (see	AT300712 .07		Not Detected		
Townsville	DF132	1/17/2015	009A	Internal North wall	Appears to be modern FC sheet, sampled to confirm, representative of		AW15011 7/07	Not Detected	Walls	Fibre cement product
Townsville	DF132	1/17/2015	011	Ceiling	perforated sheets. Also in 011A		AW15011 7/05	Not Detected	Ceiling	Fibre cement product
Townsville	DF132	1/17/2015	External, East, Awning over concrete deck.	Ceiling	Cement sheet.	AT020312 .12		Not Detected	Ceiling	Fibre cement product
Townsville	DF132	1/17/2015	External, North, front entrance	Ceiling	Cement sheet.	AT300712 .02		Not Detected	Ceiling	Fibre cement product
Townsville	DF132	1/17/2015	External, North, front entrance area	Walls	Fibrocement faux timber weatherboards. Previously sampled by	AT300712 .03		Not Detected	Walls	Fibre cement product
Townsville	DF132	1/17/2015	External, South	Wall cladding external to room 006.	Cement sheet.	AT300712 .05		Not Detected	Walls	Fibre cement product
Townsville	DF132	1/17/2015	Roof space	Insulation over ceiling.	Synthetic mineral fibre	AT020312 .17		Not Detected	Insulation	
Townsville	DG242	4/15/2015	005	Floor	Light green	0285/07 DG242-03		Not Detected	Floor	Vinyl tile
Townsville	DG242	4/15/2015	007	Floor	Modern vinyl sheet. No backing layer. Not suspected to contain asbestos.			Not Detected	Floor	Vinyl sheet
Townsville	DG242	4/15/2015	011	West and South Walls	New fibre cement sheeting applied to west and south walls in October 2013.			Not Detected	Wall	Fibre cement product
Townsville	DG242	4/15/2015	External	Expansion joint		AT250712 .40		Not Detected	Sealant	Mastic
Townsville	DG243	7/25/2012	002	Upper walls		AT250712 .20		Not Detected	Wall	Fibre cement product
Townsville	DG251	7/23/2012	124	Ceiling	Ripple finish	AT230712 .04		Not Detected	Ceiling	Fibre cement product
Townsville	DG251	7/23/2012	Stairs to First Floor	Floor under vinyl sheet		AT230712 .02		Not Detected	Floor	Fibre cement product
Townsville	DG252	7/24/2012	001	Floor under carpet	Cream vinyl tiles	AT240712 .03		Not Detected	Floor	Vinyl tile
Townsville	DG252	7/24/2012	001A	Floor covering	Grey vinyl tiles	AT240712 .07		Not Detected	Floor	Vinyl tile

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DG252	7/24/2012	002	Walls		AT240712.05		Not Detected	Wall	Fibre cement product
Townsville	DG252	7/24/2012	100C	Floor under floor covering	Grey vinyl tiles	AT240712.06		Not Detected	Floor	Vinyl tile
Townsville	DG252	7/24/2012	214	Door infill panel	Confirmed by Abscan 2007			Not Detected	Wall	Fibre cement product
Townsville	DG252	7/24/2012	EXTERNAL	Walls		AT240712.02		Not Detected	Wall	Fibre cement product
Townsville	DG253	7/24/2012	110	Floor covering	Cream vinyl tile	AT240712.14		Not Detected	Floor	Vinyl tile
Townsville	DG253	7/24/2012	110	Walls		AT240712.15		Not Detected	Wall	Fibre cement product
Townsville	DG253	7/24/2012	207	Floor covering	Cream vinyl tile. Confirmed by Abscan 2007.	0285/07 DG253-15		Not Detected	Floor	Vinyl tile
Townsville	DG253	7/24/2012	207	Walls	Confirmed by Abscan 2007	0285/07 DG253-16		Not Detected	Wall	Fibre cement product
Townsville	DG253	7/24/2012	001	Walls	Confirmed by Abscan 2007	0285/07 DG253-09		Not Detected	Wall	Fibre cement product
Townsville	DG253	7/24/2012	005	Walls		AT240712.10		Not Detected	Wall	Fibre cement product
Townsville	DG253	7/24/2012	005	Rear wall	Confirmed by Abscan 2007	0285/07 DG253-07		Not Detected	Wall	Fibre cement product
Townsville	DG253	7/24/2012	204	Floor covering	Confirmed by Abscan 2007	0285/07 DG253-18		Not Detected	Floor	Vinyl tile
Townsville	DG253	7/24/2012	213	Ceiling	Ripple finish	AT240712.16		Not Detected	Ceiling	Fibre cement product
Townsville	DG253	7/24/2012	Level 1 External Corridor	Window infills		AT240712.13		Not Detected	Wall	Fibre cement product
Townsville	DG254	8/6/2012	005A	Walls		AT060812.10		Not Detected	Wall	Fibre cement product
Townsville	DG255	7/24/2012	002A	Floor under carpet	Yellow vinyl tiles	AT240712.20		Not Detected	Floor	Vinyl tile
Townsville	DG255	7/24/2012	102	Walls		AT240712.21		Not Detected	Wall	Fibre cement product
Townsville	DG255	7/24/2012	203	Floor covering	Grey vinyl tiles. Presumed no asbestos detected by JTA. Sampled in Building	0285/07 DG255-14		Not Detected	Floor	Vinyl tile
Townsville	DG255	7/24/2012	External Level 2 Walkway	Walls		AT240712.22		Not Detected	Wall	Fibre cement product
Townsville	DG256	7/25/2012	002	Ceiling		AT250712.05		Not Detected	Ceiling	Fibre cement product
Townsville	DG256	7/25/2012	004	Floor under carpet		AT250712.06		Not Detected	Floor	Vinyl sheet
Townsville	DG256	7/25/2012	007	Walls		AT250712.04		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DG256	7/25/2012	007	Window infills	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG256-03		Not Detected	Cladding	Fibre cement product
Townsville	DG256	7/25/2012	204	Walls		AT250712 .10		Not Detected	Wall	Fibre cement product
Townsville	DG256	7/25/2012	213	Floor covering	Cream vinyl tile.	AT250712 .08		Not Detected	Floor	Vinyl tile
Townsville	DG256	7/25/2012	213	Floor under vinyl tiles	Black adhesive.	AT250712 .09		Not Detected	Floor	Adhesive
Townsville	DG256	7/25/2012	EXTERNAL	Expansion joint	Black sealant	AT250712 .01		Not Detected	Sealant	Mastic
Townsville	DG256	7/25/2012	EXTERNAL	Window infill panels	Pink cement sheet	AT250712 .03		Not Detected	Wall	Fibre cement product
Townsville	DG256	7/25/2012	EXTERNAL	East wall awning & fascia	Some broken fascia pieces on ground.	AT250712 .02		Not Detected	Awning	Fibre cement product
Townsville	DG256	7/25/2012	Level 1 External Walkway	Walls	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG256-11		Not Detected	Wall	Fibre cement product
Townsville	DG257	8/6/2012	012	Walls	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG257-11		Not Detected	Wall	Fibre cement product
Townsville	DG257	8/6/2012	EXTERNAL	Eave linings	Presumed no asbestos detected by JTA. Abscan sampled 2007.	0285/07 DG257-01		Not Detected	Eaves	Fibre cement product
Townsville	DG257	8/6/2012	EXTERNAL	Awning linings		AT060812 .12		Not Detected	Awning	Fibre cement product
Townsville	DG257	8/6/2012	EXTERNAL	Infills to rear wall surrounding ducting		AT060812 .13		Not Detected	Infill panels	Fibre cement product
Townsville	DH100	4/15/2015	Corridor to Courts	Floor	Non-asbestos vinyl sheet. No backing layer.			Not Detected	Floor	Vinyl sheet
Townsville	DH100	4/15/2015	Corridor to Courts	Floor	Vinyl tiles beneath vinyl sheet	AT260712 .21		Not Detected	Floor	Vinyl tile
Townsville	DH100	4/15/2015	External	Ceiling	Northern covered area	See AT260712 .22		Not Detected	Ceiling	Fibre cement product
Townsville	DH100	4/15/2015	External	Eaves	South side eave soffit (upper). Appears to be new material. Photo in Abscan report circa 2010 indicates this		ASB_0013 7	Not Detected	Eaves	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DH100	4/15/2015	Men's & Ladies Toilets	Partitions		AT260712.23		Not Detected	Partitions	Fibre cement product
Townsville	DH100	4/15/2015	Toilets on East Wall	Walls		See AT260712.22		Not Detected	Wall	Fibre cement product
Townsville	DH100	4/14/2015	Viewing area & courts	Walls		See AT260712.22		Not Detected	Wall	Fibre cement product
Townsville	DH100	4/14/2015	Viewing area & courts	Ceiling		AT260712.22		Not Detected	Ceiling	Fibre cement product
Townsville	DH101	4/14/2015	External	Infill, top of blockwork wall to roof	Previously sampled by Abscan (2007) and JTA (2012)	0285/07 DH101-01 &		Not Detected	Infill	Fibre cement product
Townsville	DX191	11/3/2015	003	Floor	Modern sheet vinyl on concrete, not suspected to be ACM			Not Detected	Floor Covering	Vinyl sheet
Townsville	DX191	11/3/2015	004	Ceiling to ladies toilet. Ceiling space accessed from this room.	Cement sheet	AT010312.04	ASB_0328_3	Not Detected	Ceiling	Fibre cement product
Townsville	DX191	11/3/2015	External	Soffit & fascia	Cement sheet product	AT010312.01	ASB_0328_5	Not Detected	Eaves	Fibre cement product
Townsville	DX191	11/3/2015	External	Walkway beams boxed in with identical product as soffit round admin building	Cement sheet product, representative samples taken at other nearby locations [AT010312.01 & ASB_03285]			Not Detected	Cladding	Fibre cement product
Townsville	DX191	11/3/2015	External	Support posts for covered walkway	Fibre cement pipe	AT010312.02	ASB_0328_6	Not Detected	Column	Fibre cement product
Townsville	DX191	11/3/2015	External	Switchboard	Viewed inside switch cabinet. No visible suspected ACM.			Not Detected		
Townsville	DX191	11/3/2015	Internal	Roof space	No suspected ACM found.			Not Detected		
Townsville	DX191	11/3/2015	Internal corridor between ladies and men's toilet	Corridor between ladies and men's toilet Ceiling	Cement sheet		ASB_0328_4	Not Detected	Ceiling	Fibre cement product
Townsville	DX192	11/3/2015	002	Sheet vinyl floor covering	Shows 004 on plan. Modern sheet vinyl on concrete, not suspected to be ACM			Not Detected	Floor Covering	Vinyl sheet
Townsville	DX192	11/3/2015	002	Ceiling	Cement sheeting		ASB_0328_7	Not Detected	Debris	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DX192	11/3/2015	003	Ceiling	Cement sheeting	AT010312.05	ASB_03288	Not Detected	Ceiling	Fibre cement product
Townsville	DX192	11/3/2015	External	Eave lining & fascia panels	Cement sheeting, sampled by JTA.	AZ010312.03		Not Detected	Eave & Fascia	
Townsville	DX192	11/3/2015	Internal	Roof space	No suspected ACM found.			Not Detected		
Townsville	DX193 "B Block"	11/3/2015	006	Ceiling boxed section to Ducting.	Painted cement sheet. Taken as representative of cladding around	AT010312.10	ASB_03290	Not Detected	Ceiling	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	009	Ceiling toilet /shower recess / vanity area	Painted cement sheet		ASB_03289	Not Detected	Ceiling	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	109	Bathroom ceiling	Painted cement sheet. Same material as bathroom 213. (See sample			Not Detected	Ceiling	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	207 & 208	Bathroom ceiling	Painted cement sheet. Same material as bathroom 213. (See sample			Not Detected	Ceiling	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	212	Bathroom ceiling	Painted cement sheet. Same material as Room 213. (See sample			Not Detected	Ceiling	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	213	Bathroom ceiling	Painted cement sheet		ASB_03291	Not Detected	Ceiling	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	External	Support columns	Cement casing	AT010312.06	ASB_03295	Not Detected	Column	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	External	Gable infills under metal panels	Cement sheet, previously sampled by JTA.	AT010312.07		Not Detected	Cladding	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	External	Fascia	Cement sheeting		ASB_03294	Not Detected	Fascia	Fibre cement product
Townsville	DX193 "B Block"	11/3/2015	Internal	Roof Space	No suspected ACM found.			Not Detected		
Townsville	DX193 "B Block"	11/3/2015	Top level balcony eastern side	Soffit lining	Cement sheeting. Taken as representative of all Balcony	AT010312.08	ASB_03293	Not Detected	Soffit	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	009	Ceiling	Toilet / Vanity /Shower. Material same as 109 (see sample ASB_03298)			Not Detected	Ceiling	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	109	Ceiling	Toilet / Vanity /Shower		ASB_03298	Not Detected	Ceiling	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	209	Ceiling	Shower / toilet / vanity area		ASB_03296	Not Detected	Ceiling	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	211	Ceiling	Shower area. Same material as 209 (see sample ASB03296).			Not Detected	Ceiling	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DX194 "A Block"	11/3/2015	212A	Balcony soffit	Cement sheeting. Previously sampled by JTA, precise location not recorded.	AT010312.09	ASB_03297	Not Detected	Soffit	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	Between block B & A to left of undercover walkway	Electrical pits	Concrete pits		ASB_03299	Not Detected	Service Pit	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	Between block B & A to left of undercover	Overflow gully	Formwork		ASB_03300	Not Detected	Service Pit	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	External	Fascia	Same material as B block, (see sample ASB_03294)			Not Detected	Fascia	Fibre cement product
Townsville	DX194 "A Block"	11/3/2015	Internal	Roof Space	No suspected ACM found.			Not Detected		
Townsville	DY111	1/29/2015	001	Walls	Plaster. No fibre cement sheet observed as reported by JTA. Nail			Not Detected		
Townsville	DY111	1/29/2015	001	Infill around door frame leading to 002. Continuation of wall in 005 (sampled)	Same as ASB_00022			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	002	Walls			ASB_00021	Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	002	Ceiling	Same as ASB_00021			Not Detected	Ceiling	Fibre cement product
Townsville	DY111	1/29/2015	005	East wall			ASB_00022	Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	007	Shower recess walls	Inspected behind laminate to shower recess. Panels laid into timber frame. No fibre cement sheet observed.			Not Detected		
Townsville	DY111	1/29/2015	012	Walls	Toilet and storeroom have same material. Same as ASB_00023			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	015	Infill panels to western window			ASB_00024	Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	117	Ceiling	Sprayed coating		ASB_00028	Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	1/29/2015	164	Ceiling	Sprayed coating		ASB_00027	Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	1/29/2015	206	Ceiling	Sprayed coating		ASB_00029	Not Detected	Sprayed Coating	Textured Coating

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DY111	1/29/2015	258	Ceiling	Sprayed coating		ASB_00026	Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	4/17/2015	A wing Roof Space	Roof space above Rm338. Settled dust on ceiling.	No visible evidence of suspect roofing insulation material.		ASB_00167	Not Detected	Dust	Dust
Townsville	DY111	1/28/2015	A337 Toilets	Wall cavity behind toilets	Quarter round of fibre cement pipe strapped to black Asbestos Cement		ASB_00019	Not Detected	Patch	Fibre cement product
Townsville	DY111	1/28/2015	Bathroom - Room 301	Walls under ceramic tiles	Modern fibre cement sheet. Sampled by JTA in 2012 location description "1st floor Unisex Toilets"	AT260712.10		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/28/2015	Corridor	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor corridor B-Wing, asbestos not detected.	See AT260712.08		Not Detected	Floor	Vinyl sheet
Townsville	DY111	1/28/2015	Corridor to Rooms 201 to 213 & 214 to 236	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing, asbestos not detected.	See AT260712.09		Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	1/29/2015	East wing	Infill panels beneath southern windows	Same material as ASB_00024			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 003 (Kevin Hodson room)	West wall	Mixture of fibre cement and plasterboard		ASB_00025	Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	East bathroom	Fibre cement sheet behind laminate. Laminate laid on same material as ASB_00025			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	West corridor, step down from main living area. Walls	Fibre cement sheet similar to 00025 used to walls of corridor			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	West bathroom walls	Ceramic tiles laid on fibre cement sheet, similar to 00025			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	West bathroom ceiling	Fibre cement sheet similar to ASB_00025			Not Detected	Ceiling	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	West toilet wall	Wall adjoining bathroom is fibre cement sheet similar to ASB_00025			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	West toilet ceiling	Fibre cement sheet similar to 00025			Not Detected	Ceiling	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	Wall cladding to veranda	Fibre cement sheet similar to ASB_00025			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing 014	External wall cladding to end of west corridor	Fibre cement sheet similar to ASB_00025			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	East wing kitchen	External walls	Same material as ASB_00024			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/27/2015	EXTERNAL	Wall adjacent Laundry 008	Sampled by JTA in 2012.	AT260712.04		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DY111	1/27/2015	EXTERNAL	Upper infills above doors adjacent Room 003, Ground Floor	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712 .02		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/27/2015	EXTERNAL	Window - lower infills	Sampled by JTA in 2012.	AT260712 .01		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	External	Veranda soffit between rooms 001 and 003	Same as ASB_00023			Not Detected		
Townsville	DY111	1/29/2015	External	External facing walls of veranda to 001 and 003			ASB_00023	Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	External	Infill above doors to 001, 003 and 004	Same as ASB_00023			Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	External Toilet Adjacent to Room 003	Walls under ceramic tiles	Modern fibre cement sheet. Representative sample taken external to Room 013 No asbestos detected.	See AT260712 .02		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	External Toilet Adjacent to Room 003	External walls	Cement sheet. No asbestos detected.	AT260712 .05		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	External Toilet Adjacent to Room 003	Ceiling	Modern fibre cement sheet. Sample from wall considered representative.	See AT260712 .05		Not Detected	Ceiling	Fibre cement product
Townsville	DY111	1/28/2015	FIRST FLOOR Corridor - B Section	Floor under carpet	Cream vinyl sheet. No asbestos detected. PLM & XRD analysis.	AT260712 .08		Not Detected	Floor	Vinyl sheet
Townsville	DY111	1/28/2015	FIRST FLOOR Corridor - B Section	Ceiling	Sprayed finish. No asbestos detected.	AT260712 .09		Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	1/29/2015	Ground Floor General	Upper infills to doors / windows	Modern fibre cement sheet. Representative sample taken external	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Kitchen Adjacent to Room 002	External wall	Modern fibre cement sheet, Representative sample taken external to Laundry 008.	See AT260712 .04		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/28/2015	Levels 1, 2 & 3	Fire doors	All inspected fire doors were labelled with installation date of 2009			Not Detected		
Townsville	DY111	1/29/2015	Living Room; Kitchenette & Room 013	External wall, Room 013	Modern fibre cement sheet. Representative sample taken external	AT260712 .02		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 001 Living Area & Kitchenette	Walls	Modern fibre cement sheet. Representative sample taken room 012	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 002	External wall	Modern fibre cement sheet, Representative sample taken external to Laundry 008.	See AT260712 .04		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 002	Walls	Modern fibre cement sheet. Representative sample taken room 012	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 002	Walls under ceramic tiles	Modern fibre cement sheet. Representative sample taken room 012	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 002	Ceiling	Modern fibre cement sheet. Representative sample taken room 012	See AT260712		Not Detected	Ceiling	Fibre cement product
Townsville	DY111	1/29/2015	Room 003	Walls	Modern fibre cement sheet, Representative sample taken external	See AT260712		Not Detected	Wall	Fibre cement product

ASBESTOS NOT DETECTED

Building No.	Building ID or Name	Date Inspected	Location (e.g. room number)	Secondary Location	Comments	Prev. Sample ID	GCG Sample ID	Asbestos Status	Application	Material Type
Townsville	DY111	1/29/2015	Room 003	Window infills	Modern fibre cement sheet. Representative sample taken external	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 005	Walls	Modern fibre cement sheet. Representative sample taken room 012 asbestos not detected.	See AT260712 .06		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 013 Toilets	Walls	Modern fibre cement sheet. Representative sample taken external	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Room 013 Toilets	Ceiling	Modern fibre cement sheet. Representative sample taken external	See AT260712		Not Detected	Ceiling	Fibre cement product
Townsville	DY111	1/29/2015	Room 015	Walls	Modern fibre cement sheet. Representative sample taken room 012	See AT260712		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/29/2015	Rooms 012; 011; 010	Floor under carpet	Green vinyl tiles. No asbestos detected. PLM & XRD analysis.	AT260712 .03		Not Detected	Floor	Vinyl tile
Townsville	DY111	1/29/2015	Rooms 012; 011; 010	Walls, sampled in room 012	Cement sheet. No asbestos detected.	AT260712 .06		Not Detected	Wall	Fibre cement product
Townsville	DY111	1/28/2015	Rooms 101 to 136	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor	See AT260712		Not Detected	Floor	Vinyl sheet
Townsville	DY111	1/28/2015	Rooms 101 to 136	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing,	See AT260712		Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	1/28/2015	Rooms 158 to 137	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor	See AT260712		Not Detected	Floor	Vinyl sheet
Townsville	DY111	1/28/2015	Rooms 158 to 137	Ceiling	Sprayed finish. Representative sample taken from first floor corridor B-Wing,	See AT260712		Not Detected	Sprayed Coating	Textured Coating
Townsville	DY111	1/28/2015	Rooms 177 to 162	Floor under carpet	Modern cream sheet vinyl. Representative sample taken first floor	See AT260712		Not Detected	Floor	Vinyl sheet